

LICENSEE EVENT REPORT

Update Report:

Previous Report Date: 6-29-82

CONTROL BLOCK:

									1
--	--	--	--	--	--	--	--	--	---

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: NCBEP1; LICENSE NUMBER: 000-000000-000; LICENSE TYPE: 41111; CAT: 5

CON'T REPORT SOURCE: L; DOCKET NUMBER: 6050-0325; EVENT DATE: 7060182; REPORT DATE: 8010583

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

1 During plant operation, while performing the weekly comparative check of suppression chamber water level instrument indications to the local level indicator, PT-08.1.6, remote shutdown panel instrument, I-CAC-LI-3342, indicated -25", and post-accident monitoring instruments, I-CAC-LI-2601-3 and LR-2602, indicated -24" and -28.8" respectively, while the actual level was -27". This event did not affect the health and safety of the public.

2 Technical Specifications 3.3.5.2, 3.3.5.3, 6.9.1.9b

9 SYSTEM CODE: IE; CAUSE CODE: B; CAUSE SUBCODE: A; COMPONENT CODE: INSTRU; COMP. SUBCODE: T; VAL'VE SUBCODE: Z; LER/RO REPORT NUMBER: 82; SEQUENTIAL REPORT NO.: 0516; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 1; ACTION TAKEN: E; FUTURE ACTION: F; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: Y; NPRD-4 FORM SUB.: Y; PRIME COMP. SUPPLIER: N; COMPONENT MANUFACTURER: B04C

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

10 A change in trickle flow to the wet reference leg of each instrument's transmitter LT-3342, Rosemont Model No. 1152, and LT-2601/LT-2602, both Bailey Model No. B015221, caused each transmitter to send an incorrect input signal to its respective instrument. The trickle flow to each transmitter was properly reestablished and the subject transmitters were calibrated and returned to service.

5 FACILITY STATUS: E; % POWER: 060; OTHER STATUS: NA; METHOD OF DISCOVERY: B; DISCOVERY DESCRIPTION: Periodic Test

6 ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

7 PERSONNEL EXPOSURES: NUMBER: 000; TYPE: Z; DESCRIPTION: NA

8 PERSONNEL INJURIES: NUMBER: 000; DESCRIPTION: NA

9 LOSS OF OR DAMAGE TO FACILITY: TYPE: Z; DESCRIPTION: NA

10 PUBLICITY ISSUED: N; DESCRIPTION: NA

8301170230 830105
PDR ADOCK 05000325
S PDR

GPO 917-925

LER ATTACHMENT - RO #1-82-56

Facility: BSEP Unit No. 1

Event Date: June 1, 1982

As a result of an event involving this instrumentation on Unit No. 1, as reported in LER 1-81-07 and several recent LERs, and a post-TMI requirement, plant modification packages (1-80-79 and 1-80-016 for Unit No. 1 and 2-80-78 and 2-80-017 for Unit No. 2) have been developed. These modifications will install a surge volume reservoir in the reference leg in order to increase the accuracy and reliability of this instrument, and remove the requirement to have flow in the reference leg to ensure that it is full.