

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A S E S 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 0 3 8 7 7 1 2 2 2 8 2 8 0 1 0 5 8 3 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing the Loss of Offsite Power Startup Test, the Standby Gas
0 3 Treatment System did not operate as designed. The lead train failed to start
0 4 when a false high radiation signal was received from the discharge monitor.
0 5 The system then transferred to the standby train. This train started but
0 6 tripped off when the proper delta temperature was not achieved. This is re-
0 7 portable per 6.9.1.8.3. No adverse consequences resulted from the incident.
0 8

0 9 SYSTEM CODE S C 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 15
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LEI/RO REPORT NUMBER 8 2 21 22 SEQUENTIAL REPORT NO. 0 6 2 24 26 OCCURRENCE CODE / 0 1 27 29 REPORT TYPE T 30 REVISION NO. 0 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED Y 23 NPPD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z 9 9 9 26
31 34 35 36 37 38 39 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The false high radiation signal was the result of the monitor failing high, on
1 1 a loss of power. The high radiation transfer was deleted from the SGTS logic.
1 2 The standby train delta temperature trip signal was investigated but could not
1 3 be reproduced. The system was tested, operated as designed, and returned to
1 4 service.

1 5 FACILITY STATUS B 28 % POWER 0 0 0 29 OTHER STATUS n/a 30 METHOD OF DISCOVERY C 31 DISCOVERY DESCRIPTION Loss of Offsite Power Test 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 6 ACTIVITY CONTENT RELEASED Z 33 AMOUNT OF ACTIVITY n/a 35 LOCATION OF RELEASE n/a 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION n/a 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION n/a 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION n/a 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

2 0 PUBLICITY ISSUED DESCRIPTION N 44 n/a 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER D.G. Mitchell

PHONE (717) 542-2181 X524

Attachment

Licensee Event Report 82-062/01T-0

During performance of the Loss of Offsite Power Test, the Standby Gas Treatment System was to have initiated and operated as designed. However, the SGTS failed to operate for the following reasons. The lead train did not start because of a high radiation signal which transferred operation to the standby train. The false high radiation signal was the result of the monitor drifting high upon loss of power. This transfer function has been deleted from the SGTS logic. The standby train started, but did not continue to operate after the delta temperature requirement was not met, which tripped off that train. The delta temperature trip prevents operation of the standby train if the necessary inlet temperature is not reached within the required time. This trip function was checked out, and retested. The delta temperature trip did not actuate during the retests. The SGTS was retested, operated properly, and was returned to service.

During this event there were no adverse consequences because the reactor was shutdown and there were no abnormal releases to the secondary containment.