

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	A	S	0	S	3	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4		5
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	--	---

  
7 8 9 14 15 25 26 30 57 CAT 58

CONT

0	1	L	6	0	5	0	0	0	3	6	2	7	1	2	0	5	8	2	8	0	1	0	4	8	3	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 Diesel Generator 3G003 was taken out of service and as a result no boration flow

0 3 paths powered by emergency power sources were available contrary to Technical

0 4 Specification Section 3.1.2.3. There was no impact on plant operation or the health

0 5 and safety of plant personnel or the public associated with this event.

0 6

0 7

0 8

0	9	R	B	11	A	12	A	13	G	E	N	E	R	A	14	D	15	Z	16	17	18	2	19	0	0	5	20	0	3	21	L	22	0	23	1	0	24	0	25	1	0	1	1	26
---	---	---	---	----	---	----	---	----	---	---	---	---	---	---	----	---	----	---	----	----	----	---	----	---	---	---	----	---	---	----	---	----	---	----	---	---	----	---	----	---	---	---	---	----

  
7 8 9 10 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Loss of boration flow paths powered by emergency power sources was caused by

1 1 failure to recognize the effect of taking Diesel Generator 3G003 out of service

1 2 given that other paths were not available to satisfy the LCO. 3G003 was returned

1 3 to service at 0600 on December 5, 1982. Responsible Operations personnel have

1 4 reviewed the circumstances of this event and have been directed to perform a

1 5 more detailed review of the impact on plant operations of taking a diesel generator

1 6 out of service. This will also be included in their monthly retraining session.

1	5	B	28	0	0	0	29	N/A	30	B	31	Operator Review	32
---	---	---	----	---	---	---	----	-----	----	---	----	-----------------	----

  
7 8 9 10 12 13 44 45 46 80  

1	6	Z	33	Z	34	N/A	35	N/A	36
---	---	---	----	---	----	-----	----	-----	----

  
7 8 9 10 11 44 45 80  

1	7	0	0	0	37	Z	38	N/A	39
---	---	---	---	---	----	---	----	-----	----

  
7 8 9 11 12 13 80  

1	8	0	0	0	40	N/A	41
---	---	---	---	---	----	-----	----

  
7 8 9 11 12 80  

1	9	Z	42	N/A	43
---	---	---	----	-----	----

  
7 8 9 10 80  

2	0	N	44	N/A	45
---	---	---	----	-----	----

  
7 8 9 10 808301200109 830104  
PDR ADOCK 05000362  
S PDR

NRC USE ONLY

NAME OF PREPARER H.B. RAY HB Ray / JCM

PHONE 714-492-7700