EXHIBIT A

	CONTROL BLOCK:	QUIRED INFORMATION)
7 8	The state of the s	1 1 1 1 1 4 1 15 15
1 <u>0</u> 1 <u>1</u> 8	REPORT L 6 0 5 0 0 0 3 6 8 7 1 2 1 1 8 2 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74	
10121	EVENT DESCRIPTION AND PROBABLY CONSEQUENCES 10 [On 12/11/82, while starting cooldown with the unit in Mode 3, it was found that ma	in feedwater isolation valve !
10131	3 12CV-1024 for steam generator 'A' failed to operate. Redundant valve 2CV-1023-1 wa	s available and operable.
10141		operator were reported via [
10151	5	J-
10161	51 1	
10171	ZI I	
10181	3	1
10191		COMP VALVE SUBCODE A 15 Z 16 20 REPORT REVISION
17	LER/RO EVENT YEAR REPORT NO. CODE 17 REPORT 8 2	TYPE NO 1 1 0
	NUMBER 21 22 23 24 26 27 28 29	30 31 32
T/	ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS SUBMITTED FORM SUB A 18 X 19 Z 20 Z 21 10 0 0 22 N 23 1 Y 24 33 34 35 36 37 0 0 0 22 1 1 24 A 18 X 19 Z 20 Z 21 37 40 41 42 A TACHMENT NPRD-4 NPRD-4	PRIME COMP. COMPONENT SUPPLIER MANUFACTURER 1 A 25 1 L 2 1 0 1 0 126 43 44 47
1101	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 The cause of this occurrence appears to be insufficient clutch compression spring	force which caused partial [
1111		ious internal components.
11121	I Immediate corrective action was to replace damaged parts. After reassembly, the v	alve was satisfactorily
11131	[tested. A request for an engineering evaluation has been initiated to determine]	ong term corrective action.
11141		1 80
7 8	8 9 10 10 129 NA 30 A 31 Operational Even	Y DESCRIPTION
7 6	T Z 33 Z 34 NA	ON OF RELEASE 136
11171	NUMBER TYPE DESCRIPTION 0 0 0 37 Z 38 MA 8 9 11 12 13	139
	PERSONNEL INJURIES	80
1 8	NUMBER DESCRIPTION 1	141
8	TYPE DESCRIPTION PDR ADOCK 05000368	80
11191	1 1 Z 142 1 NA	143
7 1 0 1	PUBLICITY ISSUED DESCRIPTION I N 144 NA 8 9 10 6	NRC USE ONLY
	NAME OF DOEDADED D. F. Managaphara	DHONE: (501) 964-3100