

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: MIDCC2; LICENSE NUMBER: 00-000000-000; LICENSE TYPE: 41111; CAT 88: 4

REPORT SOURCE: L; DOCKET NUMBER: 05000316; EVENT DATE: 122382; REPORT DATE: 012183

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 DURING A REFUELING OUTAGE, THE WEST RHR HEAT EXCHANGER COMPONENT COOLING WATER... 03 OUTLET VALVE, CMO-429, WAS REMOVED FROM THE LINE TO DETERMINE THE CAUSE OF SEAT... 04 LEAKAGE. IT WAS DISCOVERED THAT PART OF THE ELASTOMER SEAT WAS MISSING FROM THE... 05 VALVE BODY. THE VALVE, WHICH HAD BEEN INSTALLED IN JAN., 1982, WAS REPLACED WITH... 06 A VALVE OF A DIFFERENT MANUFACTURER AND THE SYSTEM WAS RETURNED TO SERVICE. A... 07 SIMILAR OCCURENCE WAS REPORTED AS RO 82-007/03L-0.

SYSTEM CODE: W A; CAUSE CODE: E; CAUSE SUBCODE: D; COMPONENT CODE: VALVEX; COMP SUBCODE: B; VALVE SUBCODE: D

EVENT YEAR: 82; SEQUENTIAL REPORT NO.: 15; OCCURRENCE CODE: 03; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: C; FUTURE ACTION: Z; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0000; ATTACHMENT SUBMITTED: N; NRC-4 FORM SUB.: Y; PRIME COMP. SUPPLIER: A; COMPONENT MANUFACTURER: P340

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

08 THE SEAT LEAKAGE WAS DUE TO PART OF THE ELASTOMER SEAT MISSING FROM THE VALVE BODY. 09 THE CAUSE OF THE MISSING SEAT MATERIAL IS BEING INVESTIGATED.

FACILITY STATUS: A; % POWER: 000; OTHER STATUS: NA; METHOD OF DISCOVERY: A; DISCOVERY DESCRIPTION: DURING MAINTENANCE

ACTIVITY CONTENT RELEASED OF RELEASE: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES NUMBER: 000; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES NUMBER: 000; DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY TYPE: Z; DESCRIPTION: NA

PUBLICITY ISSUED DESCRIPTION: N; 8301280110 830121 PDR ADOCK 05000316 PDR