

LICENSEE EVENT REPORT

UPDATE REPORT

PREVIOUS REPORT DATE: 12/3/82

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I | L | D | R | S | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 32

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 4 | 9 | 7 | 1 | 1 | 1 | 2 | 8 | 2 | 8 | 1 | 2 | 1 | 7 | 8 | 2 | 9
7 8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

0 2 | During normal plant operation while performing routine plant inspection, water dis-
0 3 | covered spraying from the one inch drain line off of the bottom of 3A Feedwater Reg.
0 4 | Isolation Valve, MO3-3206A (T.S. 6.6.B.2.d). Event of minimal safety significance
0 5 | since all leakage was contained in Turbine Building floor drain sumps. No effect on
0 6 | public health or safety. Previous similar occurrences on Unit 3 were reported by
0 7 | R.O. 82-19 and 82-25 on Docket 50-249.

0 8 | _____

0 9 | SYSTEM CODE [C H] 11 CAUSE CODE [E] 12 CAUSE SUBCODE [B] 13 COMPONENT CODE [P I P E X X] 14 COMP. SUBCODE [A] 15 VALVE SUBCODE [Z] 16
7 8 9 10 11 12 13 14 15 16 17 18

17 | LER/RO REPORT NUMBER [8 2] 21 | SEQUENTIAL REPORT NO. [0 4 6] 24 | OCCURRENCE CODE [0 3] 28 | REPORT TYPE [X] 30 | REVISION NO. [1] 32
18 | ACTION TAKEN [F] 33 | FUTURE ACTION [Z] 34 | EFFECT ON PLANT [Z] 35 | SHUTDOWN METHOD [Z] 36 | HOURS [0 0 0 0] 37 | ATTACHMENT SUBMITTED [N] 41 | NPRO-4 FORM SUB. [N] 42 | PRIME COMP. SUPPLIER [N] 43 | COMPONENT MANUFACTURER [G 0 8 0] 47

1 0 | The leakage was caused by a cracked weld at the one inch drain line connection to
1 1 | MO3-3206A. The drain line was removed and refitted using a sock-o-let to provide
1 2 | additional reinforcement. System integrity continues to be verified by routine
1 3 | inspections by Operating.

1 4 | _____

1 5 | FACILITY STATUS [E] 28 | % POWER [0 9 8] 29 | OTHER STATUS [N/A] 30 | METHOD OF DISCOVERY [A] 31 | DISCOVERY DESCRIPTION [Routine Inspection by Shift Foreman] 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 6 | ACTIVITY CONTENT [Z] 33 | RELEASED OF RELEASE [Z] 34 | AMOUNT OF ACTIVITY [N/A] 35 | LOCATION OF RELEASE [N/A] 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 7 | PERSONNEL EXPOSURES NUMBER [0 0 0] 37 | TYPE [Z] 38 | DESCRIPTION [N/A] 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 8 | PERSONNEL INJURIES NUMBER [0 0 0] 40 | DESCRIPTION [N/A] 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE [Z] 42 | DESCRIPTION [N/A] 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20

2 0 | PUBLICITY ISSUED DESCRIPTION [N] 44 | DESCRIPTION [N/A] 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20

N/A
8301280125 821217
PDR ADOCK 05000249
S PDR

NRC USE ONLY

NAME OF PREPARER B. Christel

PHONE: 815-942-2920, X-421

U.S. GPO 1977-2-92

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12	- 3	- 82	- 77	

PART 1	TITLE OF EVENT	OCCURRED	
	Leak on 3A Feedwater Reg. Valve Drain Line	<u>11/12/82</u>	<u>0916</u>
		DATE	TIME
	REASON FOR SUPPLEMENTAL REPORT		
	Revised cause description		
PART 2			
	ACCEPTANCE BY STATION REVIEW	<u><i>J. Brunner</i></u>	<u><i>Michael Wright</i></u>
	DATE	<u>1/4/83</u>	<u>1-13-83</u>
	SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u><i>Douglas Scott</i></u>	<u>1/13/83</u>
		STATION SUPERINTENDENT	DATE