(7.77) LICENSEE EVENT REPORT CONTROL BLOCK: 10 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 - 0 0 3 4 1 1 1 1 0 57 CAT 56 5. 0 1 NJJSIGIS CON'T REPORT 10122888260111383 68 69 EVENT DATE 74 75 REPORT DATE 80 0 1 0 5 0 0 0 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On December 28, 1982, during routine surveillance on No. 21 Service Water Pump, an 0 2 operator noticed that the discharge strainer differential pressure was excessive. 03 Since No. 22 Pump was already inoperable, No. 21 Service Water Loop was rendered in-0 4 operable and Action Statement 3.7.4 was entered. The redundant loop was operable 0 5 throughout the occurrence; due to the loss of redundancy, the event constituted 0 6 operation in a degraded mode in accordance with Technical Specification 6.9.1.9.b. 0 7 0 8 SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE E R (14 TI 0 9 (16) OCCURRENCE SEQUENTIAL REVISION REPORT NO. CODE NO REPORT 14 9 0 3 0 NUMBER SUPPLIER SUBMITTED COMPONENT ACTION METHOD LANT HOURS (22) FORM SUB MANUFACTURER A 0 6 0 26 Z (19 N 24 Z (21) 0 0 0 0 Y 23 A Z (20) 25 (18)CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) 1 0 Investigation revealed that grassy debris and silt had plugged the strainer. The problem would not normally result in an inoperable header; the strainer was cleaned 1 1 the header was returned to service and the action statement was terminated. 1 2 1 3 1 4 METHOD OF STATUS OTHER STATUS (30) * POWER DISCOVERY DESCRIPTION (32) B (31) Surveillance Testing 1 5 (28) 0 6 1 CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35 OF RELEASE 1 6 34 (33) POSURES DESCRIPTION (39) Z (38) 1 7 NA PERSONNEL INJURIES DESCRIPTION (41) 1 8 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION B301280203 B30113 ADDCK 05000311 FDR 1 9 Z (42) 10 PUBLICITY NRC USE ONLY DESCRIPTION 45 2 0 R. Frahm (609) 935-6000 Ext 3078 PHONE: NAME OF PREPARER.