

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 |
 MIDCC2 |
 200 - 0000000 - 00 |
 3411111 |
 _____ | _____ | _____

CON'T
01 | REPORT SOURCE L6 | 05000316 | 7010783 | 8012183 | _____

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING A SURVEILLANCE TEST ON THE SPRAY ADDITIVE TANK FLOW RATE, BOTH EAST AND WEST
03 | CONTAINMENT SPRAY PUMP EDUCTOR LINE FLOW RATES FROM THE SPRAY ADDITIVE TANK WERE
04 | FOUND BELOW THE REQUIRED 20 GPM CONTRARY TO THE REQUIREMENTS OF TECHNICAL SPECIFI-
05 | CATION 4.6.2.2.d. THE PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
06 | _____
07 | _____
08 | _____

SYSTEM CODE SH | CAUSE CODE D | CAUSE SUBCODE Z | COMPONENT CODE VALVIOP | COMP. SUBCODE A | VALVE SUBCODE Z

LE/RO REPORT NUMBER 83 | SEQUENTIAL REPORT NO. 004 | OCCURRENCE CODE 01 | REPORT TYPE T | REVISION NO. 0

ACTION TAKEN EZ | EFFECT ON PLANT Z | SHUTDOWN METHOD Z | HOURS 0000 | ATTACHMENT SUBMITTED Y | NPR-4 FORM SUB. N | PRIME COMP. SUPPLIER N | COMPONENT MANUFACTURER A200

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | INVESTIGATION REVEALED THAT THE LOW FLOW RATES FROM THE RWST TEST LINE TO THE
11 | CONTAINMENT SPRAY PUMP EDUCTOR LINE WERE DUE TO THE CONTAINMENT SPRAY PUMP
12 | EDUCTOR VALVES IMO-212 AND IMO-222 BEING PARTIALLY CLOSED. THE VALVES WERE FULLY
13 | OPENED AND FLOW RATES WERE VERIFIED TO BE WITHIN THE ALLOWABLE TECHNICAL
14 | SPECIFICATION LIMITS. (SEE ATTACHED SUPPLEMENT)

FACILITY STATUS H | % POWER 000 | OTHER STATUS NA | METHOD OF DISCOVERY B | DISCOVERY DESCRIPTION SURVEILLANCE TEST

ACTIVITY CONTENT ZZ | AMOUNT OF ACTIVITY NA | LOCATION OF RELEASE NA

PERSONNEL EXPOSURES NUMBER 000 | TYPE Z | DESCRIPTION NA

PERSONNEL INJURIES NUMBER 000 | DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z | DESCRIPTION NA

PUBLICITY ISSUED N | DESCRIPTION NA

8301280205 830121
 PDR ADOCK 05000316
 S PDR

LER # 83-004/01T-0

SUPPLEMENT TO CAUSE DESCRIPTION

INVESTIGATION REVEALED THAT THE LOW FLOW RATES FROM THE RWST TEST LINE TO THE CONTAINMENT SPRAY PUMP EDUCTOR LINE WERE DUE TO THE CONTAINMENT SPRAY PUMP EDUCTOR VALVES IMO-212 AND IMO-222 BEING PARTIALLY CLOSED. THE VALVES WERE FULLY OPENED AND FLOW RATES WERE VERIFIED TO BE WITHIN THE ALLOWABLE TECHNICAL SPECIFICATION LIMITS.

IT WAS FOUND THAT DURING PREOPERATIONAL TESTING, THE SUCTION SOURCE (CONTAINMENT RECIRCULATION SUMP) DID NOT ADEQUATELY SIMULATE THE EXPECTED SUCTION PRESSURE OF THE CONTAINMENT SPRAY PUMPS DURING AN ACTUAL CONTAINMENT SPRAY, WHEN THE SPRAY ADDITIVE TANK IS EXPECTED TO BE USED. THE LOW CONTAINMENT SPRAY PUMP SUCTION PRESSURE WHICH EXISTED FROM USING THE RECIRCULATION SUMP TO SET THE FLOW (20 GPM \pm 1) THROUGH THE EDUCTOR RESULTED IN A NON-CONSERVATIVE EDUCTOR FLOW RATE. THE TECHNICAL SPECIFICATION REQUIRED EDUCTOR FLOW HAS SUBSEQUENTLY BEEN CHANGED BY AMMENDMENT 45 TO READ \geq 20 GPM TO \leq 50 GPM.

A SIMILAR FLOW CONDITION WAS REPORTED BY LER 050-316/78-024. THIS EVENT REPORTED THE INABILITY TO ESTABLISH FLOW THRU CHECK VALVE CTS-120E AS REQUIRED BY ASME SECTION XI. AT THAT TIME, IT WAS NECESSARY FOR THE EDUCTOR VALVES TO BE FULLY OPENED BY HAND. A RETEST OF THE CHECK VALVE WAS PERFORMED WHICH GAVE ACCEPTABLE RESULTS.