LICENSEE EVENT REPORT

CONTROL BLOCK 1 1 1 1 1 1 1 1 1
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 A L J M F 1 2 0 0 - 0 0 0 0 - 0 0 3 4 11 1 1 1 4 5 65 65 65 CAT 58
CON'T O 1 SOURCE L 60 0 5 0 0 10 3 4 8 7 1 12 3 0 8 12 8 0 11 12 8 8 3 9 O SOURCE SOURCE 60 0 1 1 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
[0] 2 At 2100 on 12/30/82, during the performance of FNP-0-STP-26.3, the "B" train
[0]3 chlorine detector was declared inoperable when control room supply damper HV3625
[0]4] [would not close. Tech. Spec. 3.3.3.6, in part, requires this chlorine detector
[0]5 to be operable. Tech. Spec. action statement requirements were met. Health/
[0]6 safety of the public was not affected. (Note: This LER is applicable to both
[0]7 Unit 1 and Unit 2 at FNP)
0 8 6
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
CODE
ACTION FUTURE SPECT SHUTDOWN METHOD HOURS CZ ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACT
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [1 [0] This event was caused by a faulty solenoid valve. The faulty solenoid valve
[1] was replaced and following the satisfactory completion of FNP-0-STP-26.3
[1] [(Control Room Ventilation Isolation Test), the "B" train chlorine detector
was declared operable at 1310 on 12/31/82.
7 8 9 FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 F (28) 0 9 8 (29) NA B (31) Surveillance Test
7 8 9 ACTIVITY CONTENT 12 13 44 45 46 10 ACTIVITY (35) ACTIVITY (35) AMOUNT OF ACTIVITY (35) NA NA NA NA
7 8 9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA
PERSONNEL INJURIES 80
NA 8302070617 830128
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTION 45
7 8 9 7D NA 68 69 80 3
W. G. Hairston, III (205) 899-5156