

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A T M I 1 2 3 4 1 1 1 1 4 5  
 7 8 9 14 15 25 26 30 57 CAT 56

CON'T  
 0 1 REPORT SOURCE L 6 0 5 0 0 0 2 8 9 7 0 1 0 1 8 3 8 0 2 0 1 8 3 9  
 7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
 0 2 During shutdown while RB Purge was in progress, station radiation monitor RM-A9, iodine  
 0 3 channel, failed. No significant occurrence took place. The particulate and noble gas  
 0 4 channels of RM-A9 were operable. No iodine above background was present since plant  
 0 5 has been in cold shutdown since 1979. Public health and safety were unaffected.  
 0 6 Reportable per 6.9.2.B(2)  
 0 7  
 0 8

0 9 SYSTEM CODE: B B (11); CAUSE CODE: E (12); CAUSE SUBCODE: A (13); COMPONENT CODE: I N S T R U (14); COMP. SUBCODE: E (15); VALVE SUBCODE: Z (16)  
 17 LER NO REPORT NUMBER: 8 3 (21); SEQUENTIAL REPORT NO.: 0 0 1 (24); OCCURRENCE CODE: / (27); REPORT TYPE: L (30); REVISION NO.: 0 (32)  
 ACTION TAKEN: A (33); FUTURE ACTION: X (34); EFFECT ON PLANT: Z (35); SHUTDOWN METHOD: Z (36); HOURS: 0 0 0 0 (40); ATTACHMENT SUBMITTED: Y (41); NPRD-4 FORM SUB.: Y (42); PRIME COMP. SUPPLIER: A (43); COMPONENT MANUFACTURER: V 1 1 5 (47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
 1 0 Failure of RM-A9 iodine channel was due to single channel analyzer circuit board  
 1 1 failure. Shortly before failure routine source check had been performed satisfactorily  
 1 2 purge was secured per TS Table 3.21-2. Circuit board replaced and quarterly calibra-  
 1 3 tion performed. No further corrective action required.  
 1 4

1 5 FACILITY STATUS: X (28); % POWER: 0 0 0 (29); OTHER STATUS: NRC Order (30); METHOD OF DISCOVERY: B (31); DISCOVERY DESCRIPTION: Operator Observation (32)  
 1 6 ACTIVITY CONTENT RELEASED OF RELEASE: Z (33); AMOUNT OF ACTIVITY: N/A (35); LOCATION OF RELEASE: N/A (36)  
 1 7 PERSONNEL EXPOSURES NUMBER: 0 0 0 (37); TYPE: Z (38); DESCRIPTION: N/A (39)  
 1 8 PERSONNEL INJURIES NUMBER: 0 0 0 (40); DESCRIPTION: N/A (41)

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42); DESCRIPTION: (43)  
 PUBLICITY ISSUED DESCRIPTION: N (44); DESCRIPTION: (45)

8302090175 830201  
 PDR ADOCK 05000289  
 S PDR

LER 83-01

I. Current Activities at the Time of the Occurrence

TMI Unit 1 was in a long term cold shutdown condition.

II. Circumstances Leading to the Occurrence

At 0150 on 1/1/83 RM-A9 Iodine channel, which monitors the Reactor Building purge effluent, failed. A Reactor Building purge was in progress at the time.

Shortly before the failure a routine source check of the Iodine channel had been satisfactorily performed.

III. Description

Per action statement 31 of Tech. Spec. Table 3.21-2 the purge which was in progress may continue for up to 28 days, provided that, within 4 hours after the channel has been declared inoperable, samples are continuously collected with auxiliary sampling equipment. The Reactor Building purge was terminated at 0155 hours on 1/1/83, within the required 4 hours.

While RM-A9 Iodine channel was out of service the minimum number of operable channels was less than that required by Tech. Spec. 3.21-2. This item is considered reportable under Technical Specification 6.9.2.B.(2) as operation in a degraded mode permitted by a limiting condition for operation.

IV. Resultant Event

No significant occurrence took place as a result of this event. The particulate and gas channels of RM-A9 were operable during the purge. No iodine above background was present since the plant has been in cold shutdown since 1979.

V. Previous Events of a Similar Nature

LER 82-07.

VI. Root Cause

Failure of RM-A9 iodine single channel analyzer circuit board.

VII. Immediate Corrective Action

Immediate corrective action was to secure the purge within the required time frame. An investigation revealed that the single channel analyzer circuit board of RM-A9 iodine channel had failed. The circuit board was

LER 83-01

(Continued)

replaced and SP 1302-3.1, RMS Quarterly Calibration, was performed to assure the channel was functioning properly following repair.

VIII. Long Term Corrective Action

No additional corrective action is required for this isolated case of component failure.

IX. Component Failure Data

Victoreen single channel analyzer circuit board, part number 842-3-6.