Pacific Gas and Electric Company

77 Beale Street, Room 1451 P.O. Box 770000 San Francisco, CA 94177 115/973-4684 Fax 415/973-2313 Gregory M. Rueger Senior Vice President and General Manager Nuclear Power Generation

April 25, 1994

PG&E Letter HBL-94-025

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington D.C. 20555

Docket No. 50-133, OL-DPR-7 Humboldt Bay Power Plant, Unit 3 Licensee Event Report 3-94-001-00 <u>Thermoluminescent Dosimeter Missing From Onsite Radiation Monitoring</u> Station Due To Unknown Reasons

Gentlemen:

Pursuant to 10 CFR 50.73(a)(2)(i)(B), PG&E is hereby submitting the enclosed Licensee Event Report concerning the inability to perform a required environmental radiation measurement required by the Technical Specifications due to dosimeters being missing from a monitoring station.

This event had no effect on the health and safety of the public.

Sincerely,

Gregory M. Rueger

cc: Lawrence G. Bell Stewart W. Brown Leonard J. Callan Kenneth E. Perkins Humboldt Distribution

HB3-94-QC-N001

Enclosure

6435S/BDP/2246

JEDZ .

LICENSEE EVENT REPORT (LER)

ACIUTY NAME (1)												NAME AND ADDRESS OF TAXABLE PARTY.	DOCKET NUMBER (2)							PAGE (3)					
HUMBOLDT BAY UNIT 3													0 5 0 0					1	3	3	and the second sec	QE	4		
TITLE (4)		HERMOL				r DC	DSIN	1ETE	RN	4I S S	ING F	ROM	ON:	SITE RA	DIAT	ION	MO	TIN	ORI	VG	STA	ATI(I NC	DUE	TO
EVENT DATE (6) LER NUMBER (6)										REPOR	T DAT		OTHER FACILITI					IES INVOLVED (8)							
MON	MON DAY YR		YR SEQUENTIAL NUMBER					REVISION NUMBER		MON	DAY	YR	F	FACILITY NAMES			DO	DOCKET NUMBER				S)			
																			0	5	0	0	0		
03	29	94	94	-	0	0	1	-	0	0	04	25	94	territori e de la constante de					0	5	0	0	0		-
PERATIN ODE (9)			THIS	REPORT	IS	SUBM	TTED	PURSI	JANT	TO TH	E REQUI	REMEN	TS OF	10 CFR: (11)				-						
POWEL LEVEL (30)		0 0				X		10 CF OTHER	19		0.73(a) in A			below and	in t	ext,	NR	C Fo	rm 3	66A)					
LEVEL (10)			S, 1	PLAN	T E			OTHER	(Sp	ecify		bstra	act 1	below and	l in t		ЕРНО	INE NU	MBER	66A)	T	4	44-	070	0
LEVEL (10)	0		S, 1	PLAN		NG I	INEE	ER	(Sp	ICENSEE	in A	bstra STFOR	THISL	below and		<u>TEI</u>	<u>EPHO</u>	NE N	MBER	664)	L	4	44-	070	10
LEVEL (10)	0					ENG I	INEE ETE OF	ER	(Sp U FOR ABLE	ICENSEE	in A	bstra CTFOR	THISL	below and		TE)	<u>EPHO</u>	ne ni area 70 Manu	MBER CODE 7		REPO	4 RTAB NPRD	LE	070	10
LEVEL (10)	O ROY B.	WILLI			C	ENG I	INEE ETE OF	ER NE LINE	(Sp U FOR ABLE	ICENSEE	in A	bstra CTFOR	THIS L	ER (12) ESCRIBED IN	THIS REP	TE)	<u>EPHO</u>	ne ni area 70 Manu	MBER CODE 7		REPO	RTAB	LE	070	0
LEVEL (30)	O ROY B.	WILLI			C	ENG I	INEE ETE OF	ER NE LINE	(Sp U FOR ABLE	ICENSEE	in A	bstra CTFOR	THIS L	ER (12) ESCRIBED IN	THIS REP	TE)	<u>EPHO</u>	ne ni area 70 Manu	MBER CODE 7		REPO	RTAB	LE	070)0
LEVEL (30)	O ROY B.	WILLI		м 	C ANUF TURE	ING I		ER NE LINE	(Sp U FOR ABLE RDS	EACH C	in A	bstra CTFOR	THIS L	ER (12) ESCRIBED IN	THIS REP		<u>EPHO</u>	ne ni area 70 Manu	MBER CODE 7		REPO	RTAB	LE S		DO

On March 29, 1994, while the Unit was in SAFSTOR, a technician was performing the quarterly exchange of the thermoluminescent dosimeters (TLDs) in onsite environmental radiation monitoring stations when he found that one of the stations did not contain a TLD packet. The Technical Specifications (TS) require that the dosimeters at these stations be monitored at least quarterly (TS Section V.B.6.b). A new TLD packet was installed for the second quarter monitoring period.

The root cause of this event is unknown, as the packet is believed to have been removed by unknown parties for unknown reasons.

Corrective action to help prevent recurrence included fitting this and similar monitoring stations with a tamper resistant seal to discourage opening the station. In addition, all plant personnel have been informed of the purpose and importance of the stations, and information labels have been attached to the stations.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	1	l	ER NUMBER	(6)		PAGE (3)
	아이지 않는 것 같은 것이 같이 많이 했다.	VEAR		SEQUENTIAL NUMBER		REVISION NUMBER		
HUMBOLDT BAY UNIT 3	0 5 0 0 0 1 3 3	94	-	0 0 1	-	00	2 0F	4

I. Initial Conditions

Unit 3 was in SAFSTOR.

II. Description of Event

A. Event:

On March 29, 1994, a packet of thermoluminescent dosimeters (TLDs) was found to be missing from an onsite environmental radiation monitoring station where quarterly monitoring is required by Technical Specification Section V.B.6.b. This packet had been installed on December 30, 1993.

B. Discovery:

On March 29, 1994, while the Unit was in SAFSTOR, a technician was performing the quarterly exchange of the TLDs in onsite environmental radiation monitoring stations when he found that one of the stations (identified as "T12", and located near the new Sandblasting Facility) did not contain a TLD packet. A new TLD packet was installed for the second quarter monitoring period.

C. Inoperable Structures, Components, or Systems that Contributed to the Event:

None.

D. Dates and Approximate Times for Major Occurrences:

1. December 30, 1993:

As part of Surveillance Test Procedure (STP) 3.16.11, "Quarterly Environmental Monitoring TLD Exchange," a packet containing TLDs (numbers 412, 413 and 414) was installed at station "T12".

2. Sometime between December 30, 1993 and March 29, 1994:

Event Date -- The TLD packet was removed.

3. March 29, 1994:

Discovery Date -- During the performance of STP 3.16.11, the packet of TLDs installed December 30, 1993 was found to be missing. A new TLD packet was installed for the second quarter monitoring period.

E. Other Systems or Secondary Functions Affected:

None.

015101010111313 941 LICENSEE EVENT REI The event was discovered when a technician, who was performing the radiation as in onsite environmental radiation as in one of the stations (identified as found that one of the stations (identified contain and located near the new Sandblasting Facility) did not contain "T12", and located near the new Sandblasting facility and TLD packet. OCKET HUMBOLDT BAY UNIT 3 The TLD packet for the next quarterly monitoring period was installed in the monitoring station. Method of Discovery: F. TLO packet. Operator Actions: the monitoring station. Safety System Responses: G. H. None. Cause of Event TLD exchange is performed by a Radiation and Process Monitor (RPM) with the TLD exchange is performed by a Radiation and Process Monitor (RPM) with the station and Process Monitor (RPM) with according indicate provide the station and Process and discussions according indicate the previous exchange (TLD had ensue who frequent the general at the observe of the quarter. Warious personnel the fectual the station indicate the about the megative resulted on 29, 1994. All the station was inspected with negative installed on 29, 1994. Sandbiaty of (TRG) concluded that individual some time form Various group (TRG) by an unknown individual some time form all the mean is an individual some time form (IRG) and unknown individual some time form all the mean is an individual some time form (IRG) and the mean is an individual some time form all the mean is an individual some time form (IRG) and (IRG) and (IRG) and Immediate Cause: The TLD exchange is performed by a Radiation and Process Monitor (RPM) according to STP 3.16.11. Review of the STP data sheets and discussion III. Unknown. A. 8. Analysis of Event Because plant personnel are unable to determine the first reportable ion adiation CFR 50.73(a)(2)(i)(B). When the data for the station. Inder to beyond the it will be possible to review this station. NRC are compiled, review the stations, and to review the it will the later results of the it will be possible to for the station. 11. The health and safety of the public were not affected by this event -64355

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

DOCKET NUMBER (2)

FACILITY NAME (1)

HUMBOLDT BAY UNIT 3

VLAII SEDUENTIAL NUMBER 0 5 0 0 0 1 3 3 94 - 0 0 1 -

ER NUMBER (6)

REVISION NUMBER

0 0

10F 4

4

V. Corrective Actions

- A. Immediate Corrective Actions:
 - The missing TLD packet was replaced with the packet for the next quarterly monitoring period.
- B. Corrective Action to Prevent Recurrence:
 - 1. To help prevent recurrence, each of the sevence "T"-series stations has been fitted with a plastic tamper resistant seal to discourage opening the station. In addition, all plant personnel have been informed of the purpose and importance of the monitoring stations, and information labels have been attached to the stations.

VI. Additional Information

A. Failed Components:

None.

B. Previous LERs on Similar Events:

None.