



Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401-1927 Telephone (612) 330-5500

May 4, 1994

10 CFR Part 50 Section 50.73

U S Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

> PRAIRIE ISLAND NUCLEAR GENERATING PLANT Docket Nos. 50-282 License Nos. DPR-42 50-306 DPR-60

Inoperability of RadWaste Building Ventilation System Radiation Monitor R-35 Went Undetected Because of Component Failure

The Licensee Event Report for this occurrence is attached. In the report, we made the following new NRC commitment:

Functional testing of the downscale failure feature for this type of monitor will be added to the annual calibration procedure.

Please contact us if you require additional information related to this event.

Michael Dwadley for Logu O Andrewn.

Director

Licensing and Management Issues

c: Regional Administrator - Region III, NRC NRR Project Manager, NRC Senior Resident Inspector, NRC Kris Sanda, State of Minnesota

Attachment

JEDZ!

9405100075 940504 PDR ADDCK 05000282 S PDR NRC FORM 366 (5-92)

U.S. MUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

Prairie Island Nuclear Generating Plant U1

DOCKET NUMBER (2) 05000 282 PAGE (3) 1 OF 3

TITLE (4) Inoperability of Radwaste Building Ventilation System Radiation Monitor R-35 Went Undetected Because of Component Failure

EVENT DATE (5)			LER MUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)					
MONTH	DAY	YEAR	YEAR	SEQUENTIAL REVISION MONTH DAY YEAR PRAIRIE ISLAND U2		1000	05000 306								
03	03	94	94		02		00		05	04	94	FACILITY NAME	DOCKET NUMBER		
OPER	ATING	N	THIS	REPORT	IS SUE	BMITTE	D PURSUA	ANT	TO THE	REQUIRE	MENTS	OF 10 CFR §: (Check one or m	ore)	(11)	
MODE	MODE (9)		20.402(b)				20.405	c)		50.73(a)(2)(iv)		73.71(b)			
POMER LEVEL (10)		2		20.405(a)(1)(i)				-	50.36(0)(1)		50.73(a)(2)(v)		73.71(c)	
		100%	20.405(a)(1)(ii)			-	50.36(0	50.36(c)(2)		50.73(a)(2)(vii)		OTHER			
*************	*************	<u> </u>	20	.405(a)(1)(ii	ii)		X	50.73(8)(2)(i)	DB-MID BRAICHISM	50.73(a)(2)(viii)(A)	(5	pecify in	
			20.405(a)(1)(iv) 20.405(a)(1)(v)			of management	50.73(8)(2)(ii)	50.73(a)(2)(viii)(B)		Abstract below and in Text, NRC Form 366A)			
						UNIVERSE STREET	50.73(8)(2)(11	i)	50.73(a)(2)(x)	7.75				

LICENSEE CONTACT FOR THIS LER (12)

NAME

Arne A Hunstad

TELEPHONE NUMBER (Include Area Code) 612-388-1121

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPROS			CAUSE	SYSTEM	COMPONENT	MANUFACTURER		REPORTABLE TO MPRDS	
YES (If	ves, comple		AL REPORT EXPE		x	MO		SUBI	PECTED MISSION E (15)	MONTH	DA	Y	YEAR

ABSTRACT (limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)
On February 7, 1994, radiation monitor R-35, RadWaste Building Ventilation
System Monitor, was removed from service for modification of its sampling
system. The modification was completed and the monitor was returned to
service on February 11. On March 3, the noble gas monitor in R-35 did not
respond when source-checked during the routine radiation monitor
surveillance. The RadWaste Building Ventilation System was secured OFF
until the monitor could again be made operable. During investigation of
the failure on March 4, a broken detector signal lead was discovered.
Further investigation led to the conclusion that the lead had probably been
broken during the modification done in February, and that the monitor had
been inoperable since that time. The monitor was repaired, source-checked
and returned to service on March 9. Based on weekly grab samples and
historical monitoring data, it was shown that no releases via the RadWaste
Building Ventilation System took place during the event.

NRC FORM 366A U.S. (5-92)	NUCLEAR REGULATORY COMMISSION	APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95						
LICENSEE EVENT REPO TEXT CONTINUAT		FORWARI THE IN (MNBB	NFORMATION COLLI D COMMENTS REGA NFORMATION AND 1 7714), U.S. NUCL GTON, DC 20555-0 ION PROJECT	ECTION REQUERING BURD RECORDS MA EAR REGULAT 1001, AND TO (3150-0104)	NAGEMENT BRANCH FORY COMMISSION, O THE PAPERWORK O, OFFICE OF			
FACILITY NAME (1)		LER NUMBER (6	PAGE (3)					
Prairie Island Unit 1		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 05 2			
TIMILIO IDIMIN OTTO I	05000 282	94	02	00	2 OF 3			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

EVENT DESCRIPTION

On February 7, 1994, radiation monitor R-35, RadWaste Building Ventilation System Monitor (EIIS Component Identifier MON), was removed from service for modification of its sampling system. The modification was completed and the monitor was returned to service on February 11. On March 3, the noble gas monitor in R-35 did not respond when source-checked during the routine radiation monitor surveillance. The RadWaste Building Ventilation System was secured OFF until the monitor could again be made operable. During investigation of the failure on March 4, a broken detector signal lead was discovered. Further investigation led to the conclusion that the lead had probably been broken during the modification done in February, and that the monitor had been inoperable since that time. The monitor was repaired, source-checked and returned to service on March 9. Based on weekly grab samples and historical monitoring data, it was shown that no releases via the RadWaste Building Ventilation System took place during the period R-35 was inoperable.

CAUSE OF THE EVENT

Cause of the monitor inoperability discovered on March 4 was component failure. Post-modification testing of the monitor in February did not detect its inoperability. The 'esting did not include source checking. Inoperability of the monitor's detector circuitry should have been seen as a downscale failure of the monitor's indicating meter. Degradation of a capacitor in the monitor electronics had defeated the downscale failure feature.

ANALYSIS OF THE EVENT

Technical Specification 3.9.F requires the RadWaste Building Ventilation Radiation Monitor to be operable with its alarm setpoint set to insure that release limits are not exceeded. The monitor provides no other automatic actions. If it is not operable, effluents may continue to be released if grab samples are taken every 8 hours. Since ventilation flow was occurring during the time the monitor was inoperable, a discharge above allowable limits would not have been alarmed, and grab samples would not have been taken. This event is being reported pursuant to 10CFR50.73(a)(2)(i)(B). No release occurred via the RadWaste Building Ventilation System during the event; therefore, public health and safety were not affected.

The event date (the day the inoperability was discovered) was March 3, 1994. Discussions within the plant staff and, later, discussions with the resident inspectors resulted in the conclusion that the monitor inoperability may not be reportable because no releases took place.

NRC FORM 366A U.S. MUCLI (5-92)	EAR REGULATORY COMMISSION	APPROVED BY OMB MO. 3150-0104 EXPIRES 5/31/95						
LICENSEE EVENT REPORT TEXT CONTINUATION	FORWAR THE 19 (MNBB WASHIN REDUCT	NFORMATION AND F 7714), U.S. NUCL GTON, DC 20555-0	EN ESTIMATE TO NAGEMENT BRANCH ORY COMMISSION, O THE PAPERWORK , OFFICE OF					
FACILITY NAME (1)	DOCKET NUMBER (2)	CONTROL VALUE AND A	LER NUMBER (6	PAGE (3)				
Prairie Island Unit 1		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 00 2			
TIGHT TO TOTAL OUT OF T	05000 282	94	02	00	3 OF 3			

TEXT (If more space is required, use additional copies of NRC Form 366A) (17)

Further discussion with the resident inspectors and a Region III-based NRC inspector, on April 4, 1994, led to the conclusion that the event is reportable. Therefore, the 30-day clock for reporting started on April 4.

CORRECTIVE ACTION

When the monitor failed to respond during its routine surveillance on March 3, the RadWaste Building Ventilation System was shut down, and investigation of the failure was begun.

The broken detector signal lead was repaired, the monitor source-checked and returned to service on March 9.

The degraded capacitor was replaced. The downscale failure feature of similar monitors was tested; one other monitor had to be adjusted to attain the desired response. Functional testing of the downscale failure feature for this type of monitor will be added to the annual calibration procedure.

The installed check source in this type of monitor is not useful for operability testing because of its low strength. Therefore, source-checking is done with an external source. For this reason, from an ALARA standpoint it is not prudent to source check the monitor after each maintenance activity. The monitor would be source-checked only after detector replacement or other work involving the detector or its cabling. Source-checking is done monthly and at the annual calibration.

FAILED COMPONENT IDENTIFICATION

Nuclear Measurements Corporation Gas Monitor Model APM-G25.

PREVIOUS SIMILAR EVENTS

A previous event regarding inoperability of R-35 was reported as Unit 1 LER 91-006.