(7.77)LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 L 6 0 5 0 0 0 2 2 0 7 0 6 2 3 8 1 3 0 7 2 1 8 1 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During a refueling outage, while performing ST-C-11 "Puff Test" of carbon dioxide hazards, it was found that hazard numbers 1, 2, 5, 9, 12 were in-0 3 operable. Electrical maintenance found the following: Hazard #1 had loose 0 4 relay wires; Hazard #'s 2, 5, 9 had sticky relays; Hazard #12 had loose wires 0 5 on control switch in Control Room. The plant was in shutdown mode and fire 0 6 watches were placed at required positions immediately. COMP SUBCODE COMPONENT CODE SUBCODE REVISION OCCURRENCE REPORT SEQUENTIAL LER RO EVENT YEAR SCODE NO. REPORT NO. PRIME COMP COMPONENT NPRO-4 HOURS (22) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The loose wires on the 125 valt D.C. Cardox relays with a mercury tube switch and solenoid were tightened and the sticky relays were lubricated. The test was rerun and all hazards operated in accordance with Tech Specs. Surveillance testing will increased from every two years to semiannually for all hazards. METHOD OF DISCOVERY DESCRIPTION (32) OTHER STATUS & POWER DISCOVERY 0 0 10 B (31) SURVEILLANCE TESTING 9 10 ACTIVITY CONTENT LOCATION OF RELEASE (36)

AMOUNT OF ACTIVITY (35 RELEASED OF RELEASE NA 80 10 11 PERSUNNEL EXPOSURES DESCRIPTION (39) TYPE NUMBER 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 00 (40) LOSS OF OR DAMAGE TO FACILITY (43 DESCRIPTION Z (42) PUBLICITY NRC USE ONLY 8107290071 810721 PDR ADDCK 05000220 DESCRIPTION (45) 1(44) NAME OF PREPARER \_ Richard Neild PHONE: (315) 343-2110