	LICENSEE EVENT REPORT
co	NTROL BLOCK PRINT OR TYPE ALL REQUIRED INFORMATION
0 1 N	J S G S 2 2 0 0 - 0 0 0 0 0 0 3 4 1 1 1 1 4 1 5 6 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 1 1 7 0 6 2 2 8 1 8 0 7 2 2 8 1 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 NT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 L D	uring startup on June 22, 1981, the control operator noticed that the individual
03 1	od position indicator and control rod bank demand indicator for rod 1B4 were in
0 4 d	isagreement by greater then \pm 12 steps. The individual rod position indicator
0 5 W	as declared inoperable at 1640 hours and action statement 3.1.3.2.1 was entered.
0 6 T	his occurrence constituted operation in a degraded mode in accordance with
0 7 t	echnical specification 6.9.1.9.b.
7 8 9	SYSTEM CAUSE CAUSE COMP VALVE
0 9 8	CODE SUBCODE S
0	LER RO EVENT YEAR REPORT NO OCCURRENCE REPORT TYPE NO NO NO O 1/1 6
ACTIC TAKE E 33	18 Z 19 Z 20 Z 20 J 10 0 0 Y 23 Y 24 L 25 M 0 3 5 3
	quipment failure. The individual rod position indicator for control rod lB4 was
1 1 J n	ot in agreement with the control rod bank demand position indicator due to drift
1210	n the calibration of the signal conditioning module. The signal conditioning
1 3 m	odule was recalibrated and returned to service. Action statement 3.1.3:2.1 was
	erminated at 1933 hours, June 22, 1981.
7 8 9 FACILITY STATE	TY POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 (28) 0 0 0 0 29 N/A A 31 Operator Observation 80
RELEAS	TY CONTENT ED OF RELEASE AMOUNT OF ACTIVITY 35 33 Z 34 NA LOCATION OF RELEASE 36 NA N
17 0	UMBER TYPE DESCRIPTION (9) O O O 37 Z 38 NA RESONNEL INJURIES 13 85
18 6	O O NA
1 9 Z	OF OR DAMAGE TO FACILITY 43 DESCRIPTION NA 10
ISSUE	DESCRIPTION 45 OF DESCRIPTION 45 NRC USE ONLY OF DESCRIPTION 45
81072900 PDR ADDO	Frank Dickey PHONE 609-935-5100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0