LICENSEE EVENT REPORT

CONTROL BUDGE: 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
0 1 N J S G S 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58
CON'T SOURCE LO 5 0 0 3 1 1 7 0 0 2 7 8 1 8 0 7 2 7 8 1 9 TO 1 SOURCE SO 61 DOCKET NUMBER 68 69 EVENT DATE 75 REPORT FILE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2
0 3 a reactor trip and safety injection. The boron injection tank concentration
0 4 decreased to less than 20,000 ppm of boron. Action statement 3.5.4.1.b was entered
0 5 at 0408 hours, June 27, 1981. Similar occurrences: 81-09 and 81-32.
0 7
0 8 L
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SU
COMPONENT COMP
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The safety injection caused dilution of the boron injection tank. The tank was
borated until the concentration was within the allowable limits. The action
statement was terminated at 1622 hours, June 27, 1981.
13
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 E 28 0 3 0 29 N/A A 31 Operator Observation 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA NA NA NA NA NA NA NA NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 8 9 11 12 13
PERSONNEL INJURIES NUMBER DESCRIPTION 41 7 8 9 11 12
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION Z 42 NA
PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY
8108060220 810727 RER Frank Dickey PHONE 609-935-5100