

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 N C B E P 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 7 2 7 8 1 8 0 8 1 0 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a reactor startup it was discovered that control rod 34-19 had continuous
03 "full-in" RTGB position indication regardless of actual rod position. The rod was
04 then bypassed in the Rod Sequence Control System in accordance with technical speci-
05 fications. This event did not affect the health and safety of the public.
06
07

08 Technical Specifications 3.1.3.7, 6.9.1.9b

09 SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE F 13 COMPONENT CODE I N S T R U 14 COMP SUBCODE X 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 8 1 21 22 EVENT YEAR 8 1 23 24 SEQUENTIAL REPORT NO. 0 6 4 25 26 OCCURRENCE CODE 0 3 27 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
ACTION TAKEN A 18 33 FUTURE ACTION Z 19 34 EFFECT ON PLANT Z 20 35 SHUTDOWN METHOD Z 21 36 HOURS 0 0 0 0 22 37 ATTACHMENT SUBMITTED Y 23 40 NPRD-4 FORM SUB. Y 24 42 PRIME COMP. SUPPLIER N 25 43 COMPONENT MANUFACTURER G 0 8 0 26 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Transistor Q16, model number 2N3417, and integrated circuit G33, model number
11 176A1664P936, located on the rod position indication system probe buffer card failed
12 due to apparent end of life and caused the indication problem. The transistor and
13 the circuit were replaced and the rod position indication returned to normal. No
14 further corrective action to this event is required.

15 FACILITY STATUS C 25 26 % POWER 0 0 1 29 30 OTHER STATUS NA 31 METHOD OF DISCOVERY A 32 33 DISCOVERY DESCRIPTION Operational Event 34

16 ACTIVITY CONTEN. RELEASED OF RELEASE Z 33 34 35 AMOUNT OF ACTIVITY NA 36 LOCATION OF RELEASE NA 37

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 38 TYPE Z 39 DESCRIPTION NA 40

18 PERSONNEL INJURIES NUMBER 0 0 0 40 41 DESCRIPTION NA 42

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 43 DESCRIPTION NA 44

20 PUBLICITY ISSUED N 44 45 DESCRIPTION NA 46 47 NRC USE ONLY 48 49 50

NAME OF PREPARER M. J. Pastva, Jr. PHONE 919-457-9521

LER ATTACHMENT - RO #2-81-64

Facility: BSEP Unit No. 2

Event Date: 7-27-81

The failures of transistor Q16 and the integrated circuit G33 of the probe buffer card for rod 34-19 do not constitute a safety hazard and are expected on an occasional basis. Therefore, whenever these type failures do occur and are determined to have resulted from natural end of component life, they will be repaired as required.