

LICENSEE EVENT REPORT

UPDATE REPORT - PREVIOUS REPORT

DATE 08/19/80

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

REPORT
SOURCE

L	6	0	5	0	0	0	3	2	1	7	0	7	2	6	8	0	8	0	8	2	0	8	1	9
60	61	DOCKET NUMBER										68	EVENT DATE					74	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

012 | During normal operation, Drywell and Torus Temperature Recorder, 1T47-R611.

03 | was found inoperative. The redundant recorder, 1T47-R612, was operating

04 | normally. This is a repetitive event as last reported on reportable

05 | Occurrence Report No. 50-321/1980-075. There was no effect upon the

06 | Public health and safety due to this event.

0 9 11 12 13 14 15 16

(17) LER/RO REPORT NUMBER EVENT YEAR REPORT NO. CODE TYPE NO
 [8][0] [—] [0][8][9] [—] [0][3] [L] [—] [1]

ACTION TAKEN (C) (18) FUTURE ACTION (Z) (19) EFFECT ON PLANT (Z) (20) SHUTDOWN METHOD (Z) (21) HOURS (0) (0) (0) (0) (22) ATTACHMENT SUBMITTED (Y) (23) NPRD-4 FORM SUB. (N) (24) PRIME COMP. SUPPLIER (A) (25) COMPONENT MANUFACTURER (T) (0) (3) (9) (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Upon investigation the cause was found to be a stripped gear in the print

1 1 | drive mechanism. The gear was replaced and the recorder was placed in

1 2 | normal operation. A design change was initiated to replace this recorder.

1 3 | The new recorder was installed on May 22, 1981 and no further problems

1 4 | have been experienced.

FACILITY STATUS				POWER				OTHER STATUS (30)				METHOD OF DISCOVERY				DISCOVERY DESCRIPTION (32)			
1	5	E	(28)	0	1	5	(29)	NA				B	(31)	Operator observation					

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 | Z (33) | Z (34) | NA (35)

AMOUNT OF ACTIVITY

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION		(39)			
1	2	0	0	0	(37)	7	(38)	NA	

PERSONNEL INJURIES		NUMBER		DESCRIPTION		NA	
1	2	0	0	0	(40)		

1 9		Z (43)		DESCRIPTION	LOSS OF OR DAMAGE TO FACILITY
				NA	

		PUBLICITY		8108280279 810820	NRC USE ONLY
ISSUED	DESCRIPTION	(45)		PDR ADDCK 05000321	
2 0	N (44)		S	PDR NA	

NAME OF PREPARER R. T. Nix, Supt. of Maint.

PHONE: 912-367-7781

LER No.: 50-321/1980-089, Rev. 1.
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-321

Narrative Report
for LER 50-321/1980-089, Rev. 1.

During normal operation, Drywell and Torus Temperature Recorder, 1T47-R611, was found inoperative. The redundant recorder 1T47-R612 was operating normally. This is a repetitive occurrence as last reported on Reportable Occurrence Report No. 50-321/1980-075. There was no effect upon the public health or safety due to this event.

The failure of the recorder was due to a stripped gear in the print drive mechanism. The gear was replaced and the recorder returned to service. A design change was initiated to replace this recorder. The new recorder was installed on May 22, 1981, and no further problems have been experienced.