

LICENSEE EVENT REPORT

LER 81-19/3L

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | V | T | V | Y | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 23 26 LICENSE TYPE 27 57 CAT 58

CON'T
0 1 | I | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 1 | 7 | 0 | 3 | 0 | 6 | 8 | 1 | 8 | 0 | 8 | 2 | 0 | 8 | 1 | 9
7 8 9 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 RL-ORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2 | During surveillance testing of the SBT Charcoal Cells per T. S. 4.7.B.2.C. An in-
0 3 | terfering peak was found on the chromatogram. Several attempts were made to purge
0 4 | charcoal without success. The charcoal was subsequently replaced and successfully
0 5 | tested. Because of the length of time the SBT was out of service for testing, this
0 6 | is considered reportable under T. S. 6.7.B.2.b. There were no consequences to the
0 7 | health and safety of the public as a result of this occurrence. There were no
0 8 | previous occurrences of this type. _____ 80

0 9 | S | C | 11 | D | 12 | Z | 13 | F | I | L | T | E | R | 14 | Z | 15 | Z | 16
7 8 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
17 | LER RO | EVENT YEAR | SEQUENTIAL | OCCURRENCE | REPORT | REVISION
REPORT | NUMBER | 8 | 1 | 9 | 0 | 1 | 9 | 3 | L | 0
NUMBER | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32
ACTION | FUTURE | EFFECT | SHUTDOWN | HOURS | ATTACHMENT | NPRD-4 | PRIME COMP | COMPONENT
TAKEN | ACTION | ON PLANT | METHOD | 0 | 0 | 0 | 0 | N | Y | L | MANUFACTURER
33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47
A | G | Z | Z | 0 | 0 | 0 | 0 | N | Y | L | N | 2 | 3 | 0 | 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1 0 | An unknown interference appeared on the chromatogram during halogenated hydrocarbon
1 1 | testing of the SBT Charcoal Cells. Several attempts were made to purge the char-
1 2 | coal then the charcoal was replaced. After replacement of the charcoal, the test
1 3 | was completed satisfactorily. Guidelines will be provided to indicate the corrective
1 4 | action to be taken when the interfering peak occurs. _____ 80

1 5 | E | 28 | 1 | 0 | 0 | 29 | NA | D | 31 | NA | 32
7 8 9 FACILITY STATUS 10 % POWER 11 OTHER STATUS 12 METHOD OF DISCOVERY 13 DISCOVERY DESCRIPTION 14

1 6 | Z | 33 | Z | 34 | NA | 35 | NA | 36
7 8 9 ACTIVITY CONTENT 10 RELEASED OF RELEASE 11 AMOUNT OF ACTIVITY 12 LOCATION OF RELEASE 13

1 7 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39
7 8 9 PERSONNEL EXPOSURES 10 NUMBER 11 TYPE 12 DESCRIPTION 13

1 8 | 0 | 0 | 0 | 40 | NA | 41
7 8 9 PERSONNEL INJURIES 10 NUMBER 11 DESCRIPTION 12

1 9 | Z | 42 | NA | 43
7 8 9 LOSS OF OR DAMAGE TO FACILITY 10 TYPE 11 DESCRIPTION 12

2 0 | N | 44 | NA | 45
7 8 9 PUBLICITY 10 ISSUED 11 DESCRIPTION 12

8108310290 810820 PDR ADDOCK 05000271 S PDR
PARER Warren P. Murphy PHONE: (802) 257-7711
NRC USE ONLY

GPO 917-926