U.S. NUL EAR REGULA NRC FORM 366 17.771 LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 1(1) CONTROL BLOCK 4 1 1 1 1 1 000 - 0 0 0 0 0 HDBS 1 ØI 0 LICENSE NUMBER L 6 0 5 0 0 3 4 6 0 8 1 9 8 1 8 9 9 1 5 8 1 9 0 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 CONT REPORT 511 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10 (NP-33-81-59) At 1805 hours upon completion of ST 5030.17, it was noted that when the 0 2 intermediate range test module was returned to "test operate" and "operate" positions 0 3 that the logarithmic amplifier indication remained pegged high. NI-4 was declared 2 4 inoperable, however, power operation continued per Technical Specification 3.3.1.1 2 5 and Table 3.3-1. There was no danger to the health and safety of the public or sta-016 tion personnel. The redundant intermediate logarithmic amplifier was in operation during this period. 3 8 COMP VALVE CAUSE CAUSE SYSTEM COMPONENT CODE SUBCODE SUBCODE ZI EL U (14 G (13 N SITI RI T E (12 IA 18 13 REVISION OCCURRENCE REPORT SEQUENTIAL NO. CODE TYPE REPORT NO. EVENT YEAR LS ØI LER RO 013 L 11 9 REPORT 31 NUMBER COMPONENT NPRD-4 PRIME COMP. ATTACHMENT SUBMITTED HOURS (22) SHUTDOWN MANUFACTURER EFFECT ON PLANT SUPPLIER ACTION FUTURE FORMSUB B | Ø | 4 | 5 N (25 Y (24) (26) Ø IY 23 Ø 10 10 Z (21 Z C X CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause was a component failure on board PC-1, the first stage log driver of the 0 low level amplifier assembly of the logarithmic amplifier. On 8/24/81 at 1515 hours, a new logarithmic amplifier was installed in the system, tested, and the channel returned to service. The log amplifier assembly will be returned to Bailey for repair and evaluation. 80 1 4 METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32) (30) FACILITY OTHER STATUS - POWER Surveillance Test ST 5030.12 B (31) 1 0 0 NA E (28) 80 LOCATION OF RELEASE (36) ACTIVITY CONTENT AMOUNT OF ACTIVITY (35 RELEASED OF RELEASE NA Z 33 Z (34) NA 6 80 EXPOSURES PERSONNEL DESCRIPTION (39) NUMBER TYPE Z 38 NA 0000 80 PERSONNEL INJURIES DESCRIPTION (41) 010 NA 40 \$23 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION Z (42) NA 9 80 810915 8109230467 NRC USE ONLY PUBLICITY 05000346 DESCRIPTION (45) PDR ADOCK ISSUED A PDR Q NA 69 (419) 259-5000, Ext. 235 PHONE: Robert Whitsell DVR 81-118 NAME OF PREPARER .

## TOLEDO EDISON COMPANY DAVIS-BESSE NUCLEAR POWER STATION UNIT ON SUL. FMENTAL INFORMATION FOR LER NP-33-81- 9

## DATE OF EVENT: August 19, 1931

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Reactor Protection System (RPS) Channel 3 int\_rmediate range indication 'pegged high" when returning channel to operate following performance of Surveillance Test ST 5030.17, Intermediate Range Pre-Startup Functional Test

Conditions Prior to Occurrence: The unit was in Mode 1 with Power (MWT) = 2769 and Load (Gross MWE) = 906

Description of Occurr .ce: On August 19, 1981 at 1805 hours upon completion of Surveillance Test ST 5030.17, it was noted that when the intermediate range test module was returned to test operate and operate positions, that the logarithmic amplifier indication remained off-scale high instead of reading 10-4 amps as it had prior to the test.

A test deficiency list was completed and NI-4 was declared inoperable. Per Technical Specification 3.3.1.1 and Table 3.3-1, power operation was permitted to continue as reactor power was greater than 5% at the time.

Designation of Apparent Cause of Occurrence: The "pegged high" indication was caused by component failure on board PC 1, first stage logarithmic driver of low level amplifier assembly of the logarithmic amplifier. The low level amplifier is a canned unit and exact component failure not determined. The log amplifier assembly will be returned to Bailey for repair and evaluation.

Analysis of Occurrence: There was no danger to the health and safety of the public or station personnel. The redundant intermediate logarithmic amplifier (Chanael 4) was in operation during this period to provide indication which is the function of the logarithmic amplifier. As the plant was greater than 5% power, the four power range instruments were providing protective actions and indications and the intermediate ranges were acting as backup indication.

Corrective Action: On August 20, 1981, Maintenance Work Order IC-567-81 was issued to troubleshoot and repair NI-4. At 1515 hours on August 24, 1981, a new logarithmic amplifier which had been calibrated per Bailey instruction E92-314 was installed in the system, tested, and the channel returned to service.

Failure Data: There have been no previously reportable occurrences of intermediate range logarithmic applifier tailing off-scale high.

LER #81-049