11-111

	CONTROL BLOCK:
0 1	
CON'T	REPORT I 6 0 5 0 0 0 3 0 5 7 0 8 1 7 8 1 8 0 9 1 6 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	ISI testing of the Auxiliary Feedwater pumps was not performed within 7 days after
0 3	reaching a 350°F primary temperature. This was detected in a routine safety inspection
0 4	by our resident inspector and documented in his report 50-205/81-12. This is report-
0 5	able per T. S. 6.9.2.6.3. There was no effect on public safety or plant operation.
0 6	
0 7	
0 8	9 80
0 9	SYSTEM CODE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBCO
	The contact of the
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	
1 0	Misinterpretation of ASME Con- Section XI resulted in a surveillance period greater
	Misinterpretation of ASME Con-Section XI resulted in a surveillance period greater
	Misinterpretation of ASME Con-Section XI resulted in a surveillance period greater than allowed by this code. The pure's were promptly tested and procedures SP 05-104 &
112	Misinterpretation of ASME Con-Section XI resulted in a surveillance period greater than allowed by this code. The pures were promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code.
1 1 2 1 3 1 4 7 8 1 5	Misinterpretation of ASME Cop-Section XI resulted in a surveillance period greater than allowed by this code. The pures were promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code. 105 have been revised to comply with the code. 106 have been revised to comply with the code. 107 have been revised to comply with the code. 108 have been revised to comply with the code. 109 have been revised to comply with the code. 100 have been revised to comply with the code. 101 have been revised to comply with the code. 102 have been revised to comply with the code. 103 have been revised to comply with the code. 105 have been revised to comply with the code. 106 have been revised to comply with the code. 107 have been revised to comply with the code. 108 have been revised to comply with the code. 109 have been revised to comply with the code. 109 have been revised to comply with the code. 100 have been revised to comply with the code. 100 have been revised to comply with the code. 100 have been revised to comply with the code. 101 have been revised to comply with the code. 102 have been revised to comply with the code. 103 have been revised to comply with the code. 105 have been revised to comply with the code. 106 have been revised to comply with the code. 107 have been revised to comply with the code. 108 have been revised to comply with the code.
1 1 2 1 3 1 4 7 8 1 5 7 8 1 6	Misinterpretation of ASME Co. Section XI resulted in a surveillance period greater than allowed by this code. The panals were promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code. 105 have been revised to comply with the code. 106 Pacility Status (30) METHOD OF DISCOVERY DESCRIPTION (32) 107 POWER OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) 108 POWER DISCOVERY DESCRIPTION (32) 109 POWER DISCOVERY DESCRIPTION (32) 100 POWER DISCOVERY DESCRIPTION (32) 100 POWER DISCOVERY DESCRIPTION (32) 101 POWER DISCOVERY DESCRIPTION (32) 102 POWER DISCOVERY DESCRIPTION (32) 103 POWER DISCOVERY DESCRIPTION (32) 105 POWER DISCOVERY DESCRIPTION (32) 106 POWER DISCOVERY DESCRIPTION (32) 107 POWER DISCOVERY DESCRIPTION (32) 108 POWER DISCOVERY DESCRIPTION (32) 109 POWER DISCOVERY DESCRIPTION (32) 109 POWER DISCOVERY DESCRIPTION (32) 100 POWER DISCOV
1 1 2 1 3 1 4 7 8 1 5 7 8	Misinterpretation of ASME Co 2 Section XI resulted in a surveillance period greater than allowed by this code. The pulse were promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code. 105 have been revised to comply with the code. 105 have been revised to comply with the code. 105 have been
1 1 2 1 3 1 4 7 8 1 5 7 8 1 6	Misinterpretation of ASME Co 2 - Section XI resulted in a surveillance period greater than allowed by this code. The panes were promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code. 105 have been revised to comply with the code. 106 have been revised to comply with the code. 107 have been revised to comply with the code. 108 have been revised to comply with the code. 109 have been revised to comply with the code. 100 have been revised to comply with the code. 10
1 1 2 1 3 1 4 7 8 1 6 7 8 1 7 7 8 1 8 1 8	Misinterpretation of ASME Co 2 - Section XI resulted in a surveillance period greater than allowed by this code, The panes were promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code. 105 have been revised to comply with the code. 106 have been revised to comply with the code. 107 have been revised to comply with the code. 108 have been revised to comply with the code. 109 have been revised to comply with the code. 100 have been revised to comply with the code. 10
1 1 2 1 3 1 4 7 8 1 5 7 8 1 7 8 1 8 7 8	Misinterpretation of ASME Co 2 Section XI resulted in a surveillance period greater than allowed by this code. The public swere promptly tested and procedures SP 05-104 & 105 have been revised to comply with the code. 105 have been revised to comply with the code. 105 have been revised to comply with the code. 106 have been revised to comply with the code. 107 have been revised to comply with the code. 108 have been revised to comply with the code. 109 have been revised to comply with the code. 100 have been revised to comply with the code.