

LICENSE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 ALBRF1 200-000000-00 341111 45  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
01 REPORT SOURCE L 605000259 7021080 8092581 9  
7 8 80 81 88 89 94 95 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  
02 With unit 1 in a scheduled refueling outage, unit 2 at steady state power of 1087 MWe,  
03 and unit 3 at 1100 MWe, steady state power, notification was received from TVA's  
04 Division of Engineering Design that, should a recirculation system line break be  
05 followed by a reactor building closed cooling water line break, valve failure, and  
06 system drainage, degradation of primary system integrity could result. There was no  
07 danger to the health or safety of the public. No previous occurrence. Redundancy  
08 does not apply. 80

09 SYSTEM CODE SA 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE ZZZZZZ 14  
7 8 9 10 11 12 13 18 19 20 15 16  
17 LER/RO REPORT NUMBER 80 21 EVENT YEAR 80 22 SEQUENTIAL REPORT NO. 016 23  
7 8 21 22 23 24 26 27 28 29 30 31 32  
ACTION TAKEN G 18 Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 000 22 ATTACHMENT SUBMITTED Y 23  
33 34 35 36 37 40 41 42 43 44 47  
NPRD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER Z 25 COMPONENT MANUFACTURER Z999 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27  
10 Subsequent evaluation by EN DES determined no immediate safety significance exists.  
11 Evaluation determined two areas where postulated circumferential break locations in  
12 the recirculation have potential for RBCCW line impingement. It is EN DES's judgment  
13 that RBCCW integrity would not be lost due to impingement and no immediate corrective  
14 actions are required. 80

15 FACILITY STATUS H 28 % POWER 000 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION 32  
7 8 9 10 11 12 13 44 45 46 80  
16 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 44 45 80  
17 PERSONNEL EXPOSURES 000 37 Z 38 DESCRIPTION 39 NA  
7 8 9 10 11 12 13 80  
18 PERSONNEL INJURIES 000 40 DESCRIPTION 41 NA  
7 8 9 10 11 12 80  
19 LOSS OF OR DAMAGE TO FACILITY Z 42 DESCRIPTION 43 NA  
7 8 9 10 11 12 80  
20 PUBLICITY N 44 DESCRIPTION 45 NA  
7 8 9 10 11 12 80

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 80016 R1 Technical Specification Involved 3.7.A.2

Reported Under Technical Specification 6.7.2.A.9 \*Date due NRC: NA

Date of Occurrence 2/10/80 Time of Occurrence 1900 Unit 1, 2, 3

Identification and Description of Occurrence:

TVA Division of Engineering Design notified BFNP that design problems existed whereby, should a recirc line break be followed by a RBCCW line break, the RBCCW system could drain and thereby degrade primary containment integrity.

Conditions Prior to Occurrence:

Unit 1 - scheduled refueling outage.

Unit 2 - 1087 MWe, steady state.

Unit 3 - 1100 MWe, steady state.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Design deficiency

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant occurrence.

Corrective Action:

None required at this time based on information provided by TVA Engineering Design. This deficiency is still under evaluation and any further actions taken will be provided in a supplemental report.

Failure Data:

NA

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

\*Revision:

*ALL*