U.S NUCLEAR REGULATORY COMMISSION CPN JOE LICENSEE EVENT EEPORT CONTROL BLOCK IPLEASE PRINT OR TYPE ALL REQUIRED INFORMATION V A S P SI E 01 51 01 0 01 21 8 0 0 01 9 0 2 8 1 6 0 9 12 19 18 11 REPORT SOURCE DOCKET NUMBER EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10 With the unit at 100% power, it was discovered the high alarm set point for component cooling radiation monitor RM-CC-105 had been exceeded without the annunciator alarming or the CC surge tank vent closing. The effluent from the surge tank vent enters the process vent system where it is continuously monitored. No increase in | activity was evident; therefore the health and safety of the public were not affected. This event is contrary to T.S.3.7.E and is reportable per T.S. 6.6.2.b (4). CODE CAUSE CAUSE COMP SUBCODE CODE SUBCODE COMPONENT CODE SUBCODE E (12) G (13) IINSITIRU 14 Y (15) MC 12116 12 18 OCCURRENCE SEQUENTIAL REVISION ACPORT REPORT NO. EVENT YEAR CODE LERIRO NO. REPORT 18 | 1| 0 | 4 | 2 1013 10 25 28 FUTURE EFFECT ON PLANT METHOD HOURS 2 S SUBMITTED NPRD PRIME COMP COMPONENT MANUFACTURES FORM SUE. 1(25) N (74) - Y 3 2 (31 01010101 A (18) Z V |1 |1 |5 Z A 25 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause of the event was a failed log ratemeter card in the radiation monitor. The card was replaced, the instrument calibrated, and the radiation monitor was returned to service. 80 METHOD OF STATUS (30) S POWER OTHER STATUS DISCOVERY DESCRIPTION (32) 1(28) 0 0 29 A (31) Operator Observation N/A CTIVITY CONTENT 45 80 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE (36) OF RELEASE RELEASED Z 34 1 (33) Z N/A N/A 10 80 PERSONNEL EXPOSURES DESCRIPTION (39 TYPE NUMBER 0 (37) z (32) 0 N/A PERSONNEL INJURIES 20 DESCRIPTION (41 NUMBER 10 0 (20) N/A 0 DESCRIPTION EC OSS OF OF DAMAGE TO FACILITY (23 8110060454 810929 PDR ADDCK 05000280 PUBLICITY N C LESCAIPTION NEC USE ONLY 11111111111111 NIA 5ê 65 32 Ways of secrets J. L. Wilson (804) 357-3184

ATTACHMENT 1 SURRY POWER STATION, UNIT 1 DOCKET NO: 50-280 REPORT NO: LER 81-042/03L-0 EVENT DATE: 09-02-81

RM-CC-105 OUT OF CALIBRATION

1. DESCRIPTION OF EVENT:

On September 2,1981, with the unit at 100% power, the control room operator noticed that the meter reading from the component cooling radiation monitor RM-CC-105, had exceeded the high alarm set point but the annunciator had not sounded nor had the component cooling surge tank vent closed. This event is contrary to Technical Specification 3.7.E and is reportable per Technical Specification 6.6.2.b(4).

2. FROBABLE CONSEQUENCES OF OCCURRENCE:

Effluent from the component cool ng surge tank went enters the process vent system where the activity levels are continuously monitored. Ther, was no noticeable increase in the activity levels of the process vent system during this event; therefore, the health and safety of the public were not affected.

3. CAUSE OF EVENT:

The log ratemeter card in the instrument drawer had failed. This resulted in the absence of the alarm and the corresponding automatic function (e.g. closing the component cooling surge vent).

4. IMMEDIATE CORRECTIVE ACTION:

The immediate corrective action was to isolate the component cooling surge tank vent.

5. SUBSEQUENT CORRECTIVE ACTION:

The failed log ratemeter card in the radiation monitor was replaced and the instrument was recalibrated. The alarm set point was adjusted to a value of less than or equal to two times background as per Tech. Spec. Table 3.7-5.

6. ACTIONS TAKEN TO PREVENT RECURRENCE:

As these monito are checked daily, per Tech. Spec. 4.1, and occupy a conspicuous location in the control room, no further action is deemed necessary.

7. GENERIC IMPLICATIONS:

None.