

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | A | L | J | M | F | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

REPORT SOURCE | L | 5 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 8 | 7 | 0 | 8 | 3 | 1 | 8 | 1 | 3 | 0 | 9 | 2 | 8 | 8 | 1 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 1040 on 8/31/81, the Instrumentation Loop associated with the refueling water storage tank level indication was declared inoperable when the level indicator (LI4075A) failed Low. Technical Specification 3.3.3.8 requires the Instrumentation Loop to be operable. Tech. Spec. 3.3.3.8 action statement requirements were met. Health/safety of the public was not affected.

SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP SUBCODE | VALVE SUBCODE

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

During switching of the Instrumentation Loop power supply, the instrumentation was momentarily de-energized and the indicator pointer stuck at the low position. The pointer was freed and retested several times without recurrence of the problem. The Instrumentation Loop was subsequently returned to service at 1520 on 8/31/81.

FACILITY STATUS | % POWER | OTHER STATUS | METHOD OF DISCOVERY | DISCOVERY DESCRIPTION

ACTIVITY CONTENT RELEASED | AMOUNT OF ACTIVITY | LOCATION OF RELEASE

PERSONNEL EXPOSURES NUMBER | TYPE | DESCRIPTION

PERSONNEL INJURIES NUMBER | DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY TYPE | DESCRIPTION

PUBLICITY ISSUED DESCRIPTION