

CONTROL BLOCK:

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | L | J | M | F | 1 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5

REPORT SOURCE

L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 4 | 8 | 7 | 0 | 8 | 3 | 0 | 8 | 1 | 3 | 0 | 9 | 2 | 8 | 8 | 1 | 7

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

012 | At 0320 on 8/30/81, the pressurizer pressure Instrumentation Channel to the Hot Shutdown Panel was declared inoperable due to the failure of the Pressure Indicator. Tech. Spec. 3.3.3.5, in part, requires the Instrumentation Channel to be operable. Tech. Spec. 3.3.3.5 action statement requirements were met. Health/safety of the public was not affected.

019 | SYSTEM CODE: I C 11; CAUSE CODE: E 12; CAUSE SUBCODE: E 13; COMPONENT CODE: I N S T R U 14; COMP SUBCODE: I 15; VALVE SUBCODE: Z 16; LER/RO REPORT NUMBER: 17; EVENT YEAR: 8 1; SEQUENTIAL REPORT NO.: 0 6 5; OCCURRENCE CODE: 0 3; REPORT TYPE: L; REVISION NO.: 0; ACTION TAKEN: A 18; FUTURE ACTION: Z 19; EFFECT ON PLANT: Z 20; SHUTDOWN METHOD: Z 21; HOURS: 0 0 0 0; ATTACHMENT SUBMITTED: N 23; NPD-4 FORM SUB.: N 24; PRIME COMP. SUPPLIER: N 25; COMPONENT MANUFACTURER: W 1 2 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

110 | An investigation revealed that the Pressure Indicator was functioning in a non-linear manner and thus was not indicating the correct pressure. The indicator was replaced and following calibration the Instrumentation Channel was returned to service at 2320 on 8/31/81.

115 | FACILITY STATUS: E 28; % POWER: 0 9 9 29; OTHER STATUS: NA 30; METHOD OF DISCOVERY: B 31; DISCOVERY DESCRIPTION: Surveillance Test 32; ACTIVITY RELEASED OF RELEASE: Z 33; AMOUNT OF ACTIVITY: NA 35; LOCATION OF RELEASE: NA 36; PERSONNEL EXPOSURES NUMBER: 0 0 0 37; TYPE: Z 38; DESCRIPTION: NA 39; PERSONNEL INJURIES NUMBER: 0 0 0 40; DESCRIPTION: NA 41; LOSS OF OR DAMAGE TO FACILITY TYPE: Z 42; DESCRIPTION: NA 43; PUBLICITY ISSUED: N 44; DESCRIPTION: NA 45; 8110070305 810928 PDR ADOCK 05000348 S PDR