

LER SUPPLEMENTAL INFORMATION

BERO 50- 259 / 81051 Technical Specification Involved 3.8.B.6, 3.8.B.8
Reported Under Technical Specification 6.7.2.b(2) *Date due NRC: 10/8/81
Date of Occurrence 9/8/81 Time of Occurrence 1105 Unit 1

Identification and Description of Occurrence:
Turbine building ventilation exhaust radiation monitor was declared inoperable, due to low flow.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.
Unit 2 at 66%.
Unit 3 at 98%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

A belt on the sample pump was loose causing a low flow condition.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action:

Turbine building roof exhaust fans were removed from service and vents closed. Continuous air monitor was repaired and returned to service. This is considered a random failure and no further recurrence control is required.

Failure Data: None

Retention: Period - Lifetime: Responsibility - Document Control Supervisor

*Revision: *All*