

LER No.: 50-366/1981-095
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366

Narrative Report
for LER 50-366/1981-095.

With the plant in hot shutdown, 2B21-N301E, H and K, Safety Relief Valve Position Secondary Indicator Pressure switches, were found to actuate at 26 psig, 14.4 psig and 25.6 psig respectively. Tech Specs Section 4.4.2, Item b, requires actuation at 20 +/-5 psig. Redundant secondary position indicator, 2B21-R614, was operable. Plant operation or the public's health and safety was not affected. This is a repetitive event as last reported on Reportable Occurrence Report No. 50-366/1979-009.

The cause of this event has been attributed to setpoint drift. The switches were recalibrated per HNP-2-5240, Static-O-Ring Pressure Switch Calibration, then functionally tested and returned to service.

Unit I uses the same type pressure switches for this application; however, a generic review revealed no inherent problems.