LICENSEE EVENT REPORT

| | CONTROL SLOCK: |
|-------|--|
| 0 1 | FILITIPIS 4 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58 |
| CON'T | SOURCE SO 61 DOCKET NUMBER 38 SP EVENT DATE 74 75 REPORT DATE 30 |
| 0 2 | While performing a routine surveillance test, the "A" Auxiliary |
| 0 3 | Feedwater (AFW) pump could not be properly tripped and was taken out of |
| 3 4 | service to be repaired. The "B" and "C" AFW pumps were operable. Unit 3 |
| 0 5 | was in cold shutdown condition. Full power operation of Unit 4 continued |
| 06 | pursuant to T.S. 3.8.1.b.1. This is reportable pursuant to T.S. 6.9.2.b.2. |
| 0 7 | The most recent occurrences relating to the AFW systems were reported as |
| 7 3 | LER'S 250-81-04 and 251-81-05. |
| 0 9 | SUBCODE SUBCOD |
| | 17 REPORT NUMBER 8 1 |
| 110 | TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED SORM SUB. SUPPLIER MANUFACTURER TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED SORM SUB. SUPPLIER MANUFACTURER MANUFACTURER TO SUBMITTED SUPPLIER MANUFACTURER TO SUBMITTED SUB |
| | a misaligned yoke on the emergency overspeed trip valve. The yoke was |
| 1 2 | realigned and the set screw was retightened. The pump was then tested and |
| 1 3 | returned to service within 20 hours. |
| 1 4 | 30 |
| 1 5 | STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32 |
| | ELEASED OF RELEASE NA LOCATION OF RELEASE 26 |
| 17 | PERSONNEL EXPOSURES PUMBER TYPE DESCRIPTION 39 NA |
| 7 3 | PERSONNEL INJURIES DESCRIPTION (1) |
| 7 3 | CSS OF CR DAMAGE TO FACILITY 43 |
| 7 3 | PUBLICITY SSUED DESCRIPTION 45 NAC USE ONLY NAC USE ONLY |
| 7 3 | 30 se |
| | NAME OF PREPARER P.L. PACE PHONE: (3UD) 332-3034 |