LICENSEE EVENT REPORT

EXHIBIT A

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 B	0 R T N P 1 2 0 0 - 0 0 0 0 0 0 4 1 1 1 1 1 1 5 5
O 1	SOURCE L 6 0 5 0 - 0 3 4 4 7 0 9 0 2 8 1 8 1 0 0 2 8 1 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 2	DURING NORMAL 100% POWER OPERATION, STS 3.7.6.1 WAS NOT MET WHEN PERFORM-
0 3	ANCE OF A PERIODIC OPERATING TEST REVEALED THAT THE CONTROL ROOM EMERGENCY J
0 4	[VENTILATION HUMIDISTAT PREHEAT COIL WOULD NOT ENERGIZE TO MAINTAIN CONTROL]
0 5	[ROOM HUMIDITY. THERE WAS NO EFFECT ON PLANT OR PUBLIC SAFETY SINCE THE
0 6	REDUNDANT TRAIN OF CONTROL ROOM EMERGENCY VENTILATION WAS OPERABLE.
0 7	
0 8 7 8	9 80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE NO.
	ACTION FUTURE EFFECT SHUTDOWN HOURS (22) SUBMITTED FORMSUB SUPPLIER MANUEACTURER
	A 8 Z 19 Z 20 Z 20 O O O Y 23 N 24 A 25 P 1 5 5 (
1101	THE CAUSE OF THE OCCURRENCE WAS FAILURE OF A DIAPHRAGM IN THE HUMIDISTAT
	PNEUMATIC DRIVE MECHANISM. THE DIAPHRAGM WAS REPLACED. THE PREHEAT COIL
لناسا	THE PERIOD HAD REFINEED, THE PRINTED OF
[3]	WAS TESTED FOR OPERABILITY AND THEN DETURNED TO CERUICE
	WAS TESTED FOR OPERABILITY, AND THEN RETURNED TO SERVICE.
112	WAS TESTED FOR OPERABILITY, AND THEN RETURNED TO SERVICE.
114	
114	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 SURVEILLANCE TEST
1 4 7 8 1 5 7 8 A	PACILITY STATUS SIRVEILLANCE TEST STATUS SURVEILLANCE TEST SURVEILLANCE TEST BO CLICATION OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 4 7 8 1 5 7 8 A	PERSONNEL EXPOSURES 9 OTHER STATUS OTHER
1 4 7 8 1 5 7 8 A	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 4 7 8 1 5 7 8 A	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 3
1 4 7 8 A A A A A A A A A A A A A A A A A A	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
1 4 7 8 7 8 ARI 1 6 7 8 1 7 7 8 1 8 1 8 7 8	Second S
1 4 2 8 7 8 A A A A A A A A A A A A A A A A A	Solution of release