| . CONTROL BLOCK: |
|--|
|] GA E I H 1 3000 - 10 00 00 0 - 10 00 34 12 11 11 1 0 57 CAT 56 0 |
| REPORT LE DO 5 0 0 0 3 2 1 7 0 9 1 14 8 1 8 1 10 1 14 18 11 9 |
| on 9-14-81, with Hatch 1 at steady state 99% thermal power following com |
| pletion of the "HPCI Pump Rated Flow" test it was discovered that an oil |
| leak developed on the oil system. This is reportable under Tech Spec |
| Section 6.1.9.1.b. As per Tech Spec 3.5.D.2, RCIC, ADS, CSS, LPCI were |
| operable and no significant event occurred. This is a repetitive occ- |
| urrance (Ref: 50-321/1981-088). There were no effects upon public |
| health and safety due to this event. |
| SYSTEU CAUSE SUBCODE S |
| The oil leak was due to a torn diaphragm on the HPCI Robt. Shaw control |
| valve resulting from a component defect in the valve. The valve was |
| replaced and a new diaphragm was installed. The system was proven oper- |
| able. The unit is now in full compliance with the requirements and no |
| further reporting is required. |
| SACILITY DISCOVERY DESCRIPTION 32 |
| ACTIVITY CONTENT RELEASED OF RELEASE NA LOCATION OF RELEASE 36 NA LOCATION OF RELEASE 36 |
| 7 O O O O O O O O O O O O O O O O O O O |
| NUMBER OF O O O O O O O O O O O O O O O O O O |
| TYPE DESCRIPTION NA |
| NAC USE ONLY NAC USE ONLY NAC USE ONLY |
| NAME OF PHEOROGEN C. L. Coggin - Supt. Plt. Eng. Serv. PHONE 912-367-7851 |
| Compartment of the second |