
PMBILER



This report is submitted in accordance with the requirements of Appendix A to Operating License DPR-49, Specification 6.11.3.

## Problem:

· \*

On September 14, 1981, during an annual surveillance test, diesel fire pump 1P-49 did not develop the required flow rate or discharge pressure. Technical Specification 4.13.B.1.e requires this pump to deliver at least 3100 gpm at a discharge pressure of 112 PSIG. The pump instrumentation indicated the pump was delivering 2000 gpm at 100 PSIG. Electric fire pump 1P-48 was demonstrated operable immediately and daily thereafter, while 1P-49 was out of service, to satisfy Technical Specification 4.13.B.2. 1P-49 was disassembled and the bowl assembly was replaced. Following reassembly, the pump was again tested but still would not meet the head and flow requirements.

## Cause:

Investigation revealed the cause of the low flow and discharge pressure from 1P-49 was a broken tensioning rod in the pumps minimum flow valve, PSV-3300. This was allowing a significant portion of the water being delivered by the pump to be diverted from the fire system back to the circulating water system pit.

## Corrective Action:

8110230353 811014 PDR ADGCK 05000331

The tensioning rod in PSV-3300 was replaced and the diesel fire pump was satisfactorily tested and returned to service on September 25, 1981. No further corrective action is planned at this time.

IE22

OCT 1 6 1981

Mr. James G. Keppler October 14, 1981 Page 2

This report has been reviewed by the DAES Operations Committee.

Very truly yours,

york for

Daniel K. Mineck Chief Engineer Duane Arnold Energy Center

DLM/JVS/p1

Docket No. 50-0331

cc: L. Root D. McGaughy B. York J. Vinquist R. Anderson NRC Resident Office