

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0790-7170 04040000

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81048 Technical Specification Involved Table 3.1.A

Reported Under Technical Specification 6.7.2.b.2 *Date due NRC: 10/21/81

Date of Occurrence 9/21/81 Time of Occurrence 2350 Unit 2

Identification and Description of Occurrence:

Flow totalizer FQ-68-5 drifted high, causing erroneous flow indication to APRM channels A, C, and E.

Conditions Prior to Occurrence:

Unit 1 in refueling outage.

Unit 2 at 99%.

Unit 3 at 98%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

The General Electric model 563 flow totalizer failed electronically.

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action: Operations initiated a half scram in trip channel A, the totalizer was replaced and successfully tested, and the system was returned to service. This is considered a random failure and no further recurrence control is required. Trip channel was operable.

Failure Data: BFRO-50-260/81029.

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: All