

## Public Service Company of Colorado

August 15, 1981 Fort St. Vrain Unit No. 1 P-81230

Mr. Karl V. Seyfrit, Director Nuclear Regulatory Commission Region IV Office of Inspection and Enforcement 611 Ryan Plaza Drive Suite 1000 Arlington, Texas 76012



Reference: Facility Operating License

No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/81-053, Final, submitted per the requirements of Technical Specification AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/81-053.

Very truly yours,


Don Warembourg

Manager, Nuclear Production

DW/cls

Enclosure

cc: Director, MIPC



81110204015

IEZZ sili

REPORT DATE: So, dember 15, 1981

REPORTABLE OCCURRENCE 81-053

ISSUE 0 Page 1 of 2

OCCURRENCE DATE: August 16, 1981

FORT ST. VRAIN NUCLEAR GENERATING STATION PUBLIC SERVICE COMPANY OF COLORADO 16805 WELD COUNTY ROAD 19 1/2 PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/81-053/03-L-0

Final

IDENTIFICATION OF OCCURRENCE:

During normal plant operation, 1B diesel generator day tank, T-9203X, was found to contain less than 325 gallons. This is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2 as a degraded mode of LCO 4.6.1.

## FVENT DESCRIPTION:

While operating at 70% thermal power and 235 MW electrical power, an operator, during a routine check, noted that the 1B emergency diesel generator day tank level was about 315 gallons, which is less than the 325 gallons required by LCO 4.6.1. The operator rapped the level control switch, which automatically starts the fuel oil transfer pump on low tank level, and the pump started and brought the day tank level to 350 gallons. The problem was reported, and instrument personnel checked the level control circuit.

CAUSE DESCRIPTION:

The level control switch had dirt on contacts and linkage.

CORRECTIVE ACTION:

The level control switch contacts and linkage were cleaned.

The level control switch contacts and linkage for the day tank on 1A diesel generator (T-9202X) was also examined and cleaned to ensure proper operation of T-9202X.

No further corrective action is anticipated or required.

rrepared By:

Technical Services Technician

Reviewed By:

Milt McBude

Technical Services Manager

Reviewed By:

Edwin D. Hill Station Manager

Approved By:

Don Warembourg
Manager, Nuclear Production