(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	G A E I H 2 2 0 0 1 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 67 CAT 58
O 1 8	REPORT L 6 0 5 0 0 0 3 6 6 7 0 3 1 1 8 1 8 0 4 0 7 8 1 9 SOURCE 60 61 DOCKET NUMBER 88 69 EVENT DATE 74 75 REPORT DATE 80
0 2	With the reactor in cold shutdown, while performing HNP-2-3102, Reactor
03	High Pressure (Shutdown Cooling Mode) Functional Test and Calibration,
0 4	reactor pressure switch, 2B21-N018B, was found to actuate at 164 psig, inc.
[0]5]	Tech Specs Table 3.3.2-2, Item 6, requires actuation at ≤135 psig +25
06	psig head correction. Redundant switch 2B21-N018A was operable and
0 7	actuated within tolerance. Plant operation or the public's health and
08	safety were not affected. This is a non-repetitive event.
7 8	SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE SUBCODE
0 9	C F (1) E (12) E (13) I M S T R U (14) S (15) (16) 9 10 11 12 12 13 13 OCCURRENCE REPORT REVISION
	17 REPORT NUMBER 8 1
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER SUPPLI
1 0	The cause of this event has been attributed to setpoint drift. The switch
	was recalibrated per HNP-2-5279, Barksdale Pressure Switch Calibration,
1 2	and functionally tested successfully per HNP-2-3102, Reactor High Pressure
[1]3	(Shutdown Cooling Mode) Functional Test and Calibration.
1 4	80
	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 G 28 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
7 6 7 8	AMOUNT OF ACTIVITY TO NA LOCATION OF RELEASE 36 NA LOCATION OF RELEASE 36 NA PERSONNE EXPOSURES
1 7	1 0 0 0 37 Z 38 NA
7 8	9 11 12 13 PERSONNEL INJURIES NUMBER DESCRIPTION 41
1 8	0 0 0 40 NA
	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
7 8	8111050406 810407 8DP ADDCK 05000366
2 0	N 44 DESCRIPTION 45 S PDR NA
7 8	NAME OF PREPARER R. T. Nix, Supt. of Maint. PHONE 912-367-7781

LER No.: 50-366
Licensee: Georgia Power Company
Facility: Edwin I. Hatch
Docket No.: 50-366/1981

Narrative Report
for LER 50-366/1981-020.

On March 11, 1981, with the reactor in cold shutdown and while performing
HNP-2-3102, Reactor High Pressure (Shutdown Cooling Mode) Functional Test
and Calibration, reactor pressure switch 2B21-N019B was found to actuate
at 164 psig increasing pressure. Tech Specs Table 3.3.2-2, Item 6.b,
requires switch actuation at less than or equal to 135 psig +25 psig
head correction. The redundant switch 2B21-N018A was found to be operable
and actuating within expected tolerance. Plant operation nor public
health and safety were affected. This is a non-repetitive event.

The cause of this event has been attributed to setpoint drift. The switch

The cause of this event has been attributed to setpoint drift. The switch was recalibrated per HNP-2-5279, Barksdale Pressure Switch Calibration, then functionally tested successfully per HNP-2-3102, Reactor High Pressure (Shutdown Cooling Mode) Functional Test and Calibration, and returned to service.

A generic review revealed no inherent problems with this switch for this particular application. Unit I does not use this type of switch for this application, but these type switches are used on both units for safety related functions and have a previous history for setpoint drift.