

LICENSEE EVENT REPORT

CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

V A S I P S 1 0 0 - 0 0 0 0 0 0 - 0 0 4 1 1 1 1 1 4 5
LICENSEE CODE 14 LICENSE NUMBER 25 LICENSE TYPE 30 CAT 58

REPORT SOURCE L 6 0 5 0 0 0 2 8 0 1 0 0 5 8 1 8 1 0 3 0 8 1 9
DOCKET NUMBER 56 EVENT DATE 74 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
313 With the reactor coolant at approximately 200°F, and heating up, TV-CC-109A
314 (Component Cooling to RHR isolation valve would not close. The trip valve was
315 isolated by closing the downstream manual isolation valve. Since the integrity of
316 the component cooling water piping inside of the containment was maintained, an
317 isolation barrier between inside containment and the environment was maintained.
318 Therefore, the health and safety of the general public were not affected. This
319 event is contrary to T.S.3.8.A.1 and reportable per T.S.6.6.2.b(2).

SYSTEM CODE W B 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V O P 14 COM' SUBCODE D 15 VALVE SUBCODE Z 16
LER/RO REPORT NUMBER 17 EVENT YEAR 8 1 21 SEQUENTIAL REPORT NO. 0 1 5 1 9 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32
ACTION TAKEN X 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NPD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER F 1 3 1 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
310 A mechanical cause for this valve failing to close could not be determined. Operating
311 air was disconnected from the top of the diaphragm operator and the air line observed
312 to blow clear. The air line was reconnected and the pneumatic operator was found to
313 operate correctly. The valve was cycled several times satisfactorily and was
314 returned to service.

FACILITY STATUS G 28 % POWER 0 0 0 0 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operational Event 32
ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
PUBLICITY ISSUED N 44 DESCRIPTION N/A 45

8111050630 811030
PDR ADOCK 05000280
PDR

ATTACHMENT 1
SURRY POWER STATION, UNIT 1
LOCKET NO: 50-281
REPORT NO: 81-059/03L-0
EVENT DATE: 10-05-81

TITLE OF THE EVENT: TV-CC-109A WOULD NOT CLOSE

1. DESCRIPTION OF THE EVENT:

With the reactor coolant at approximately 200⁰F, and heating up, TV-CC-109A (Component cooling isolation valve to residual heat removal) would not close. The valve was manually isolated by closing the downstream manual isolation valve. This event is contrary to T.S.3.8.A.1 and reportable per T.S.6.6.2.b(2).

2. PROBABLE CONSEQUENCES:

The Design Bases for the containment isolation system is that during accident conditions, at least two barriers exist between the atmosphere outside the containment structure and the atmosphere inside the containment. Failure of one valve or barrier will not prevent isolation of the containment.

Component cooling water piping is separated from the reactor coolant system, or a connecting system, and the containment atmosphere, by a closed valve under administrative control and a membrane barrier.

Since the integrity of the membrane barrier, the component cooling water piping inside containment, was maintained, an isolation barrier between the inside of the containment structure and the environment was maintained during this event. Therefore, the health and safety of the public were not affected.

3. CAUSE:

The valve malfunction could not be attributed to any mechanical problem. The valve operated satisfactorily following the disconnector and reconnection of its air line.

4. IMMEDIATE CORRECTIVE ACTION:

The immediate corrective action was to manually isolate the valve and station an operator at the valve for Administrative control.

5. SUBSEQUENT CORRECTIVE ACTION:

Maintenance department verified the air supply to the valve and verified the pneumatic operator functioning correctly. The valve was cycled several times satisfactorily and returned to service.

6. ACTION TAKEN TO PREVENT RECURRENCE:

Since the valve cycled satisfactorily, no additional action is deemed necessary.

7. GENERIC IMPLICATION:

None.