LER NO.: 50-321/1981-110 LICENSEE: Georgia Power Company PACILITY: Edwin I. Hatch DOCKET NO.: 50-321

January and the Company of the Compa

NARRATIVE REPORT

Por LER 50-321/1981-110

October 2. 1981, with the reactor in Hot Standby, 1011-P001 instack Monitor was found inoperative. Environmental Technical ecifications Section 2.1.4.b requires continuous monitoring of seous releases for gross radioactivity. there was neither flow nor ltap on the panel. The sample pump B was not running, redundent mp A was put in service, and the system was returned to its normal eration within half an hour. This event did not affect the normal eration of the plant and also had no effect on safety and health of e public. This is a repetetive event as was last reported on -366/1980-331.

e reason the pump B was inoperative was due to corrosion of carbon nes. The pump was disassembled, the vane cleaned, and reinstalled the pump, and the pump was found to be performing satisfactorily.

ese type pumps (carbon vane) are installed in the reactor building nt radiation monitors for both Units 1 and 2 and have experienced milar operating problems. A study will be undertaken to determine at action can be taken to minimize future occurrences of this at action can be taken to minimize future occurrences of this pe. A followup report will be submitted when the study is complete.

8111050705 811029 PDR ADDCK 05000321 S PDR

] Z B O O Q Q N/A B B 3	SURVEILLANCE
ACTIVITY CONTENT 17 13 ACTIVITY CONTENT 17 13 RELEASED OF RELEASE AUGUNT OF ACTIVITY (35) Z (33) Z (34) N/A	LOCATION OF RELEASE (36)
PERSONNEL EXPOSERIES OFSCRIFTION (19)	
PEASONALL INJURIES NUMBER DESCRIPTION (41) 1 10 10 10 (40) N/A	
LOSS OF OR DENAGE TO FACILITY (3) 1 Z (42) N/A	
PORTION CO	NRC USE ONLY
NAME OF PHEDAMER W.H. Rogers Health Physics	PHONE 912-367-7851