

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: F L C R P 3
 LICENSE NUMBER: 00000000-000
 LICENSE TYPE: 41111
 CAT 58: 4
 REPORT SOURCE: L
 DOCKET NUMBER: 950-0302
 EVENT DATE: 100781
 REPORT DATE: 110481

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

At 0845, while performing SP-132, Engineered Safeguards Channel Calibration, it was determined that ESFAS RC pressure transmitter RC-3A-PT3 was discovered to be out of tolerance. This event was not attributed to a specific activity as required by Reg. Guide 1.16 and, therefore, is reportable as being contrary to T.S. 3.3.2.1. There was no effect upon the health or safety of the general public. This was the first occurrence of this type, and this is the twenty-first event reported under this Specification.

SYSTEM CODE: S F
 CAUSE CODE: X
 CAUSE SUBCODE: Z
 COMPONENT CODE: I N S T R U
 COMP. SUBCODE: T
 VALVE SUBCODE: Z

LER/RO REPORT NUMBER: 17
 EVENT YEAR: 81
 SEQUENTIAL REPORT NO.: 064
 OCCURRENCE CODE: 03
 REPORT TYPE: L
 REVISION NO.: 0

ACTION TAKEN: E
 FUTURE ACTION: Z
 EFFECT ON PLANT: Z
 SHUTDOWN METHOD: Z
 HOURS: 0000
 ATTACHMENT SUBMITTED: Y
 NPRD-4 FORM SUB.: N
 PRIME COMP. SUPPLIER: A
 COMPONENT MANUFACTURER: F180

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause of this event is attributed to instrument drift. The instrument was recalibrated, and the functional test was satisfactory. No further corrective action is deemed necessary.

FACILITY STATUS: G
 % POWER: 000
 OTHER STATUS: NA
 METHOD OF DISCOVERY: B
 DISCOVERY DESCRIPTION: Technician observation

ACTIVITY CONTENT RELEASED OF RELEASE: Z
 AMOUNT OF ACTIVITY: NA
 LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES NUMBER: 000
 TYPE: Z
 DESCRIPTION: NA

PERSONNEL INJURIES NUMBER: 000
 DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY TYPE: Z
 DESCRIPTION: NA

PUBLICITY ISSUED: N

NAME OF PREPARER: Victor A. Hernandez
 PDR ADOCK 05000302
 S PDR
 NRC USE ONLY
 904/795-6486
 PHONE: _____

SUPPLEMENTARY INFORMATION

Report No.: 50-302/81-064/03L-0

Facility: Crystal River Unit 3

Report Date: November 04, 1981

Occurrence Date: October 7, 1981

Identification of Occurrence:

A channel of the Engineered Safety Feature Actuation System was discovered to be inoperable during shutdown surveillance activities. This event was not attributed to a specific shutdown activity as required by Regulatory Guide 1.16, and therefore, is reportable as being contrary to Technical Specification 3.3.2.1.

Condition Prior to Occurrence:

Mode V cold shutdown (0%).

Description of Occurrence:

At 0845 while performing SP-132, Engineered Safeguards Channel Calibration, Reactor Coolant Pressure Transmitter RC-3A-PT3 was found out-of-tolerance.

Designation of Apparent Cause:

The cause of this event is attributed to instrument drift.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

The instrument was recalibrated, and the functional test was satisfactory. No further corrective action is deemed necessary at this time.

Failure Data:

This was the first occurrence of this type, and this is the twenty-first event reported under this Specification.

/rc