

LER NO. 81-71/3L
DOCKET NO. 50-317
LICENSE NO. DPR-53
EVENT DATE 10-05-81
REPORT DATE 11-04-81
ATTACHMENT

044 20
2001077

04-08-81 9 3011 10*

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Electronic failure of Control Element (CEA) #57 Individual Control Module (ICM) (Electro-Mechanics #23210) such that a continuous CEA insertion signal was generated caused the event. Initially, with the Control Element Drive System (CEDS) Control Panel power switch in the "off" position malfunction of the ICM caused no CEA movement.

The plant computer, however, responded to the false insertion signal and all Primary CEA Position Indication alarms for Group One and CEA deviations and Power Dependent Insertion Limits were actuated in proper sequence. Upon receipt of the Primary indication alarms, operators verified that no Secondary (originated by Reed Switch Position Transmitter) CEA Position Indication System alarms had occurred, and concluded that the plant computer CEA Position circuitry was at fault. Attempting to regain normal indications, the CEDS Control Panel was energized in Manual Group control mode. CEA #57 immediately began to move in, as indicated by the Secondary Position Indication System. This system initiated a CEA Motion Inhibit signal to stop the CEA motion at the appropriate CEA height. At this time, aware of the CEA channel at fault, operators selected CEA #57 for Primary System Group One indication. The computer indicated a false CEA #57 height of 70 inches. Operators then attempted, in Manual Individual control mode, to drive CEA #57 back out. CEA #57 continued its inward motion as soon as the CEA Motion Inhibit was bypassed for this purpose. CEA #57 inserted to 117 inches, by Secondary CEA Position Indication. Movement of the CEA had begun from its fully withdrawn height of 134 inches.

The CEDS Control Panel was deenergized until CEA #57 ICM was replaced with a spare. The malfunctioning module will be sent to its supplier for analysis and repair. Pending analysis by the supplier, no preventive action is planned.

A copy of this report will be routed to licensed operators for information.