

LICENSEE EVENT REPORT

CONTROL BLOCK _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | ALBRF2 | 00-000000-000 | 41111 | 5

01 | L | 05000260 | 7100781 | 8110481 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | During normal operation, containment atmosphere hydrogen analyzer was removed from
03 | service for maintenance because return sample pump was cycling. 2-H₂M-76-104 was
04 | declared inoperable. (T.S. 3.7.H.2) There was no danger to the health or safety
05 | of the public. Redundant systems were available and operable. Previous similar
06 | event: BFR0-50-260/81050.
07 |
08 |

09 | S | A | E | X | I | N | S | T | R | U | E | Z | 8 | 1 | 0 | 5 | 2 | 0 | 3 | L | 0 | E | X | Z | 0 | 0 | 0 | 0 | Y | N | L | X | 9 | 9 | 9 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | Motor for B hydrogen analyzer sample return pump thermal overloads tripped. (Reference
11 | BFR0-50-260/81054) A gas calibration of the Hayes-Republic model 643 hydrogen
12 | analyzer was performed per SI 4.7.H and the analyzer was returned to service. This
13 | and other failures are under investigation on BFR0-50-259/81062. Estimated date of
14 | completion 12/15/81.

15 | E | 1 | 0 | 0 | NA | B | Maintenance
16 | Z | Z | NA | NA
17 | 0 | 0 | 0 | Z | NA
18 | 0 | 0 | 0 | NA
19 | Z | NA
20 | N | NA

LER SUPPLEMENTAL INFORMATION

BFRO-50- 260 / 81052 Technical Specification Involved 3.7.H.2

Reported Under Technical Specification 6.7.2.b(2)*Date due NRC: 11/6/81

Date of Occurrence 10/7/81 Time of Occurrence 0315 Unit 2

Identification and Description of Occurrence:

The containment atmosphere hydrogen analyzer was removed from service for maintenance because return sample pump was cycling.

Conditions Prior to Occurrence:

Unit 1 at 50%.

Unit 2 at 100%.

Unit 3 at 92%.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

None

Apparent Cause of Occurrence:

Motor for B hydrogen analyzer sample return pump thermal overloads tripped. (Reference BFRO-50-260/81054).

Analysis of Occurrence:

There was no danger to the health or safety of the public, no release of activity, no damage to the plant or equipment, and no resulting significant chain of events.

Corrective Action: A gas calibration of the Hayes-Republic model 643 hydrogen analyzer was performed per SI 4.7.H and the analyzer was returned to service. This and other failures are under investigation on BFRO-50-259/81062. Estimated date of completion 12/15/81.

Failure Data: BFRO-50-260/81050.

*Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: