LICENSEE EVENT REPORT

	CONTROL BLOCK:
0 1	F L S L S 1 2 0 0 - 0 0 0 0 - 0 0
CON'T	SOURCE IL 6 10 15 10 10 10 13 13 15 011 10 11 0 8 1 1 3 11 1 0 9 8 1 9 EVENT DATE SO EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	While shutdown for refueling, maintenance and vendor recommended
0 3	modifications were performed on "A" Diesel Generator. During a
0.14	retest run the engine turbocharger failed. The "A" D.G. was
0 5	repaired and retested satisfactorily. During this event the
0 [6]	"B" D.G. was fully operable and the health and safety of the
0.7	public was not affected. See LER #77-2, 77-42, and 79-21 for
0 3	previous turbocharger failures.
0 9	SYSTEM CAUSE CODE SUSCODE COMPONENT CODE SUSCODE SUSCO
	17 REPORT VENT YEAR REPORT NO. CODE TYPE NO.
1 0	An exact cause for the Turbocharger failure could not be determined
Ш	bowever, in the week prior to failure there were approximately
[12]	sixty engine starts and a great deal of light load operation
13	associated with maintenance and modification retesting.
1 5 7 8	STATUS SPOWER OTHER STATUS OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRI
1 6 1 8	Z 33 Z 34 NA NA NA NA NA NA NA NA NA
17	O O O O Z 39 NA
T I	PERSONNEL INJURIES NUMBER DESCRIPTION (4) NA
7 3	2 11 12 LCSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION
1 9	Z 3 NA
2 0	SSUED DESCRIPTION 45 NA
1 8	P T Page (305) 552-3654
	NAME OF PREPARER 1. I. PACE PHONE (505) 552-5054