(7.771 LICENSEE EVENT REPORT CONTROL BLOCK: \Box (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) L C R P 3 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 L 6 05 0 - 0 3 0 2 7 2 0 2 7 8 1 8 1 1 1 1 0 8 1 9 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 REPORT EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [At 1030 during routine refueling operations, notification was received from the 0 2 Architect Engineer that the main steam lines supplying the turbine driven emergency 0 3 Ifeed pump are presently categorized as High Energy Lines, but were not considered 0 4 in the 1973 FPC High Energy Line Break Outside the Containment (Helboc) Report. 0 5 This requires reporting per T.S. 6.9.1.8.i. There was no effect upon the health or 0 6 safety of the general public. This was the first event of this type. 07 SYSTEM CAUSE CAUSE COMP CODE CODE SUBCODE COMPONENT CODE SUBCODE (13 X (14 REVISION SEQUENTIAL REPORT NO. OCCURRENCE REPORT EVENT YEAR CODE LEP RO TYPE NO. REPORT 016 011 T 0 NUMBER COMPONENT MET VO FUTURE EFFECT ON PLANT SUBMITTED PRIME COMP. (22) HOURS FORM SUS MANUFACTURER SUPFLIER F (19 0 0 0 9 Y (23) (25 9 N (24) Z (21) 9 (18) A CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) This event was caused by changes in operational procedures not specifically considered 1 0 by the A/E in the Helboc Report. The creation of High Energy Lines, therefore, falls 1 1 1 outside the bounds of the analysis. Evaluation of the lines is in progress. Following 2 completion of the evaluation and procurement of material, modification (MAR 81-10-19) 3 will be completed during the first available outage of sufficient duration. 1 4 80 METHOD OF DISCOVERY FAC.LITY STATUS OTHER STATUS (30) DISCOVERY DESCRIPTION (32) % POWER D (31) Notification from A/E 5 H (28) 01 0 0 (29 80 9 10 ACTIVITY CONTENT LOCATION OF REL ASE (36) AMOUNT OF ACTIVITY (35 RELEASED_OF RELEASE Z (33) NA Z (34) NA 6 10 45 80 11 4.4 PERSONNEL EXPOSURES DESC IPTION (35 NUMBER 0 | 2(38) 80 PERSONNEL INJURIES DESCRIPTION (41) UMBER NA 01 010 8 80 LOSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION TYPE NA Z (42) 8111200743 PDR ADOCK (80 811110 PUBLICITY NRC USE ONLY DESCRIPTION (45) NED (44) PDR 11111 0 68 69 80 Victor 904/795-6486 NAME OF PREPARER PHONE ATTACHED SUPPI FMENTARY INFORMATION SHEET) (CEF

SUPPLEMENTARY INFORMATION

Report No.:	50-302/81-068/01T-0
Facility:	Crystal River Unit 3
Report Date:	November 10, 1981
Occurrence Date:	October 27, 1981

Identification of Occurrence:

Corrective measures are required to prevent operation in a manner less conservative than that assumed in the Accident Analysis in the Final Safety Analysic Report for a High Energy Line Break Outside Containment, as described in Technical Specification 6.9.1.8.1.

Conditions Prior to Occurrence:

Mode 6 refueling (0%).

Description of Occurrence:

At 1030, during routine refueling operations, notification was received from the Architect Engineer, Gilbert Associates, Inc., that the main steam lines supplying the turbine driven emergency feed pump are presently categorized as High Energy Lines, but that they were not considered as such when the FPC High Energy Line Break Outside Containment (Helboc) Report was done in 1973.

Designation of Apparent Cause:

This event was caused by changes in operational procedures not specifically considered by the Architectural Engineer in the Helboc Report. High Energy Lines were created, and, therefore fell outside the bounds of this analysis.

Analysis of Occurrence:

There was no effect upon the health or safety of the general public.

Corrective Action:

Evaluation of the lines is in progress. Following completion of the evaluation, and procurement of material, modification (MAR 81-10-19) will be completed during the first available outage of sufficient duration.

Failure Data:

This was the first event of this type.