

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 14 15 25 26 30 57 58 59
 [0][1] [M][D][C][C][N][1] [2] [0][0]-[0][0][0][0][0][0]-[0][0] [3] [4][1][1][1][1] [4] [5]

CON'T
 7 8 60 61 68 69 74 75 80
 [0][1] [L] [6] [0][5][0][0][0][3][1][7] [7] [1][0][1][0][8][1] [8] [1][1][0][9][8][1] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0][2] | At 2035, testing of the No. 1 Main Turbine Control Valve (MTCV) was |

[0][3] | performed while Turbine Control was on load limit. This resulted in |

[0][4] | a lower steam flow to the Main Turbine which caused a Reactor Coolant |

[0][5] | System (RCS) temperature swing and pressurizer (PZR) level exceeded |

[0][6] | the programmed band by >± 5% (T.S. 3.4.4). Pressurizer level returned |

[0][7] | to normal at 2040. No similar events have occurred. |

[0][8] | _____ |

7 8 9 11 12 13 18 19 20 21 22 23 24 26 27 28 29 30 31 32 33 34 35 36 37 40 41 42 43 44 47

SYSTEM CODE: [C][B] (11) CAUSE CODE: [A] (12) CAUSE SUBCODE: [A] (13) COMPONENT CODE: [Z][Z][Z][Z][Z][Z] (14) COMP. SUBCODE: [Z] (15) VALVE SUBCODE: [Z] (16)

LER/RO REPORT NUMBER: (17) [8][1] EVENT YEAR: [8][1] SEQUENTIAL REPORT NO.: [0][7][5] OCCURRENCE CODE: [0][3] REPORT TYPE: [L] REVISION NO.: [0]

ACTION TAKEN: [H] (18) FUTURE ACTION: [Z] (19) EFFECT ON PLANT: [Z] (20) SHUTDOWN METHOD: [Z] (21) HOURS: [0][0][0][0] (22) ATTACHMENT SUBMITTED: [Y] (23) NPRD-4 FORM SUB.: [N] (24) PRIME COMP. SUPPLIER: [Z] (25) COMPONENT MANUFACTURER: [Z][9][9][9] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1][0] | When testing of a MTCV is performed while turbine control is on load |

[1][1] | limit, steam flow to the main turbine is reduced, resulting in an |

[1][2] | increase in RCS temperature which causes pressurizer level to exceed |

[1][3] | the programmed band by >± 5%. Appropriate procedure changes have |

[1][4] | been implemented to prevent reoccurrence of this event. |

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS: [F] (28) % POWER: [0][8][5] (29) OTHER STATUS: NA (30) METHOD OF DISCOVERY: [A] (31) DISCOVERY DESCRIPTION: NA (32)

ACTIVITY RELEASED OF RELEASE: [Z] (33) [Z] (34) AMOUNT OF ACTIVITY: NA (35) LOCATION OF RELEASE: NA (36)

PERSONNEL EXPOSURES NUMBER: [0][0][0] (37) TYPE: [Z] (38) DESCRIPTION: NA (39)

PERSONNEL INJURIES NUMBER: [0][0][0] (40) DESCRIPTION: NA (41)

LOSS OF OR DAMAGE TO FACILITY TYPE: [Z] (42) DESCRIPTION: NA (43)

PUBLICITY ISSUED DESCRIPTION: [N] (44) NA (45)

8111250395 811109
 PDR ADOCK 05000317
 S PDR

NRC USE ONLY

LER NO. 81-75/3L
DOCKET NO. 50-317
LICENSE NO. DPR-53
EVENT DATE 10-10-81
REPORT DATE 11-09-81
ATTACHMENT

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (CONT'D)

Normally, testing of the Main Turbine Control Valves (MTCV'S) is performed while turbine control is in the load set position, which regulates the amount of steam flow to the Main Turbine. This test of the No. 1 MTCV was performed in the load limit position, MTCV'S are in a set position and when one valve closes, steam flow is reduced resulting in an increase of RCS temperature and pressurizer level swings of greater than +/- 5% from the programmed band. Appropriate procedure changes have been implemented to prevent reoccurrence of this event.

RECEIVED
NOV 13 1981
NRC