LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C O F S V 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 2 0 4 57 CAT 58 5
0 1 7 8	SOURCE L 6 0 5 0 0 0 2 6 7 7 1 0 1 7 8 1 8 1 1 1 1 6 8 1 9
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal plant operation, the hot reheat header activity monitors were temporar-
0 3	ily removed from service to allow radiography to be completed. This is a degraded
0 4	mode of LCO 4.4.1 and is reportable per Fort St. Vrain Technical Specification
0 5	AC 7.5.2(b)2. No effect on public health or safety. No related reports and no ac-
06	companying occurrences.
0 7	
08	9 80
0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 1 1 25 42 43 45 44 47 47
110	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Excessive feedwater leakage in #5 feedwater heater required blocking the heater.
	Quality Assurance program required radiography to verify the welds. The reheat
1 2	monitors were temporarily removed from service to prevent unnecessary loop shutdown.
1 3	The monitors were returned to service following each exposure.
1 4	80
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 4 1 29 N/A A 31 Personnel Observation
1 6	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 N/A N/A LOCATION OF RELEASE 36
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) 0 0 0 37 Z 38 N/A
7 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION 41)
7 8	0 0 0 0 N/A 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	Z (42) N/A
2 0	PUBLICITY 45 PDR ADOCK 05000267 NRC USE ONLY ISSUED DESCRIPTION 45 PDR PDR
7 8	9 10 NAME OF PREPARED Charles tulls PHONE: (303) 785-2224