



LER ATTACHMENT - RO #2-81-120

Facility: BSEP Unit No. 2

Event Date: 11/2/81

This event occurred as a result of moisture intrusion into the instrument housing internals of ADS initiation logic "A" permissive pressure switch, 2-E11-PS-N016D. An inspection of the electrical conduit, fittings and terminal box associated with the instrument revealed that a lack of watertight integrity had allowed moisture to complete the electrical circuit between the contacts of the switch causing the annunciation.

As a result of IE Bulletin 79-01B, plant maintenance practices have been revised to ensure proper instrumentation sealing integrity following preventive or corrective maintenance to plant equipment. Also, a task force has been assigned to assure that all equipment is inspected to ensure a proper environmental seal. It is felt that this will help in the prevention of future similar events.