

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|---|---|---------------|----|-----|----------------|----|----|--------------|----|----|----|----|----|----|----|----|----|----|----|----|----|----|---|
| 0 1 | N | J | S | G | S 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5 | 5 |
| 7 | 8 | 9 | LICENSEE CODE | 14 | 15 | LICENSE NUMBER | 25 | 26 | LICENSE TYPE | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | |

CONT

| | | | | | | | | | | | | | | | | | | | | | | | | | | |
|-----|---------------|---|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|----|---|
| 0 1 | REPORT SOURCE | 1 | 6 | 0 | 5 | 0 | 0 | 0 | 2 | 7 | 2 | 7 | 1 | 0 | 2 | 5 | 8 | 1 | 8 | 1 | 1 | 1 | 8 | 8 | 1 | 5 |
| 7 | 8 | 9 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

At 1710 hours, October 25, 1981, the Control Operator noticed that the Intermediate Range Detector N-36 had failed. The level trip switch for this channel was placed in the bypass position, and Action Statement 3.3.1.3.c was entered.

C 6

C 7

C 8

C 9

| | SYSTEM CODE | CAUSE CODE | CAUSE SUBCODE | COMPONENT CODE | COMP SUBCODE | VALVE SUBCODE | REV'D BY |
|-----|----------------------|------------|----------------------|-----------------|--------------------|---------------|----------|
| 0 9 | I A 11 | E 12 | G 13 | I N S T R U 14 | P 15 | Z 16 | |
| 7 | 9 10 | 11 | 12 | 13 | 15 | 16 | |
| 17 | LER RC REPORT NUMBER | EVENT YEAR | SEQUENTIAL REPORT NO | OCCURRENCE CODE | REPORT TYPE | | |
| 21 | 8 1 | 22 | 1 0 3 | 0 1 3 | L | | |
| 33 | A 18 | Z 19 | Z 20 | 0 0 0 0 | Y 23 | | |
| 34 | 35 | 36 | 37 | 40 | 41 | 42 | 43 |
| 38 | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD4 FORM SUB | PRIME COFF SUPPLIE | L 25 | W 1 2 0 |
| 40 | 39 | 41 | 42 | 43 | 44 | 45 | 46 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (21)

The cause was a failure of the detector high voltage power supply. The power supply was replaced and tested satisfactorily, and at 2115 hours, October 27, 1981, Action Statement 3.3.1.3.c was terminated.

C 13

C 14

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 E 28 0 9 8 29 N/A A 31 Operator Observation

ACTIVITY CONTENT RELEASED. OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 2 33 Z 34 N/A N/A

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (38)

1 7 0 0 0 37 Z 38 N/A

PERSONNEL INJURIES NUMBER DESCRIPTION (41)

1 8 0 0 0 45 N/A

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)

1 9 2 42 N/A

PUBLICITY ISSUED DESCRIPTION (45)

2 0 N 44 N/A

8112010490 811118
PDR ADDOCK 05000272
S PDR

NRC USE ONLY

68 69 80 81

NAME OF PREPARER Ken Whitcomb

PHONE 609-935-0998