LICENSEE EVENT REPORT

| | JON THOU BLOCK |
|---------|--|
| 1011 | |
| 7 8 | 0 H D B S I 2 Ø Ø - Ø Ø Ø Ø - Ø Ø Ø 3 4 I I I I I 1 4 5 CAT 58 5 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 |
| ON'T | SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 |
| 0 2 | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [(NP-33-81-78) On 10/26/81 the Station Review Board determined that an event which |
| [2] | occurred on 9/19/81 was reportable. On 9/19/81 at 1700 hours while performing surveil- |
| | lance testing, operators discovered that C5762B was de-energized. Radiation monitors |
| 10 [4] | RE 5030A,B,C, RE 8446, RE 5327A,B,C, RE 2387, and RE 1412 were declared inoperable, |
| 0 5 | and the station entered the action statement of Technical Specification 3.3.3.1 and |
| 0 6 | |
| [0]7] | 3.3.3.6. There was no danger to the health and safety of the public or station per- |
| 0 8 | sonnel. The redundant channels were operable throughout this occurrence. |
| 0 9 | SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC |
| | SEQUENTIAL REPORT TYPE NO. LERARO EVENT YEAR REPORT NO. SEQUENTIAL REPORT TYPE NO. NO. 17 NUMBER 8 1 |
| | ACTION LUTURE CFFECT SHUTDOWN HOURS 22 ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MADURACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER LA 18 Z 19 Z 20 Z 21 Ø Ø Ø Ø Y Z 3 Z 25 Z 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 |
| | CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) |
| 1 0 | The cause of this occurrence was due to a blown power supply fuse in circuit Y103. |
| | Station electricians replaced the fuse under Maintenance Work Order 81-1019, and the |
| 1 2 | applicable portions of ST 5099.05 were successfully completed. At 2030 hours on |
| 13 | 9/19/81 the radiation monitors were declared operable, and the station was removed |
| 114 | from the action statements. |
| 1 8 | FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 B 31 Performance of ST 5099.05 |
| | DELEASE OF RELEASE AMOUNT OF ACTIVITY (35) |
| 1 6 | Z 33 Z 34 NA |
| | NUMBER TYPE DESCRIPTION (39) |
| 11/ | 9 11 12 13 80 80 80 80 80 80 80 80 80 80 80 80 80 |
| 1 8 | NUMBER DESCRIPTION (41) (9 9 9 40 NA |
|) 8 | 11 12 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION |
| 1 9 | Z 42 NA 80 |
| | PUBLICITY ISSUED DESCRIPTION 45 IN (44) NA |
| 7 8 | 9 8112040499 811124 Mathematical Mathema |
| 7R 81-1 | S PDR ADOCK 05000346 This Matheny |

TOLEDO EDISON COMPANY DAVIS-BESSE NUCLEAR POWER STATION UNIT ONE SUPPLEMENTAL INFORMATION FOR LER NP-33-81-78

DATE OF EVENT: September 19, 1981 (determined reportable October 26, 1981)

FACILITY: Davis-Besse Unit 1

IDENTIFICATION OF OCCURRENCE: Severa' radiation monitors inoperable due to a blown fuse in circuit Y103

Conditions Prior to Occurrence: The unit was in Mode 1 with Power (MWT) = 2765 and Load (Gross MWE) = 910.

Description of Occurrence: On October 26, 1981, the Station Review Board determined that an event documented on September 19, 1981 on Deviation Report 81-135 should have also been reported as a Licensee Event Report. On September 19, 1981 at 1700 hours while performing Surveillance Test ST 5099.04, Shift Channel Check of the Radiation Monitoring System, operators discovered that C57628, Radiation Monitoring System Channel 1 Panel, was de-energized. At that time, radiation monitors RE 5030A,B,C, RE 8446, RE 5327A,B,C, RE 2387, and RE 1412 were declared inoperable. The requirements of the Radiation Monitoring Instrumentation Technical Specification 3.3.3.1 were being met even with the above detectors de-energized. However, the event is reportable because RE 5030A,B,C, must be operable in order to meet the requirements of the Post-Accident Instrumentation Technical Specification 3.3.3.6 which is applicable in Modes 1, 2, and 3.

Designation of Apparent Cause of Occurrence: The cause of this occurrence was due to a blown power supply fuse for circuit Y103.

Analysis of Occurrence: There was no danger to the health and safety of the public or to station personnel. The redundant channels were operable throughout this occurrence.

Corrective Action: The station electricians replaced the fuse under Maintenance Work Order 81-1019. Applicable portions of Surveillance Test ST 5099.05 were successfully completed.

At 2030 hours on September 19, 1981, radiation monitors RE 5327A,B,C, RE 2387A,B,C, RE 5030A,B,C, RE 8446, and RE 1412 were declared operable and the station was removed from the associated action statements.

Failure Data: No previous occurrences of the loss of power to circuit Y103 and associated equipment due to a blown fuse have been reported.

LER #81-069