## LICENSEE EVENT REPORT

EIGENSEE EVENT HEI ONT
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1   C   O   F   S   V   1   2   O   O   -   O   O   O   O   O   O   O
CON'T  O 1 SOURCE L G O 5 0 0 0 2 6 7 7 1 0 2 7 8 1 8 1 1 2 5 8 1 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 13  O 2 On two separate occasions between October 28 and November 3, 1981, the steam genera-
[0]3 tor penetration overpressure protection required by LCO 4.4.1, Table 4.4-2 was not in
0 4 service. This is a degraded mode of the LCO and is reportable per Fort St. Vrain
Technical Specification AC 7.5.2(b)2. Related occurrences are RO's 80-30, 81-067,
0 6 81-068. No affect on public health or safety. No similar reports.
0 8 6
SYSTEM CAUSE CODE SUBCODE SUBC
LER/RO   EVENT YEAR   REPORT NO.   CODE   TYPE   NO.
The Loop 2 steam generator overpressure protection instrumentation was out of service
during modifications to the penetration pressurizing piping. The modifications were
[1] [completed, and the instrumentation was returned to service.
13
114
FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 X 28 0 0 1/2 29 N/A A Personnel Observation
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  12 13  44 45 47  LOCATION OF RELEASE (36)  N/A  12 13  AMOUNT OF ACTIVITY (35)  N/A  45 45 47
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  1 7 0 0 0 37 Z 38 N/A
1 B 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  1 B 0 0 0 0 0 N/A
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION  1 9 Z (42 N/A
PUBLICITY   SSUED   DESCRIPTION 45   PDR   ADDCK 05000267   PDR   DESCRIPTION 45   S   ADDCK 05000267   PDR   DDR   DDR
NAME OF PREPARER Charles Fully PHONE: (303) 785-2223