

Portland General Electric Company Trojan Nuclear Plant 71760 Columbia River Hwy Rainier. Oregon 97048 (503) 556-3713

April 25, 1990 CPY-144-90

U.S. Nuclear Regulatory Commission Document Control Desk Washington DC 20555

Gentlemen:

Licensee Event Report No. 90-10 is attached. This report discusses an event in which a chlorine detector failure caused isolation of the Control Room Normal Ventilation System.

Sincerely,

C. P. Yundt General Manager Trojan Nuclear Plant

undt

c: Mr. John B. Martin Regional Administrator, Region V U.S. Nuclear Regulatory Commission

> Mr. David Stewart-Smith State of Oregon Department of Energy

Mr. R. C. Barr USNRC Resident Inspector Trojan Nuclear Plant FACILITY NAME (1)

LICENSEE EVENT REPORT (LER)

ABSTRACT (Limit to 1400 spaces (a. approximately fifteen single-space typewritten lines) (16)

APPROVED OMB NO. 3150-0104 * XPIRES: 4/30/92

ESTIMATED BURDEN 754 RESPONSE TO COMPLY WTH THIS INFORMATION COLLECTION REQUEST 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTE MANAGEMENT BRANCH IP-530, U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20603.

DOCKET NUMBER (2)

REGULATORY COMMISSION, WASHINGTON, DC 20555, AUGUST THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFIL OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20803.

T	rojan	Nuc1	lear 1	Plant						14	15 10 10	10131	414	1 0	013					
TITLE I	•				*************						-1-1	4-1-1		1 1 1 -						
Chlo	rine	Detec	ctor !	Pailure Ca	auses Is	olati	on Of	Cont	rol Re	oom Normal	Ventila	ition 5	Syst	em						
EVENT DATE (6) LER NUMBER (6)					PRODUCT MARKINGS OF	PORT DA	COLUMN STREET		OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIA	L REVISION NUMBER	MONTH	DAY	YEAR		PACILITY NAM	es .	DOCKET			1.1					
0 3	2 7	90	90	0 1 0	00	0 4	2 6	90				0 5	0 10	101	11					
	RATING ODE (0)		-	OR RESIDENCE AND ADDRESS OF THE PERSON NAMED IN	ED PURSUANT	-	PERSONAL PROPERTY.	ENTS OF 1	0 CFR & 10	Check one or more o	the following) (1	(1)								
POWER CEVEL (10) OLO IO			20 20 20 20	405(a)(1)(ii) 405(a)(1)(iii) 405(a)(1)(iii) 405(a)(1)(iv) 405(a)(1)(iv)	50.36(c) 50.36(c) 50.73(c) 50.73(c) 50.73(c))(1))(2) ·(2)(i))(2)(ii)		X	50.73(a)(2)(v) 50.73(a)(2)(vi) 50.73(a)(2)(vii)(A 50.73(a)(2)(viii)(A 50.73(a)(2)(viii)(B) 50.73(a)(2)(viii)(B)		73.71(b) 73.71(c) OTHER (Specify in Abstract below and in Text, NRC Form 386A)									
					L	ICENSEE	CONTACT	FOR THIS	LER (12)											
NAME	E. W.	Ford	, Con	pliance H	Engineer						AREA CODE	515 I	61 -		1717					
	,			COMPLETE	ONE LINE FOR	EACH CO	MPONEN'	FAILURE	DESCRIBE	D IN THIS REPORT										
CAUSE	SYSTEM	STEM COMPO		MANUFAC- TURER	REPORTABLE TO NPRDS			CAUSE	SYSTEM	COMPONENT	MANUFAC- TURER	AEPORT	ABLE							
D	VII	1 D	EIT	X191919	N					111	111									
	Ш		ш	بيب						111	111			,						
7 46/	Ill ver co	ompiete E	XPECTED	SUPPLEMI SUBMISSION DATI	ENTAL REPORT		D (14)				SUBMISSI DATE (1	ON -	MONTH	DAY	YEAR					

On March 27, 1990, the Trojan Nuclear Plant was shutdown in Mode 5. The 1990 refueling and maintenance outage was in progress. At 1346 the "B" train chlorine detector failed, causing isolation of the Control Room Normal Ventilation System, an Engineered Safety Features actuation. The cause of chlorine detector failure was a leaking membrane cap on the sensor probe which caused the probe to lose its electrolyte. It is suspected that the sensor probe membrane was damaged or the threads on the car were not properly sealed when the detector was installed. This event had no effect upon public health and safety. The Control Room Normal Ventilation System responded, as designed, to isolate the control room from outside air when the chlorine detector failed. The failed chlorine detector probe was replaced on April 5, 1990. The chlorine detector vendor was contacted to obtain clarification on maintenance of the sensor probe. The information received will be incorporated into the chlorine detector technical manual for future reference. Additionally, the failed probe is being returned to the vendor for failure analysis. The results of the analysis will be reviewed for any further required corrective actions.

APPROVED OMB NO. 3150-0104 EXPIRES 4/30/92

LICENSEE EVENT REPORT (L ...)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 80.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530). U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20655. AND TO THE PAPERWORK REDUCTION PROJECT 13150-0104). OFFICE OF MANAGEMENT AND BURDET WASHINGTON, DC 20630.

The same that th																				
FACILITY NAME (1)	DOCKET NUMBER (2)								LER NUMBER (6)								PAGE (3)			
									-	EAR		SEQUE	BER		REVIS	ION		T	T	
Trojan Nuclear Plant	0	15	10	10	10	13	14	14	9	10	_	01	10	_	01	0	01	20	F	013

TEXT (If more beace is required, use additional NRC Form \$584's) (17)

EVENT DESCRIPTION

On March 27, 1990, the Trojan Nuclear Plant was shutdown in Mode 5. The 1990 refueling and maintenance outage was in progress. At 1346 the "B" train chlorine detector [VI,DET] failed, causing isolation of the Control Room Normal Ventilation System [VI]. This is considered to be an event that resulted in an automatic actuation of an Engineered Safety Feature which is reportable under the requirements of 10 CFR 50.72(b)(2)(ii). At 1450 the Nuclear Regulatory Commission was notified of the event via the Emergency Notification System. This event is also considered reportable under the requirements of 10 CFR 50.73(a)(2)(iv). This report is submitted to fulfill those reporting requirements.

CAUSE

The cause of the Engineered Safety Feature actuation (isolation of the Control Room Normal Ventilation System) was the failure of the "B" train chlorine detector. The chlorine detection system is designed to isolate the Control Room Normal Ventilation System upon system failure or upon detection of chlorine in excess of predetermined concentrations. Therefore, the actuation occurred in accordance with plant design.

The cause of chlorine detector failure was a leaking membrane cap on the sensor probe which caused the probe to lose its electrolyte. The chlorine detectors presently in use at the Trojan Nuclear Plant were installed earlier in the month because the response time of the original detectors was not adequate to meet the requirements of the plant toxic gas analysis. It is suspected that the sensor probe membrane was damaged or the threads on the cap were not properly sealed when the detector was installed.

EVENT ANALYSIS

This event had no effect upon public health and safety. The Control Room Normal Ventilation System responded, as required, to isolate the control room from outside air when the chlorine detector failed.

CORRECTIVE ACTIONS

The failed chlorine detector probe was replaced on April 5, 1990. The chlorine detector vendor (Sensidyne) was contacted to obtain clarification on maintenance of the sensor probe. The information received will be incorporated into the chlorine detector technical manual for future reference. Additionally, the failed probe is being returned to the vendor for failure analysis. The results of the analysis will be reviewed for any further required corrective actions.

NAC FORM 366A

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104 EXPIRES. 4/30/92

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-830), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 2065S, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20603.

PACILITY NAME (1)										
DOCKET NUMBER (2)		L	ER NUMB	PAGE (3)						
	100000000000000000000000000000000000000	1 (2000)	SEQUEN	TIAL		REVISION NUMBER				
0 5 0 0 0 3 4 4	9,0	-	0 1	10	_	0,0	0,3	OF	0	, 3
	0 5 0 0 0 3 4 4	YEAR	YEAR	LEH NUMBO	YEAR SEQUENTIAL NUMBER	YEAR SEQUENTIAL NUMBER	DOCKET NUMBER (2) LER NUMBER (6) YEAR SEQUENTIAL REVISION NUMBER NUMBER	VEAR SEQUENTIAL REVISION NUMBER	DOCKET NUMBER (2) LER NUMBER (6) PAGE YEAR SEQUENTIAL REVISION NUMBER NUMBER	DOCKET NUMBER (2) LER NUMBER (6) PAGE (3) YEAR SEQUENTIAL REVISION NUMBER

TEXT III more score is required, use additional VRC Form 3884's) (17

PREVIOUS SIMILAR EVENTS

Three previous events were identified in which the Control Room Normal Ventilation System was isolated due to a toxic gas detector failure or because a spurious actuation signal was generated. These events were documented in Licensee Event Reports 88-07, 89-03 and 90-08.

This is the first Licensee Event Report identifying the failure of one of the new detectors.