

NUREG/CR-5834  
PNL-7906

---

# Auxiliary Feedwater System Risk-Based Inspection Guide for the Fort Calhoun Nuclear Power Plant

---

Prepared by  
N. E. Moffitt, B. F. Gore, T. A. Vehec, T. V. Vo

Pacific Northwest Laboratory  
Operated by  
Battelle Memorial Institute

Prepared for  
U.S. Nuclear Regulatory Commission

9303120001 930228  
PDR ADOCK 05000285  
G PDR

## AVAILABILITY NOTICE

### Availability of Reference Materials Cited in NRC Publications

Most documents cited in NRC publications will be available from one of the following sources:

1. The NRC Public Document Room, 2120 L Street, NW., Lower Level, Washington, DC 20555
2. The Superintendent of Documents, U.S. Government Printing Office, P.O. Box 37082, Washington, DC 20013-7082
3. The National Technical Information Service, Springfield, VA 22161

Although the listing that follows represents the majority of documents cited in NRC publications, it is not intended to be exhaustive.

Referenced documents available for inspection and copying for a fee from the NRC Public Document Room include NRC correspondence and internal NRC memoranda; NRC bulletins, circulars, information notices, inspection and investigation notices; licensee event reports; vendor reports and correspondence; Commission papers; and applicant and licensee documents and correspondence.

The following documents in the NUREG series are available for purchase from the GPO Sales Program: formal NRC staff and contractor reports, NRC-sponsored conference proceedings, international agreement reports, grant publications, and NRC booklets and brochures. Also available are regulatory guides, NRC regulations in the *Code of Federal Regulations*, and *Nuclear Regulatory Commission Issuances*.

Documents available from the National Technical Information Service include NUREG-series reports and technical reports prepared by other Federal agencies and reports prepared by the Atomic Energy Commission, forerunner agency to the Nuclear Regulatory Commission.

Documents available from public and special technical libraries include all open literature items, such as books, journal articles, and transactions. *Federal Register* notices, Federal and State legislation, and congressional reports can usually be obtained from these libraries.

Documents such as theses, dissertations, foreign reports and translations, and non-NRC conference proceedings are available for purchase from the organization sponsoring the publication cited.

Single copies of NRC draft reports are available free, to the extent of supply, upon written request to the Office of Administration, Distribution and Mail Services Section, U.S. Nuclear Regulatory Commission, Washington, DC 20555.

Copies of industry codes and standards used in a substantive manner in the NRC regulatory process are maintained at the NRC Library, 7920 Norfolk Avenue, Bethesda, Maryland, for use by the public. Codes and standards are usually copyrighted and may be purchased from the originating organization or, if they are American National Standards, from the American National Standards Institute, 1430 Broadway, New York, NY 10018.

## DISCLAIMER NOTICE

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, or any of their employees, makes any warranty, expressed or implied, or assumes any legal liability of responsibility for any third party's use, or the results of such use, of any information, apparatus, product or process disclosed in this report, or represents that its use by such third party would not infringe privately owned rights.

NUREG/CR-5834  
PNL-7906

---

---

# Auxiliary Feedwater System Risk-Based Inspection Guide for the Fort Calhoun Nuclear Power Plant

---

---

Manuscript Completed: December 1992  
Date Published: February 1993

Prepared by  
N. E. Moffitt, B. F. Gore, T. A. Vehec, T. V. Vo

Pacific Northwest Laboratory  
Richland, WA 99352

Prepared for  
Division of Systems Safety and Analysis  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555  
NRC FIN L1310

## Abstract

In a study sponsored by the U.S. Nuclear Regulatory Commission (NRC), Pacific Northwest Laboratory has developed and applied a methodology for deriving plant-specific risk-based inspection guidance for the auxiliary feedwater (AFW) system at pressurized water reactors that have not undergone probabilistic risk assessment (PRA). This methodology uses existing PRA results and plant operating experience information. Existing PRA-based inspection guidance information recently developed for the NRC for various plants was used to identify generic component failure modes. This information was then combined with plant-specific and industry-wide component information and failure data to identify failure modes and failure mechanisms for the AFW system at the selected plants. Fort Calhoun was selected as the sixth plant for study. The product of this effort is a prioritized listing of AFW failures which have occurred at the plant and at other PWRs. This listing is intended for use by NRC inspectors in the preparation of inspection plans addressing AFW risk-important components at the Fort Calhoun plant.

## Contents

Abstract .....	iii
Summary .....	ix
1 Introduction .....	1.1
2 Fort Calhoun AFW System .....	2.1
2.1 System Description .....	2.1
2.2 Success Criterion .....	2.1
2.3 System Dependencies .....	2.2
2.4 Operational Constraints .....	2.2
3 Inspection Guidance for the Fort Calhoun AFW System .....	3.1
3.1 Risk Important AFW Components and Failure Modes .....	3.1
3.1.1 Multiple Pump Failures due to Common Cause .....	3.1
3.1.2 Turbine Driven Pump Fails to Start or Run .....	3.2
3.1.3 Motor Driven Pump A or B Fails to Start or Run .....	3.3
3.1.4 Pump Unavailable Due to Maintenance or Surveillance .....	3.3
3.1.5 Air Operated Isolation and Flow Control Valve Failure .....	3.4
3.1.6 Motor Operated Valve Failure .....	3.4
3.1.7 Manual Suction or Discharge Valves Fail Closed .....	3.5
3.1.8 Leakage of Hot Feedwater through Check Valves .....	3.6
3.2 Risk Important AFW System Walkdown Table .....	3.6
4 Generic Risk Insights from PRAs .....	4.1
4.1 Risk Important Accident Sequences Involving AFW System Failure .....	4.1
4.2 Risk Important Component Failure Modes .....	4.1
5 Failure Modes Determined From Operating Experience .....	5.1
5.1 Fort Calhoun Experience .....	5.1
5.1.1 AFW Pump Control Logic, Instrumentation and Electrical Failures .....	5.1
5.1.2 Failure of AFW Pump Discharge Flow Control Valve to Steam Generator .....	5.1
5.1.3 AFW Valve Failures .....	5.1
5.1.4 Human Errors .....	5.1

5.2 Industry Wide Experience .....	5.1
5.2.1 Common Cause Failures .....	5.2
5.2.2 Human Errors .....	5.3
5.2.3 Design/Engineering Problems and Errors .....	5.4
5.2.4 Component Failures .....	5.5
6 References .....	6.1

## Figure

2.1 Fort Calhoun AFW system .....	2.3
-----------------------------------	-----

## Table

3.1 Risk important walkdown table for Fort Calhoun AFW system components .....	3.7
--	-----

## Summary

This document presents a compilation of auxiliary/emergency feedwater (AFW/EFW) system failure information which has been screened for risk significance in terms of failure frequency and degradation of system performance. It is a risk-prioritized listing of failure events and their causes that are significant enough to warrant consideration in inspection planning at the Fort Calhoun plant. This information is presented to provide inspectors with increased resources for inspection planning at Fort Calhoun.

The risk importance of various component failure modes was identified by analysis of the results of probabilistic risk assessments (PRAs) for many pressurized water reactors (PWRs). However, the component failure categories identified in PRAs are rather broad, because the failure data used in the PRAs is an aggregate of many individual failures having a variety of root causes. In order to help inspectors focus on specific aspects of component operation, maintenance and design which might cause these failures, an extensive review of component failure information was performed to identify and rank the root causes of these component failures. Both Fort Calhoun and industry-wide failure information was analyzed. Failure causes were sorted on the basis of frequency of occurrence and seriousness of consequence, and categorized as common cause failures, human errors, design problems, or component failures.

This information is presented in the body of this document. Section 3.0 provide brief descriptions of these risk-important failure causes, and Section 5.0 presents more extensive discussions, with specific examples and references. The entries in the two sections are cross-referenced.

An abbreviated system walkdown table is presented in Section 3.2 which includes only components identified as risk important. This table lists the system lineup for normal, standby system operation.

This information permits an inspector to concentrate on components important to the prevention of core damage. However, it is important to note that inspections should not focus exclusively on these components. Other components which perform essential functions, but which are not included because of high reliability or redundancy, must also be addressed to ensure that degradation does not increase their failure probabilities, and hence their risk importance.



## 1 Introduction

This document is one of a series providing plant-specific inspection guidance for auxiliary/emergency feedwater (AFW/EFW) systems at pressurized water reactors (PWRs). This guidance is based on information from probabilistic risk assessments (PRAs) for similar PWRs, industry-wide operating experience with AFW systems, plant-specific AFW system descriptions, and plant-specific operating experience. It is not a detailed inspection plan, but rather a compilation of AFW system failure information which has been screened for risk significance in terms of failure frequency and degradation of system performance. The result is a risk-prioritized listing of failure events and the causes that are significant enough to warrant consideration in inspection planning at Fort Calhoun.

This inspection guidance is presented in Section 3.0, following a description of the Fort Calhoun AFW system in Section 2.0. Section 3.0 identifies the risk important system components by Fort Calhoun identification number, followed by brief descriptions of each of the various failure causes of that component. These include specific human errors, design deficiencies, and hardware failures. The discussions also identify where common cause failures have affected multiple, redundant components. These brief discussions identify specific aspects of system or component design, operation, maintenance, or testing for inspection by observation, records review, training observation, procedures review, or by observation of the implementation of procedures. An AFW system walkdown table identifying risk important components and their lineup for normal, standby system operation is also provided.

The remainder of the document describes and discusses the information used in compiling this inspection guidance. Section 4.0 describes the risk important information which has been derived from PRAs and its sources. As review of that section will show, the failure events identified in PRAs are rather broad (e.g., pump fails to start or run, valve fails closed). Section 5.0 addresses the specific failure causes which have been combined under these broad events.

AFW system operating history was studied to identify the various specific failures which have been aggregated into the PRA failure events. Section 5.1 presents a summary of Fort Calhoun failure information, and Section 5.2 presents a review of industry-wide failure information. The industry-wide information was compiled from a variety of NRC sources, including AEOD analyses and reports, information notices, inspection and enforcement bulletins, and generic letters, and from a variety of INPO reports as well. Some Licensee Event Reports and NPRDS event descriptions were also reviewed. Finally, information was included from reports of NRC-sponsored studies of the effects of plant aging, which include quantitative analyses of reported AFW system failures. This industry-wide information was then combined with the plant-specific failure information to identify the various root causes of the broad failure events used in PRAs, which are identified in Section 3.0.

## 2 Fort Calhoun AFW System

This section presents an overview description of the Fort Calhoun AFW system (Combustion Engineering plant), including a simplified schematic system diagram. In addition, the system success criterion, system dependencies, and administrative operational constraints are also presented.

### 2.1 System Description

The AFW system provides feedwater to the steam generators (SG) to allow secondary-side heat removal from the primary system when main feedwater is unavailable. The system is capable of functioning for extended periods, which allows time to restore main feedwater flow or to proceed with an orderly cooldown of the plant to where the Shutdown Cooling System can remove decay heat. A simplified schematic diagram of the Fort Calhoun AFW system is shown in Figure 2.1.

The AFW system consists of one motor-driven (MD) pump and one steam-driven (TD) pump along with the associated piping, valves and instrumentation normally connected to the Emergency Feedwater Tank (EFWT). It is designed to start up and establish flow automatically. Both pumps start on receipt of a steam generator low-low level signal to feed an intact steam generator. The turbine driven and motor driven pumps will also start automatically on a blackout signal when the Engineered Safety Feature sequencer re-energizes buses 1A4 and 1A3 respectively.

A common suction line from the EFWT supplies water through two parallel locked open valves to the suction headers of the turbine-driven pump and the motor-driven pump. Isolation valves in these lines are locked open. Power, control, and instrumentation associated with each pump is independent from the other. Steam for the turbine-driven pump is supplied by either or both steam generators, from a point upstream of the main steam isolation valves, through valves YCV-1045A and YCV-1045B. The steam supply lines then join upstream of the AFW steam stop valve YCV-1045, before steam enters the turbine driven pump. Each AFW

pump is equipped with a continuous recirculation flow system, which prevents pump deadheading.

Auxiliary feedwater is supplied by the motor driven pump to each steam generator through one of three flowpaths depending on the mode of plant operation. Two of the flow paths, used primarily during start-up and shutdown, connect the AFW piping to the MFW piping upstream of main feedwater regulating valves. One flowpath is through HCV-1384 and a backup flowpath is via cross connect valves FW-744 or FW-745 and FW-746. The third emergency feedwater AFW flowpath connects the AFW pumps discharge to the auxiliary feed nozzles through locked open manual valves FW-171, FW-172, and air operated containment isolation/flow control valves HCV-1107A/B and HCV-1108A/B. The "B" valves can be throttled to control flow and also function as backup containment isolation valves. Each line contains check valves to prevent leakage from the feedwater lines. The turbine driven pump is not normally used for such evolutions. Ft. Calhoun has recently installed a diesel driven start-up feed pump, FW-54, which is designed to be used during start-up and shutdown, relieving the motor driven AFW pump of this duty.

The (EFWT) is the normal source of water for the AFW System and is required to store sufficient demineralized water (55,000 gallons), to maintain the reactor coolant system (RCS) at hot standby conditions for 8 hours with steam discharge to atmosphere. All tank connections except those required for instrumentation, auxiliary feedwater pump suction, chemical analysis, and tank drainage are located above this minimum level. Backup AFW water supplies for the AFW system are from the CST via the Diesel driven Start-Up Feedwater pump and from the Missouri River through a fire water hookup.

### 2.2 Success Criterion

System success requires the operation of at least one pump supplying rated flow to at least one of the two steam generators.

### 2.3 System Dependencies

The AFW system depends on AC power for the motor driven pump and AFW system instrumentation, DC power at various voltage levels for control power to pumps and valves and automatic actuation signal. The Condensate and Fire Systems provide emergency makeup to the EFWT. Instrument Air is required to operate the feed supply valves to the steam generators, the steam supply valves to the turbine driven pump, the turbine governor speed control, and the recirculation control, and the recirculation control valves. The Main Feedwater System provides a flow path for normal reactor startup and shutdown operation of the AFW System through the main feedwater regulating bypass valves. Steam availability is required for the turbine-driven pump.

### 2.4 Operational Constraints

The Fort Calhoun Technical Specifications require that both AFW pumps and their associated flow paths are operable with the RCS temperature above 300 degrees fahrenheit. One AFW pump may be inoperable in Mode 1 or 2 for up to 24 hours provided that the other AFW pump is tested to demonstrate operability.

The Fort Calhoun Technical Specifications require a minimum supply of 55,000 gallons of water to be stored in the EFWT during plant operation and a backup supply to the EFWT be available from the Missouri River via the fire water system.




Figure 2.1 Ft. Calhoun AFW system

### 3 Inspection Guidance for the Fort Calhoun AFW System

In this section the risk important components of the Fort Calhoun AFW system are identified, and the important failure modes for these components are briefly described. These failure modes include specific human errors, design deficiencies, and types of hardware failures which have been observed to occur for these components, both at Fort Calhoun and at PWRs throughout the nuclear industry. The discussions also identify where common cause failures have affected multiple, redundant components. These brief discussions identify specific aspects of system or component design, operation, maintenance, or testing for inspection activities. These activities include: observation, records review, training observation, procedures review, or by observation of the implementation of procedures.

Table 3.1 is an abbreviated AFW system walkdown table which identifies risk-important components. This table lists the system lineup for normal (standby) system operation. Inspection of the components identified in the AFW walkdown table addresses essentially all of the risk associated with AFW system operation.

#### 3.1 Risk Important AFW Components and Failure Modes

Common cause failures of multiple pumps are the most risk-important failure modes of AFW system components. These are followed in importance by single pump failures, level control valve failures, and individual check valve leakage failures.

The following sections address each of these failure modes, in decreasing order of risk-importance. They present the important root causes of these component failure modes which have been distilled from historical records. Each item is keyed with a three digit code to discussions in Section 5.2 where additional information on historical events is presented.

#### 3.1.1 Multiple Pump Failures due to Common Cause

The following listing summarizes the most important multiple-pump failure modes identified in Section 5.2.1, Common Cause Failures, and each item is keyed with a 3 digit code to entries in that section.

- Incorrect operator intervention into automatic system functioning, including improper manual starting and securing of pumps, has caused failure of all pumps, including overspeed trip on startup, and inability to restart prematurely secured pumps. CC1.

**Inspection Suggestion** - Observe Abnormal and Emergency Operating Procedure (AGP/EOP) simulator training exercises to verify that the operators comply with procedures during observed evolutions. Observe surveillance testing on the AFW system to verify it is in strict compliance with the surveillance test procedure.

- Valve mispositioning has caused failure of all pumps. Pump suction, steam supply, and instrument isolation valves have been involved. CC2.

**Inspection Suggestion** - Verify that the system valve alignment, air operated valve control and valve actuating air pressures are correct using 3.1 Walkdown Table, the system operating procedures, and operator rounds logsheet. Review surveillance procedures that alter the standby alignment of the AFW system. Ensure that an adequate return to normal section exists.

- Steam binding has caused failure of multiple pumps. This resulted from leakage of hot feedwater past check valves and a motor-operated valve into a common discharge header. CC10. Multiple-pump steam binding has also resulted from improper valve lineups, and from running a pump deadheaded. CC3.

**Inspection Suggestion** - Verify that the pump discharge temperature is within the limits specified on the operator rounds logsheet ( $< 260^{\circ}\text{F}$ ). Assure any instruments used to verify the temperature by the utility are of an appropriate range and included in a calibration program. Verify affected pumps have been vented in accordance with procedure OI-AFW-3 to ensure steam binding has not occurred. Verify that a maintenance work request has been written to repair leaking check valves.

- Pump control circuit deficiencies or design modification errors have caused failures of multiple pumps to auto start, spurious pump trips during operation, and failures to restart after pump shutdown. CC4. Incorrect setpoints and control circuit calibrations have also prevented proper operation of multiple pumps. CC5.

**Inspection Suggestion** - Review design change implementation documents for the post maintenance testing required prior to returning the equipment to service. Assure the testing verifies that all potentially impacted functions operate correctly, and includes repeating any plant start-up or hot functional testing that may be affected by the design change.

- Loss of a vital power bus has failed both the turbine-driven and one motor-driven pump due to loss of control power to steam admission valves or to turbine controls, and to motor controls powered from the same bus. CC6.

**Inspection Suggestion** - The material condition of the electrical equipment is an indicator of probable reliability. Review the Preventative Maintenance (PM) records to assure the equipment is maintained on an appropriate frequency for the environment it is in and that the PM's are actually being performed as required by the program. Review the outstanding Corrective Maintenance records to assure the deficiencies found on the equipment are promptly corrected.

- Simultaneous startup of multiple pumps has caused oscillations of pump suction pressure causing

multiple-pump trips on low suction pressure, despite the existence of adequate static net positive suction head (NPSH). CC7. At H. B. Robinson, design reviews have identified inadequately sized suction piping which could have yielded insufficient NPSH to support operation of more than one pump. CC8.

**Inspection Suggestion** - Assure that plant conditions which could result in the blockage or degradation of the suction flow path are addressed by system maintenance and test procedures. Examples include, if the AFW system has an emergency source from a water system with the potential for bio-fouling, then the system should be periodically treated to prevent buildup and routinely tested to assure an adequate flow can be achieved to support operation of all pumps, or inspected to assure that bio-fouling is not occurring. Design changes that affect the suction flow path should repeat testing that verified an adequate suction source for simultaneous operation of all pumps. Verify that testing has, at sometime, demonstrated simultaneous operation of all pumps. Verify that surveillances adequately test all aspects of the system design functions, for example, demonstrate that the AFW pumps will trip on low suction pressure.

### 3.1.2 Turbine Driven Pump Fails to Start or Run

- Improperly adjusted and inadequately maintained turbine governors have caused pump failures. HE2. Problems include worn or loosened nuts, set screws, linkages or cable connections, oil leaks and/or contamination, and electrical failures of resistors, transistors, diodes and circuit cards, and erroneous grounds and connections. CF5. Fort Calhoun has experienced similar type failures.

**Inspection Suggestion** - Review PM records to assure the governor oil is being replaced within the designated frequency. During plant walk-downs carefully inspect the governor and linkages for loose fasteners, leaks, and unsecured or degraded conduit. Review vendor manuals to

ensure PM procedures are performed according to manufacturer's recommendations and good maintenance practices. Observe the operation of the turbine driven Aux Feed pump and assure that the backpressure trip is reset as directed in OI-AFW-3.

- Condensate slugs in steam lines have caused turbine speed control problems. Tests repeated right after such occurrences may fail to indicate the problem due to warming and clearing of the steam lines. Surveillances should exercise all steam supply connections. DE2.

**Inspection Suggestion** - Verify that the steam traps are valved in on the steam supply line. For steam traps that are on a pressurized portion of the steam line, check the steam trap temperature (if unlagged) to assure it is warmer than ambient (otherwise it may be stuck or have a plugged line). If the steam trap discharge is visible, assure there is evidence of liquid discharge.

- Trip and throttle valve (TTV) problems which have failed the turbine driven pump include physically bumping it, failure to reset it following testing, and failures to verify control room indication of reset. HE2. Whether either the backpressure trip or TTV trip can be reset without resetting the other, and unambiguity of control room and local indication of TTV position and backpressure trip linkage reset status, all affect the likelihood of these errors. DE3. At Fort Calhoun, the turbine driven pump has failed to start on demand due to the backpressure trip level not being reset. There is no direct indication for the trip lever position in the control room. A common alarm, "FW-10 TURBINE DRIVEN FEEDWATER PUMP TROUBLE", Annunciator A-36B window 18 in the control room could indicate this trip along with three other abnormal conditions.

**Inspection Suggestion** - Carefully inspect the TTV backpressure trip linkage and assure it is reset and in good physical condition. Assure that there is a good steam isolation to the turbine, otherwise continued turbine high

temperature can result in degradation of the oil in the turbine, interfering with proper over-speed trip operation. Review training procedures to ensure operator training on resetting the TTV is current.

### 3.1.3 Motor Driven Pump A or B Fails to Start or Run

- Control circuits used for automatic and manual pump starting are an important cause of motor driven pump failures, as are circuit breaker failures. CF7.

**Inspection Suggestion** - Review corrective maintenance records when control circuit problems occur to determine if a trend exists. Every time a breaker is racked in a PMT should be performed to start the pump, assuring no control circuit problems have occurred as a result of the manipulation of the breaker. (Control circuit stabs have to make up upon racking the breaker, as well as cell switch damage can occur upon removal and reinstallation of the breaker.)

- Mispositioning of handswitches and procedural deficiencies have prevented automatic pump start. HE3.

**Inspection Suggestion** - Confirm switch position using Table 3.1. Review administrative procedures concerning documentation of procedural deficiencies. Ensure operator training on procedural changes is current.

### 3.1.4 Pump Unavailable Due to Maintenance or Surveillance

- Both scheduled and unscheduled maintenance remove pumps from operability. Surveillance requires operation with an altered line-up. A pump train is declared inoperable during testing. Prompt scheduling and performance of maintenance and surveillance minimize this unavailability.

**Inspection Suggestion** - Review the time the AFW system and components are inoperable.

## Inspection

Assure all maintenance is being performed that can be performed within a single outage time frame, avoiding multiple equipment outages. The maintenance should be scheduled before the routine surveillance test, so credit can be taken for both post maintenance testing and surveillance testing, avoiding excessive testing. Review surveillance schedule for frequency and adequacy to verify system operability requirements per Technical Specifications.

### 3.1.5 Air Operated Isolation and Flow Control Valve Failure

Emergency AFW feed to S/G A: HCV-1107A/B  
Emergency AFW feed to S/G B: HCV-1108A/B  
Recirculation Flow Control MD: TD FCV-1368,  
FCV-1369

The emergency AFW feedwater control valves to S/G A and B are normally closed valves. AFW recirculation flow valves are normally open and they control recirculation flow to the EFWT. All of these valves are designed to fail open on loss of Instrument Air or loss of control power.

- Control circuit problems have been a primary cause of failures, both at Fort Calhoun and elsewhere. CF9. Valve failures have resulted from blown fuses, failure of control components (such as current/pneumatic convertors), diaphragm failures, broken and dirty contacts, misaligned or broken limit switches, control power loss, and calibration problems. Degraded operation has also resulted from improper air pressure due to air regulator failure or leaking air lines.

**Inspection Suggestion** - Check for control air system alignment and air leaks during plant walkdowns. (Regulators may have a small amount of external bleed to maintain downstream pressure.) Check for cleanliness and physical condition of visible circuit elements. Review valve stroke time surveillance for adverse trends, especially those valves on reduced testing frequency. Review air system surveillances to ensure that moisture content of air is within established limits.

- Leakage of hot feedwater through check valves has caused thermal binding of flow control MOVs. AOVs may be similarly susceptible. CF2.

**Inspection Suggestion** - Covered by 3.1.1 bullet 3.

- Multiple flow control valves have been plugged by clams when suction switched automatically to an alternate, untreated source. CC9.

**Inspection Suggestion** - Covered by 3.1.1 bullet 6.

### 3.1.6 Motor Operated Valve Failure

AFW to Main Feedwater Line: HCV-1384

This normally closed MOV supplies AFW Flow to the steam generators through the main feed lines during system startup or shutdown. It would also be required to be used in the event the diesel driven startup feed pump was required to supplement AFW system flow in an emergency condition. It fails as-is on a loss of power and can be manually operated using a local hand wheel.

- Common cause failure of MOVs has resulted from failure to use electrical signature tracing equipment to determine proper settings of torque switch and torque switch bypass switches. Failure to calibrate switch settings for high torques necessary under design basis accident conditions has also been involved. CC11. Fort Calhoun has experienced valve failure due to improper torque switch settings.

**Inspection Suggestion** - Review the MOV test records to assure the testing and settings are based on dynamic system conditions. Overtorquing of the valve operator can result in valve damage such as cracking of the seat or disc. Review the program to assure overtorquing is identified and corrective actions are taken to assure valve operability following an overtorque condition. Review the program to assure EQ seals are renewed as required during the restoration from testing to maintain the EQ rating of the MOV.



- Valve motors have been failed due to lack of, or improper sizing or use of thermal overload protective devices. Bypassing and oversizing should be based on proper engineering for *design basis* conditions. CF4.

**Inspection Suggestion** - Review the administrative controls for documenting and changing the settings of thermal overload protective devices. Assure the information is available to the maintenance planners.

- Grease trapped in the torque switch, driving pack of Limitorque SMB motor operators has caused motor burnout or thermal overload trip by preventing torque switch actuation. CF8.

**Inspection Suggestion** - Review this only if the MOV testing program reveals deficiencies in this area.

- Manually reversing the direction of motion of operating MOVs has overloaded the motor circuit. Operating procedures should provide cautions, and circuit designs may prevent reversal before each stroke is finished. DE7.

**Inspection Suggestion** - None. Circuit design prevents this problem at Ft Calhoun.

### 3.1.7 Manual Suction or Discharge Valves Fail Closed

TD Pump FW-10: FW-349 or FW-172  
MD Pump FW-6: FW-350 or FW-171  
EFWT Discharge: FW-339 or FW-1316

These manual valves are all normally locked open. For each pump, closure of the first valve listed would block pump suction and closure of the second valves would block pump discharge except recirculation to the EFWT.

- Valve mispositioning has resulted in failures of multiple trains of AFW. CC2. It has also been the

dominant cause of problems identified during operational readiness inspections. HE1. Events have occurred most often during maintenance, calibration, or system modifications. Important causes of mispositioning include:

- Failure to provide complete, clear, and specific procedures for tasks and system restoration
- Failure to promptly revise and validate procedures, training, and diagrams following system modifications
- Failure to complete all steps in a procedure
- Failure to adequately review uncompleted procedural steps after task completion
- Failure to verify support functions after restoration
- Failure to adhere scrupulously to administrative procedures regarding tagging, control and tracking of valve operations
- Failure to log the manipulation of sealed valves
- Failure to follow good practices of written task assignment and feedback of task completion information
- Failure to provide easily read system drawings, legible valve labels corresponding to drawings and procedures, and labeled indications of local valve position

**Inspection Suggestion** - Review the administrative controls that relate to valve positioning and sealing, system restoration following maintenance, valve labeling, system drawing updating, and procedure revision, for proper implementation.

### 3.1.8 Leakage of Hot Feedwater through Check Valves

At MFW connections: Valves FW-161, 162, 163, 164, 1334

At pump discharges: Valves FW-173, 174

- Leakage of hot feedwater through several check valves in series has caused steam binding of multiple pumps. Leakage through a closed level control valve in series with check valves has also occurred at Fort Calhoun, as would be required for leakage to reach the motor driven pumps A and B. CC10.

**Inspection Suggestion** - Covered by 3.1.1 bullet 3.

- Slow leakage past the final check valve of a series may not force the check valve closed. Other check valves in series may leak similarly. Piping orientation and valve design are important factors in achieving true series protection. CF1. Check valve leakage has occurred at Ft. Calhoun. Wahl instruments contact thermometers are installed on the discharge piping of both AFW pumps. TI-1383 on the TD AFWP and TI-1382 on the MD AFWP. The range of these instruments is 0-500 degrees. The steam binding procedure is entered at an indicated temperature of 260 degrees fahrenheit.

**Inspection Suggestion** - Covered by 3.1.1 bullet 3.

### 3.2 Risk Important AFW System Walkdown Table

Table 3.1 presents an AFW system walkdown table including only components identified as risk important. This information allows inspectors to concentrate their efforts on components important to prevention of core damage. However, it is essential to note that inspections should not focus exclusively on these components. Other components which perform essential functions, but which are absent from this table because of high reliability or redundancy, must also be addressed to ensure that their risk importance are not increased. An example would include ensuring an adequate water level in the EFWT exists.

Table 3.1 Risk important walkdown table for Fort Calhoun AFW system components

Component #	Component Name	Required Position	Actual Position
	<u>Electrical</u>		
FW-6	Motor-Driven Pump	Racked In/ Closed	_____
	<u>Diesel</u>		
FW-54	Diesel-Driven Pump	Racked In/ Closed	_____
	<u>Valves</u>		
FW-339	EFWT Outlet Valve	Locked Open	_____
FW-1316	EFWT Outlet Valve	Locked Open	_____
FW-684	CST Outlet Valve	Locked Open	_____
FW-349	TDAFW Pump FW-10 Suction	Locked Open	_____
FW-350	MDAFW Pump FW-6 Suction	Locked Open	_____
FW-1016	Diesel Pump FW-54 Suction	Open	_____
FW-172	TDAFW Pump Discharge	Locked Open	_____
FW-171	MDAFW Pump Discharge	Locked Open	_____
FW-1017	Diesel AFW Pump Discharge	Open	_____
FW-900	TDAFW Pump Recirculation Isolation	Open	_____
FCV-1368	MDAFW Pump Recirculation	Auto/Open*	_____
FCV-1369	TDAFW Pump Recirculation	Auto/Open	_____
FW-1029	Diesel AFW Pump Recirculation Isolation	Locked Open	_____
FW-1151	Diesel AFW Pump Cooling Water Flow Valve	Throttled	_____

Table 3.1 (Continued)

Component #	Component Name	Required Position	Actual Position
FW-1513	Diesel AFW Pump Excess Flow Recirculation Valve	Closed	_____
FW-1253	Diesel AFW Pump Recirculation Flow Control Valve	Operable	_____
HCV-2119	Fuel Oil Day Tank Inlet Isolation	Operable	_____
FW-744	TDAFW Alternate Discharge Isolation	Closed	_____
FW-745	MDAFW Alternate Discharge Isolation	Closed	_____
FW-746	AFW Pumps Combined Alternate Discharge Isolation	Locked Open	_____
FW-149	FCV-1101 Inlet Isolation	Locked Open	_____
FW-150	HCV-1105 Inlet Isolation	Locked Open	_____
FW-151	HCV-1105 Outlet Isolation	Locked Open	_____
FW-169	HCV-1384 Inlet Isolation	Locked Open	_____
HCV-1384	AFW/MFW Cross Connect Valve	Normal/Closed	_____
FW-170	HCV-1384 Outlet Isolation	Locked Open	_____
FW-190	FCV-1102 Inlet Isolation	Locked Open	_____
FW-191	HCV-1106 Inlet Isolation	Locked Open	_____
FW-192	HCV-1106 Outlet Isolation	Locked Open	_____
HCV-1107A	AFW to S/G A Isolation	Auto/Closed	_____
HCV-1107B	AFW to S/G A Isolation	Auto/Closed	_____
HCV-1108A	AFW to S/G B Isolation	Auto/Closed	_____

Table 7.1 (Continued)

Component #	Component Name	Required Position	Actual Position
HCV-1108B	AFW to S/G B Isolation	Auto/Closed	_____
FW-1275	Emergency Makeup to EFWT from Fire System	Open	_____
FW-661	LCV-1173 Inlet Isolation	Open	_____
FW-662	LCV-1173 Outlet Isolation	Open	_____
FW-663	LCV-1173 Bypass Isolation	Closed	_____
FW-1317	LCV-1173 Bypass Isolation	Closed	_____
FW-652	LCV-1189 Inlet Isolation	Open	_____
FW-653	LCV-1189 Outlet Isolation	Closed	_____
FW-654	LCV-1189 Bypass Isolation	Closed	_____
YCV-1045A	TDAFW Pump Steam Supply	Normal/Closed	_____
YCV-1045B	TDAFW Pump Steam Supply	Normal/Closed	_____
YCV-1045	TDAFW Pump Steam Stop Valve	After Stop/ Closed	_____
FW-161	Piping Upstream of Check Valve	< 260°F	_____
FW-162	Piping Upstream of Check Valve	< 260°F	_____
FW-163	Piping Upstream of Check Valve	< 260°F	_____
FW-164	Piping Upstream of Check Valve	< 260°F	_____
FW-1334	Piping Upstream of Check Valve	< 260°F	_____
FW-173	Piping Upstream of Check Valve	< 260°F	_____
FW-174	Piping Upstream of Check Valve	< 260°F	_____

\*Valve may be closed if MDAFW Pump is feeding S/Gs.

## 4 Generic Risk Insights from PRAs

PRAs for 13 PWRs were analyzed to identify risk-important accident sequences involving loss of AFW, and to identify and risk-prioritize the component failure modes involved. The results of this analysis are described in this section. They are consistent with results reported by INEL and BNL (Gregg et al 1988, and Travis et al, 1988).

### 4.1 Risk Important Accident Sequences Involving AFW System Failure

#### Loss of Power System

- A loss of offsite power is followed by failure of AFW and failure of feed and bleed, resulting in core damage.
- A station blackout fails all AC power except Vital AC from DC invertors, and all decay heat removal systems except the turbine-driven AFW pump. AFW system operation is subsequently impacted by loss of instrumentation or hardware failures, resulting in core damage.
- A DC bus fails, causing a trip and failure of the power conversion system. One AFW motor-driven pump is failed by the bus loss, AFW is subsequently lost completely due to other failures. Feed-and-bleed cooling fails, resulting in core damage.

#### Transient-Caused Reactor or Turbine Trip

- A transient-caused trip is followed by a loss of MFW and AFW. Feed-and-bleed cooling fails either due to failure of the operator to initiate it, or due to hardware failures, resulting in core damage.

#### Loss of Main Feedwater

- A feedwater line break drains the common water source for MFW and AFW. The operators fail to provide feedwater from other sources, and fail to initiate feed-and-bleed cooling, resulting in core damage.

- A loss of main feedwater trips the plant, and AFW fails due to operator error and hardware failures. The operators fail to initiate feed-and-bleed cooling, resulting in core damage.

#### Steam Generator Tube Rupture (SGTR)

- A SGTR is followed by failure of AFW. Coolant is lost from the primary until the refueling water storage tank (RWST) is depleted. High pressure injection (HPI) fails since recirculation cannot be established from the empty sump, and core damage results.

### 4.2 Risk Important Component Failure Modes

The generic component failure modes identified from PRA analyses as important to AFW system failure are listed below in decreasing order of risk importance.

- (1) Turbine-Driven Pump Failure to Start or Run.
- (2) Motor-Driven Pump Failure to Start or Run.
- (3) TDP or MDP Unavailable due to Test or Maintenance.
- (4) AFW System Valve Failures
  - steam admission valves
  - trip and throttle valve
  - flow control valves
  - pump discharge valves
  - pump suction valves
  - valves in testing or maintenance.
- (5) Supply/Suction Sources

## Generic Risk

- condensate storage tank stop valves
- hot well inventory
- suction valves
- Service Water System

In addition to individual hardware, circuit, or instrument failures, each of these failure modes may result

from common causes and human errors. Common cause failures of AFW pumps are particularly risk important. Valve failures are somewhat less important due to the multiplicity of steam generators and connection paths. Human errors of greatest risk importance involve: failures to initiate or control system operation when required; failure to restore proper system lineup after maintenance or testing; and failure to switch to alternate sources when required.

## 5 Failure Modes Determined From Operating Experience

This section describes the primary root causes of AFW system component failures, as determined from a review of operating histories at Fort Calhoun and at other PWRs throughout the nuclear industry. Section 5.1 describes experience at Fort Calhoun, from 1974 to 1991. Section 5.2 summarizes information compiled from a variety of NRC sources, including AEOD analyses and reports, information notices, inspection and enforcement bulletins, and generic letters, and from a variety of INPO reports as well. Some LERs and NPRDS event descriptions were also reviewed. Finally, information was included from reports of NRC-sponsored studies of the effects of plant aging, which include quantitative analysis of AFW system failure reports. This information was used to identify the various root causes expected for the broad PRA-based failure events identified in Section 4.0, resulting in the inspection guidelines presented in Section 3.0.

### 5.1 Fort Calhoun Experience

The AFW system at Fort Calhoun has experienced approximately 20 significant equipment failures in the events examined. These include failures of the AFW pumps, the pump discharge level control valves to steam generators, and system check valves. Failure modes include electrical, instrumentation, hardware failures, and human errors.

#### 5.1.1 AFW Pump Control Logic, Instrumentation and Electrical Failures

There have been eight failures of the AFW pumps to start and/or run properly experienced since 1974. These have resulted from failures of governor speed control linkages, flow transmitters or other pump related failures. The failure causes are mechanical wear, corrosion, or inadequate preventative maintenance procedures. Failure of the turbine-driven pump to stop following a surveillance was caused by a blown fuse which stopped the steam admission valve from closing.

#### 5.1.2 Failure of AFW Pump Discharge Flow Control Valve to Steam Generator

There have been two failures of the pump discharge flow control valves since 1974. These have resulted from normal wear of valve internals allowing excessive leakage.

#### 5.1.3 AFW Valve Failures

Since 1974 there have been four events involving AFW valve failures resulting in excessive leakage. Included in this category are a check valve, a manual gate valve, and air operated globe valves. The failure cause in all cases was normal wear of valve internals.

#### 5.1.4 Human Errors

Two cases relating directly to human error affecting the AFW system were found in the events examined. One case involved inadvertent actuation of the AFW system during operation when an operator mispositioned a control switch during the performance of a surveillance. The other case involved improperly setting a torque switch which caused improper valve operation. Contributing factors leading to the human error were identified as inadequate control switch labeling and improper test conditions for setting the torque switch.

### 5.2 Industry Wide Experience

Human errors, design/engineering problems and errors, and component failures are the primary root causes of AFW System failures identified in a review of industry wide system operating history. Common cause failures, which disable more than one train of this operationally redundant system, are highly risk significant, and can result from all of these causes.

This section identifies important common cause failure modes, and then provides a broader discussion of the



single failure effects of human errors, design/engineering problems and errors, and component failures. Paragraphs presenting details of these failure modes are coded (e.g., CC1) and cross-referenced by inspection items in Section 3.0.

### 5.2.1 Common Cause Failures

The dominant cause of AFW system multiple-train failures has been human error. Design/engineering errors and component failures have been less frequent, but nevertheless significant, causes of multiple train failures.

CC1. Human error in the form of incorrect operator intervention into automatic AFW system functioning during transients resulted in the temporary loss of all safety-grade AFW pumps during events at Davis Besse (NUREG-1154, 1985) and Trojan (AEO 7/T416, 1983). In the Davis Besse event, improper manual initiation of the steam and feedwater rupture control system (SFRCS) led to overspeed tripping of both turbine-driven AFW pumps, probably due to the introduction of condensate into the AFW turbines from the long, unheated steam supply lines. (The system had never been tested with the abnormal, cross-connected steam supply lineup which resulted.) In the Trojan event the operator incorrectly stopped both AFW pumps due to misinterpretation of MFW pump speed indication. The diesel driven pump would not restart due to a protective feature requiring complete shutdown, and the turbine-driven pump tripped on overspeed, requiring local reset of the trip and throttle valve. In cases where manual intervention is required during the early stages of a transient, training should emphasize that actions should be performed methodically and deliberately to guard against such errors.

CC2. Valve mispositioning has accounted for a significant fraction of the human errors failing multiple trains of AFW. This includes closure of normally open suction valves or steam supply valves, and of isolation valves to sensors having control functions. Incorrect handswitch positioning and inadequate temporary wiring changes have also prevented automatic starts of multiple pumps. Factors identified in studies of mispositioning errors include failure to add newly installed valves to valve checklists, weak administrative control of tagging, restoration, independent verification, and locked valve

logging, and inadequate adherence to procedures. Illegible or confusing local valve labeling, and insufficient training in the determination of valve position may cause or mask mispositioning, and surveillance which does not exercise complete system functioning may not reveal mispositionings.

CC3. At ANO-2, both AFW pumps lost suction due to steam binding when they were lined up to both the EFWT and the hot startup/blowdown demineralizer effluent (AEOD/C404, 1984). At Zion-1 steam created by running the turbine-driven pump deadheaded for one minute caused trip of a motor-driven pump sharing the same inlet header, as well as damage to the turbine-driven pump (Region 3 Morning Report, 1/17/90). Both events were caused by procedural inadequacies.

CC4. Design/engineering errors have accounted for a smaller, but significant fraction of common cause failures. Problems with control circuit design modifications at Farley defeated AFW pump auto-start on loss of main feedwater. At Zion-2, restart of both motor driven pumps was blocked by circuit failure to de-energize when the pumps had been tripped with an automatic start signal present (IN 82-01, 1982). In addition, AFW control circuit design reviews at Salem and Indian Point have identified designs where failures of a single component could have failed all or multiple pumps (IN 87-34, 1987).

CC5. Incorrect setpoints and control circuit settings resulting from analysis errors and failures to update procedures have also prevented pump start and caused pumps to trip spuriously. Errors of this type may remain undetected despite surveillance testing, unless surveillance tests model all types of system initiation and operating conditions. A greater fraction of instrumentation and control circuit problems has been identified during actual system operation (as opposed to surveillance testing) than for other types of failures.

CC6. On two occasions at a foreign plant, failure of a balance-of-plant inverter caused failure of two AFW pumps. In addition to loss of the motor driven pump whose auxiliary start relay was powered by the inverter, the turbine driven pump tripped on overspeed because the governor valve opened, allowing full steam flow to the turbine. This illustrates the importance of assessing

the effects of failures of balance of plant equipment which supports the operation of critical components. The instrument air system is another example of such a system.

CC7. Multiple AFW pump trips have occurred at Millstone-3, Cook-1, Trojan and Zion-2 (IN 87-53, 1987) caused by brief, low pressure oscillations of suction pressure during pump startup. These oscillations occurred despite the availability of adequate static NPSH. Corrective actions taken include: extending the time delay associated with the low pressure trip, removing the trip, and replacing the trip with an alarm and operator action.

CC8. Design errors discovered during AFW system re-analysis at the Robinson plant (IN 89-30, 1989) and at Millstone-1 resulted in the supply header from the EFWT being too small to provide adequate NPSH to the pumps if more than one of the three pumps were operating at rated flow conditions. This could lead to multiple pump failure due to cavitation. Subsequent reviews at Robinson identified a loss of feedwater transient in which inadequate NPSH and flows less than design values had occurred, but which were not recognized at the time. Event analysis and equipment trending, as well as surveillance testing which duplicates service conditions as much as is practical, can help identify such design errors.

CC9. Asiatic clams caused failure of two AFW flow control valves at Catawba-2 when low suction pressure caused by starting of a motor-driven pump caused suction source realignment to the Nuclear Service Water system. Pipes had not been routinely treated to inhibit clam growth, nor regularly monitored to detect their presence, and no strainers were installed. The need for surveillance which exercises alternative system operational modes, as well as complete system functioning, is emphasized by this event. Spurious suction switchover has also occurred at Callaway and at McGuire, although no failures resulted.

CC10. Common cause failures have also been caused by component failures (AEOD/C404, 1984). At Surry-2, both the turbine driven pump and one motor driven pump were declared inoperable due to steam binding caused by leakage of hot water through multiple check valves. At Robinson-2 both motor driven pumps were

found to be hot, and both motor and steam driven pumps were found to be inoperable at different times. Backleakage at Robinson-2 passed through closed motor-operated isolation valves in addition to multiple check valves. At Farley, both motor and turbine driven pump casings were found hot, although the pumps were not declared inoperable. In addition to multi-train failures, numerous incidents of single train failures have occurred, resulting in the designation of "Steam Binding of Auxiliary Feedwater Pumps" as Generic Issue 93. This generic issue was resolved by Generic Letter 88-03 (Miraglia, 1988), which required licensees to monitor AFW piping temperatures each shift, and to maintain procedures for recognizing steam binding and for restoring system operability.

CC11. Common cause failures have also failed motor operated valves. During the total loss of feedwater event at Davis Besse, the normally-open AFW isolation valves failed to open after they were inadvertently closed. The failure was due to improper setting of the torque switch bypass switch, which prevents motor trip on the high torque required to unseat a closed valve. Previous problems with these valves had been addressed by increasing the torque switch trip setpoint - a fix which failed during the event due to the higher torque required due to high differential pressure across the valve. Similar common mode failures of MOVs have also occurred in other systems, resulting in issuance of Generic Letter 89-10, "Safety Related Motor-Operated Valve Testing and Surveillance (Partlow, 1989)." This generic letter requires licensees to develop and implement a program to provide for the testing, inspection and maintenance of all safety-related MOVs to provide assurance that they will function when subjected to design basis conditions.

CC12. Other component failures have also resulted in AFW multi-train failures. These include out-of-adjustment electrical flow controllers resulting in improper discharge valve operation, and a failure of oil cooler cooling water supply valves to open due to silt accumulation.

### 5.2.2 Human Errors

HE1. The overwhelmingly dominant cause of problems identified during a series of operational readiness

evaluations of AFW systems was human performance. The majority of these human performance problems resulted from incomplete and incorrect procedures, particularly with respect to valve lineup information. A study of valve mispositioning events involving human error identified failures in administrative control of tagging and logging, procedural compliance and completion of steps, verification of support systems, and inadequate procedures as important. Another study found that valve mispositioning events occurred most often during maintenance, calibration, or modification activities. Insufficient training in determining valve position, and in administrative requirements for controlling valve positioning were important causes, as was oral task assignment without task completion feedback.

HE2. Turbine driven pump failures have been caused by human errors in calibrating or adjusting governor speed control, poor governor maintenance, incorrect adjustment of governor valve and overspeed trip linkages, and errors associated with the trip and throttle valve. TTV-associated errors include physically bumping it, failure to restore it to the correct position after testing, and failures to verify control room indication of TTV position following actuation.

HE3. Motor driven pumps have been failed by human errors in mispositioning handswitches, and by procedure deficiencies.

### 5.2.3 Design/Engineering Problems and Errors

DE1. As noted above, the majority of AFW subsystem failures, and the greatest relative system degradation, has been found to result from turbine-driven pump failures. Overspeed trips of Terry turbines controlled by Woodward governors have been a significant source of these failures (AEOD/C602, 1986). In many cases these overspeed trips have been caused by slow response of a Woodward Model EG governor on startup, at plants where full steam flow is allowed immediately. This oversensitivity has been removed by installing a startup steam bypass valve which opens first, allowing a controlled turbine acceleration and buildup of oil pressure to control the governor valve when full steam flow is admitted.

DE2. Overspeed trips of Terry turbines have been caused by condensate in the steam supply lines. Condensate slows down the turbine, causing the governor valve to open farther, and overspeed results before the governor valve can respond, after the water slug clears. This was determined to be the cause of the loss-of-all-AFW event at Davis Besse (AEOD/602, 1986), with condensation enhanced due to the long length of the cross-connected steam lines. Repeated tests following a cold-start trip may be successful due to system heat up.

DE3. Turbine trip and throttle valve (TTV) problems are a significant cause of turbine driven pump failures (IN 81-66). In some cases lack of TTV position indication in the control room prevented recognition of a tripped TTV. In other cases it was possible to reset either the overspeed trip or the TTV without resetting the other. This problem is compounded by the fact that the position of the overspeed trip linkage can be misleading, and the mechanism may lack labels indicating when it is in the tripped position (AEOD/C602, 1986).

DE4. Startup of turbines with Woodward Model PG-PL governors within 30 minutes of shutdown has resulted in overspeed trips when the speed setting knob was not exercised locally to drain oil from the speed setting cylinder. Speed control is based on startup with an empty cylinder. Problems have involved turbine rotation due to both procedure violations and leaking steam. Terry has marketed two types of dump valves for automatically draining the oil after shutdown (AEOD/C602, 1986).

At Calvert Cliffs, a 1987 loss-of-offsite-power event required a quick, cold startup that resulted in turbine trip due to PG-PL governor stability problems. The short-term corrective action was installation of stiffer buffer springs (IN 88-09, 1988). Surveillance had always been preceded by turbine warmup, which illustrates the importance of testing which duplicates service conditions as much as is practical.

DE5. Reduced viscosity of gear box oil heated by prior operation caused failure of a motor driven pump to start due to insufficient lube oil pressure. Lowering the pressure switch setpoint solved the problem, which had not been detected during testing.

DE6. Waterhammer at Palisades resulted in AFW line and hanger damage at both steam generators. The AFW spargers are located at the normal steam generator level, and are frequently covered and uncovered during level fluctuations. Waterhammers in top-feed-ring steam generators resulted in main feedline rupture at Maine Yankee and feedwater pipe cracking at Indian Point-2 (IN 84-32, 1984).

DE7. Manually reversing the direction of motion of an operating valve has resulted in MOV failures where such loading was not considered in the design (AEOD/C603, 1986). Control circuit design may prevent this, requiring stroke completion before reversal.

DE8. At each of the units of the South Texas Project, space heaters provided by the vendor for use in pre-installation storage of MOVs were found to be wired in parallel to the Class 1E 125 V DC motors for several AFW valves (IR 50-489/89-11; 50-499/89-11, 1989). The valves had been environmentally qualified, but not with the non-safety-related heaters energized.

#### 5.2.4 Component Failures

Generic Issue ILE.6.1, "In Situ Testing Of Valves" was divided into four sub-issues (Beckjord, 1989), three of which relate directly to prevention of AFW system component failure. At the request of the NRC, in-situ testing of check valves was addressed by the nuclear industry, resulting in the EPRI report, "Application Guidelines for Check Valves in Nuclear Power Plants (Brooks, 1988)." This extensive report provides information on check valve applications, limitations, and inspection techniques. In-situ testing of MOVs was addressed by Generic Letter 89-10, "Safety Related Motor-Operated Valve Testing and Surveillance" (Partlow, 1989) which requires licensees to develop and implement a program for testing, inspection and maintenance of all safety-related MOVs. "Thermal Overload Protection for Electric Motors on Safety-Related Motor-Operated Valves - Generic Issue ILE.6.1 (Rothberg, 1988)" concludes that valve motors should be thermally protected, yet in a way which emphasizes system function over protection of the operator.

CF1. The common-cause steam binding effects of check valve leakage were identified in Section 5.2.1, entry CC10. Numerous single-train events provide additional insights into this problem. In some cases leakage of hot MFW past multiple check valves in series has occurred because adequate valve-seating pressure was limited to the valves closest to the steam generators (AEOD/C404, 1984). At Robinson, the pump shutdown procedure was changed to delay closing the MOVs until after the check valves were seated. At Farley, check valves were changed from swing type to lift type. Check valve rework has been done at a number of plants. Different valve designs and manufacturers are involved in this problem, and recurring leakage has been experienced, even after repair and replacement.

CF2. At Robinson, heating of motor operated valves by check valve leakage has caused thermal binding and failure of AFW discharge valves to open on demand. At Davis Besse, high differential pressure across AFW injection valves resulting from check valve leakage has prevented MOV operation (AEOD/C603, 1986).

CF3. Gross check valve leakage at McGuire and Robinson caused overpressurization of the AFW suction piping. At a foreign PWR it resulted in a severe waterhammer event. At Palo Verde-2 the MFW suction piping was overpressurized by check valve leakage from the AFW system (AEOD/C404, 1984). Gross check valve leakage through idle pumps represents a potential diversion of AFW pump flow.

CF4. Roughly one third of AFW system failures have been due to valve operator failures, with about equal failures for MOVs and AOVs. Almost half of the MOV failures were due to motor or switch failures (Casada, 1989). An extensive study of MOV events (AEOD/C603, 1986) indicates continuing inoperability problems caused by: torque switch/limit switch settings, adjustments, or failures; motor burnout; improper sizing or use of thermal overload devices; premature degradation related to inadequate use of protective devices; damage due to misuse (valve throttling, valve operator hammering); mechanical problems (loosened parts, improper assembly); or the torque switch bypass circuit improperly installed or adjusted. The study concluded that current

## Failure Modes

methods and procedures at many plants are not adequate to assure that MOVs will operate when needed under credible accident conditions. Specifically, a surveillance test which the valve passed might result in undetected valve inoperability due to component failure (motor burnout, operator parts failure, stem disc separation) or improper positioning of protective devices (thermal overload, torque switch, limit switch). Generic Letter 89-10 (Partlow, 1989) has subsequently required licensees to implement a program ensuring that MOV switch settings are maintained so that the valves will operate under design basis conditions for the life of the plant.

CF5. Component problems have caused a significant number of turbine driven pump trips (AEOD/C602, 1986). One group of events involved worn tappet nut faces, loose cable connections, loosened set screws, improperly latched TTVs, and improper assembly. Another involved oil leaks due to component or seal failures, and oil contamination due to poor maintenance activities. Governor oil may not be shared with turbine lubrication oil, resulting in the need for separate oil changes. Electrical component failures included transistor or resistor failures due to moisture intrusion, erroneous grounds and connections, diode failures, and a faulty circuit card.

CF6. Electrohydraulic-operated discharge valves have performed very poorly, and three of the five units using them have removed them due to recurrent failures. Failures included oil leaks, contaminated oil, and hydraulic pump failures.

CF7. Control circuit failures were the dominant source of motor driven AFW pump failures (Casada, 1989). This includes the controls used for automatic and manual starting of the pumps, as opposed to the instrumentation inputs. Most of the remaining problems were due to circuit breaker failures.

CF8. "Hydraulic lockup" of Limitorque SMB spring packs has prevented proper spring compression to actuate the MOV torque switch, due to grease trapped

in the spring pack. During a surveillance at Trojan, failure of the torque switch to trip the TTV motor resulted in tripping of the thermal overload device, leaving the turbine driven pump inoperable for 40 days until the next surveillance (AEOD/E702, 1987). Problems result from grease changes to EXXON NEBULA EP-0 grease, one of only two greases considered environmentally qualified by Limitorque. Due to lower viscosity, it slowly migrates from the gear case into the spring pack. Grease changeover at Vermont Yankee affected 40 of the older MOVs of which 32 were safety related. Grease relief kits are needed for MOV operators manufactured before 1975. At Limerick, additional grease relief was required for MOVs manufactured since 1975. MOV refurbishment programs may yield other changeovers to EP-0 grease.

CF9. For AFW systems using air operated valves, almost half of the system degradation has resulted from failures of the valve controller circuit and its instrument inputs (Casada, 1989). Failures occurred predominantly at a few units using automatic electronic controllers for the flow control valves, with the majority of failures due to electrical hardware. At Turkey Point-3, controller malfunction resulted from water in the Instrument Air system due to maintenance inoperability of the air dryers.

CF10. For systems using diesel driven pumps, most of the failures were due to start control and governor speed control circuitry. Half of these occurred on demand, as opposed to during testing (Casada, 1989).

CF11. For systems using AOVs, operability requires the availability of Instrument Air (IA), backup air, or backup nitrogen. However, NRC Maintenance Team Inspections have identified inadequate testing of check valves isolating the safety-related portion of the IA system at several utilities (Letter, Roe to Richardson). Generic Letter 88-14 (Miraglia, 1988), requires licensees to verify by test that air-operated safety-related components will perform as expected in accordance with all design-basis events, including a loss of normal IA.

## 6 References

Beckjord, F. S. June 30, 1989. *Closeout of Generic Issue II.E.6.1, "In Situ Testing of Valves."* Letter to V. Stello, Jr., U.S. Nuclear Regulatory Commission, Washington, D.C.

Brooks, B. P. 1988. *Application Guidelines for Check Valves in Nuclear Power Plants.* NP-5479, Electric Power Research Institute, Palo Alto, California.

Casada, D. A. 1989. *Auxiliary Feedwater System Aging Study. Volume 1. Operating Experience and Current Monitoring Practices.* NUREG/CR-5404. U.S. Nuclear Regulatory Commission, Washington, D.C.

Gregg, R. E. and R. E. Wright. 1988. *Appendix Review for Dominant Generic Contributors.* BLB-31-88. Idaho National Engineering Laboratory, Idaho Falls, Idaho.

Miraglia, F. J. February 17, 1988. *Resolution of Generic Safety Issue 93, "Steam Binding of Auxiliary Feedwater Pumps" (Generic Letter 88-03).* U.S. Nuclear Regulatory Commission, Washington, D.C.

Miraglia, F. J. August 8, 1988. *Instrument Air Supply System Problem: Affecting Safety-Related Equipment (Generic Letter 88-14).* U.S. Nuclear Regulatory Commission, Washington, D.C.

Partlow, J. G. June 28, 1989. *Safety-Related Motor-Operated Valve Testing and Surveillance (Generic Letter 89-10).* U.S. Nuclear Regulatory Commission, Washington, D.C.

Rothberg, O. June 1988. *Thermal Overload Protection for Electric Motors on Safety-Related Motor-Operated Valves - Generic Issue II.E.6.1.* NUREG-1296. U.S. Nuclear Regulatory Commission, Washington, D.C.

Travis, R. and J. Taylor. 1989. *Development of Guidance for Generic, Functionally Oriented PRA-Based Team Inspections for BWR Plants - Identification of Risk-Important Systems, Components and Human Actions.* TLR-A-3874-TGA Brookhaven National Laboratory, Upton, New York.

### AEOD Reports

AEOD/C404. W. D. Lanning. July 1984. *Steam Binding of Auxiliary Feedwater Pumps.* U.S. Nuclear Regulatory Commission, Washington, D.C.

AEOD/C602. C. Hsu. August 1986. *Operational Experience Involving Turbine Overspeed Trips.* U.S. Nuclear Regulatory Commission, Washington, D.C.

AEOD/C603. E. J. Brown. December 1986. *A Review of Motor-Operated Valve Performance.* U.S. Nuclear Regulatory Commission, Washington, D.C.

AEOD/E702. E. J. Brown. March 19, 1987. *MOV Failure Due to Hydraulic Lockup From Excessive Grease in Spring Pack.* U.S. Nuclear Regulatory Commission, Washington, D.C.

AEOD/T416. January 22, 1983. *Loss of ESF Auxiliary Feedwater Pump Capability at Trojan on January 22, 1983.* U.S. Nuclear Regulatory Commission, Washington, D.C.

### Information Notices

IN 82-01. January 22, 1982. *Auxiliary Feedwater Pump Lockout Resulting from Westinghouse W-2 Switch Circuit Modification.* U.S. Nuclear Regulatory Commission, Washington, D.C.

IN 84-32. E. L. Jordan. April 18, 1984. *Auxiliary Feedwater Sparger and Pipe Hangar Damage.* U.S. Nuclear Regulatory Commission, Washington, D.C.

IN 84-66. August 17, 1984. *Undetected Unavailability of the Turbine-Driven Auxiliary Feedwater Train.* U.S. Nuclear Regulatory Commission, Washington, D.C.

IN 87-34. C. E. Rossi. July 24, 1987. *Single Failures in Auxiliary Feedwater Systems.* U.S. Nuclear Regulatory Commission, Washington, D.C.

## References

IN 87-53. C. E. Rossi. October 20, 1987. *Auxiliary Feedwater Pump Trips Resulting from Low Suction Pressure*. U.S. Nuclear Regulatory Commission, Washington, D.C.

IN 88-09. C. E. Rossi. March 18, 1988. *Reduced Reliability of Steam-Driven Auxiliary Feedwater Pumps Caused by Instability of Woodward PG-PL Type Governors*. U.S. Nuclear Regulatory Commission, Washington, D.C.

IN 89-30. R. A. Azua. August 16, 1989. *Robinson Unit 2 Inadequate NPSH of Auxiliary Feedwater Pumps*. Also, Event Notification 16375, August 22, 1989. U.S. Nuclear Regulatory Commission, Washington, D.C.

## Inspection Report

IR 50-489/89-11; 50-499/89-11. May 26, 1989. *South Texas Project Inspection Report*. U.S. Nuclear Regulatory Commission, Washington, D.C.

## NUREG Report

NUREG-1154. 1985. *Loss of Main and Auxiliary Feedwater Event at the Davis Besse Plant on June 9, 1985*. U.S. Nuclear Regulatory Commission, Washington, D.C.

## Distribution

<u>No. of Copies</u>		<u>No. of Copies</u>	
	<u>OFFSITE</u>	4	<u>Fort Calhoun Resident Inspector Office</u>
	<u>U.S. Nuclear Regulatory Commission</u>		J. H. Taylor Brookhaven National Laboratory Bldg. 130 Upton, NY 11973
	B. K. Grimes OWFN 9 A2		R. Travis Brookhaven National Laboratory Bldg. 130 Upton, NY 11973
	F. Congel OWFN 10 E2		R. Gregg EG&G Idaho, Inc. P.O. Box 1625 Idaho Falls, ID 83415
	A. C. Thadani OWFN 8 E2		Dr. D. R. Edwards Prof. of Nuclear Engineering University of Missouri - Rolla Rolla, MO 65401
	S. D. Bloom OWFN 13 H3		
	S. M. Long OWFN 10 E4		
	G. M. Holahan OWFN 8 E2		
	J. Chung OWFN 10 E4		
	M. J. Virgilo OWFN 13 E4		
2	B. Thomas OWFN 12 H26		
	<u>U.S. Nuclear Regulatory Commission - Region 4</u>		
	A. B. Beach L. J. Callan S. J. Collins T. F. Westerman		
			<u>ONSITE</u>
		23	<u>Pacific Northwest Laboratory</u>
			S. R. Doctor L. R. Dodd B. F. Gore (10) N. E. Maguire-Moffitt B. D. Shipp F. A. Simonen T. A. Vehc T. V. Vo Publishing Coordination Technical Report File (5)



**BIBLIOGRAPHIC DATA SHEET**

(See instructions on the reverse)

1. REPORT NUMBER  
(Assigned by NRC, Add Vol., Supp., Rev.,  
and Addendum Numbers, if any.)

NUREG/CR-5834  
PNL-7906

2. TITLE AND SUBTITLE

Auxiliary Feedwater System Risk-Based Inspection Guide for the  
Port Calhoun Nuclear Power Plant

3. DATE REPORT PUBLISHED

MONTH YEAR

February 1993

4. FIN OR GRANT NUMBER

L1310

5. AUTHOR(S)

N. E. Moffitt, B. F. Gore, T. E. Vehec, T. V. Vo

6. TYPE OF REPORT

Technical

7. PERIOD COVERED (Inclusive Dates)

9/91 to 12/92

8. PERFORMING ORGANIZATION - NAME AND ADDRESS (If NRC, provide Division, Office or Region, U.S. Nuclear Regulatory Commission, and mailing address; if contractor, provide name and mailing address.)

Pacific Northwest Laboratory  
Richland, WA 99352

9. SPONSORING ORGANIZATION - NAME AND ADDRESS (If NRC, type "Same as above"; if contractor, provide NRC Division, Office or Region, U.S. Nuclear Regulatory Commission, and mailing address.)

Division of Systems Safety and Analysis  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

10. SUPPLEMENTARY NOTES

11. ABSTRACT (200 words or less)

In a study sponsored by the U.S. Nuclear Regulatory Commission (NRC), Pacific Northwest Laboratory has developed and applied a methodology for deriving plant-specific risk-based inspection guidance for the auxiliary feedwater (AFW) system at pressurized water reactors that have not undergone probabilistic risk assessment (PRA). This methodology uses existing PRA results and plant operating experience information. Existing PRA-based inspection guidance information recently developed for the NRC for various plants was used to identify generic component failure modes. This information was then combined with plant-specific and industry-wide component information and failure data to identify failure modes and failure mechanisms for the AFW system at the selected plants. Fort Calhoun was selected as the sixth plant for study. The product of this effort is a prioritized listing of AFW failures which have occurred at the plant and at other PWRs. This listing is intended for use by NRC inspectors in the preparation of inspection plans addressing AFW risk-important components at the Fort Calhoun plant.

12. KEY WORDS/DESCRIPTORS (List words or phrases that will assist researchers in locating the report.)

Inspection, Risk, PRA, Ft. Calhoun, Auxiliary Feedwater (AFW)

13. AVAILABILITY STATEMENT

Unlimited

14. SECURITY CLASSIFICATION

(This Page)

Unclassified

(This Report)

Unclassified

15. NUMBER OF PAGES

16. PRICE



Federal Recycling Program

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D.C. 20555-0001

FIRST CLASS MAIL  
POSTAGE AND FEES PAID  
USNRC  
PERMIT NO. G-67

OFFICIAL BUSINESS  
PENALTY FOR PRIVATE USE, \$300

120555139531 1 JAN 1993  
US NRC-CAOM  
CIV FOIA & PUBLICATIONS SVCS  
TDS-PDR-NUREG  
F-211  
WASHINGTON DC 20555