NRC F((5-92)	DRM 358	RM 355 U.S. NUCLEAR REGULATORY COMMISSION								APPROVED BY OMB ND. 3150-0104 EXPIRES 5/31/95							
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST BOO HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MINBB 7714), U.S. NUCLEAR REQULATORY DOMMISSION, WASHINGTON, DC 2055-0001, AND TO THE PARERWORK REDUCTION PROJECT (\$150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.									
FACILITY NAME (1)								DOCKET NUMBER (2)									
Perry Nuclear Power Plant, Unit 1								05000 440				110	F4				
TITLE (4)	Fail	lure t	to Per	form Enginee nical Specif	erin fica	g Eva tion	luation Violati	n of ion	Inope	erable	Snubh	ers					
EVE	NT DATE	(5)	LER NUMBER (6)				REPORT NUMBER (7)			1	OTHER FACILITIES INVOLVED (8				(8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	R	EVISION	MONTH	DAY	YEAR	FACILITY	NAME			DOCKET NUMBER 05000			
02	18	93	93	- 007		00	03	19	93	FACILITY	NAME			DOCKET NUMBER 05000			
OPER	ATING	a and shares	THIS R	EPORT IS SUBMIT	TTED	PURSU	ANT TO TH	E REQ	UIREM	ENTS OF	10 CFR	5: (Ch	eck one or i	more)	(11)		
MOI	DE (9)	5	20.402(b)				20.405(c)				50.73(a)(2)(iv)				73.71(b)		
PO	WER		20.405(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)		
LEVE	L (10)	0	20.405(a)(1)(ii)				50 36(c)(2)				50.73(a)(2)(vii)			OTHER			
			20.405(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)			(Specify in Abstract			
				20.405(a)(1)(tv)				50.73(a)(2)(ii)			50.73 (a		1)(2)(viii)(B)		Form 366A)		
			20.405(a)(1)(v)				50.73(a)(2)(iii)			50.73(a)(2)(x)							
					LICE	NSEE C	ONTACT F	OR TH	IS LER	(12)					ALCONTANT AND ADDRESS	Add Table 11 had a second	
NAME										TELEPHONE NUMBER (Include Area Code)							
Ron W. Gaston, Compliance Engineer Extension							5004	1	(216	5) 25	9-3737						
			COMPL	ETE ONE LINE FO	R EA	CH COI	MPONENT	FAILUF	RE DESI	CRIBED I	N THIS P	EPOR	T (13)				
CAUSE	SYSTEM	сом	PONENT	MANUFACTURER	REPORTABLE TO NPROS				CAUSE	SYSTEM	COMPO	MENT	MANUFACTU	IRER	REPORT TO NP	ABLE	
	water and the d		S	UPPLEMENTAL R	EPOR	T EXPE	CTED (14)				1	EX	PECTED	MON	H DAY	YEAR	
VES (# yes, complete EXPECTED SUBMISSION DATE)					NO				SUBMISSION DATE (15)								
ABSTR	ACT (Lir	nit to 14	00 space	s, i.e., approximate	ly 15 s	ingle-sp	1 aced types	witten li	nes) (1	6)			112 (12)	1	_	1	

On February 18, 1993 while performing an evaluation in response to previously initiated nonconformance reports (NRs), it was determined that certain inoperable snubbers which were the subject of the NRs may have been inoperable since January 1991. This hypothesis was supported by a minor Reactor Pressure Vessel (RPV) level offset for the instrument channel associated with the inoperable snubbers.

The mechanical snubber failures were attributed to dried out lubricant resulting from exposure to elevated temperatures in the upper drywell area. The failed snubbers were subsequently replaced. Additional snubbers in the immediate vicinity were stroke tested and found acceptable. Due to a prior occurrence involving elevated drywell temperatures, all mechanical snubbers in the upper drywell area are being monitored to better determine their service life in this environment. All snubbers in this area will have an augmented functional test performed during the next refueling outage (RF0-4).

7303220333	930319
PDR ADOCK	05000440

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB '714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 2055-0001, AND TO THE PAPERWORK REDUCTION PROJECT (2150-0164), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) DOCKET NUMBER (2)			LER NUMBER (6)				
		YEAR	SEQUENTIAL REVISIO NUMBER NUMBER				
Perry Nuclear Power Plant, Unit 1	05000440	93	- 007 -	00	2 ^{OF} 4		

TEXT (Il more space a required, use additional copies of NRC Form 366A) (17)

I. Introduction

NRC FORM 366A

15-82

On February 18, 1993, an evaluation performed in response to a nonconformance report (NR) involving inoperable snubbers determined that the snubbers may have been inoperable since January 1991, as evidenced by a review of anomalous readings within the affected RPV instrumentation channel. This event was considered a violation of the applicable action requirement of Technical Specification 3.7.4, which requires that with one or more snubbers inoperable, the inoperable snubber be restored or replaced within 72 hours and an engineering evaluation be performed on the attached component or the attached system declared inoperable. This event is being reported pursuant to 10 CFR 50.73(a)(2)(i)(B) due to the failure to perform the evaluation at the time the snubbers are presumed to have been inoperable.

At the time of discovery the plant was shutdown for a mid-cycle maintenance outage in Operational Condition 5 (Refueling) with the reactor pressure vessel at atmospheric pressure and reactor water temperature at 108 degrees Fahrenheit.

II. Description

On February 1, 1993, Nonconformance Report (NR) 93-S-033 was written due to a suspected locked-up snubber [SNB] on the sensing line for steam condensing pot 1B21-D004A. The suspect snubber was identified during a walkdown of drywell snubbers which was performed to visually inspect for possible damage resulting from water spray inside the drywell. The water spray originated from refueling bulkhead manway flange leakage identified while raising reactor vessel level.

The PSCO Model PSA-1/4 (1H22H0407) snubber identified in NR 93-S-033 was unpinned and stroke tested. A preliminary evaluation determined that the lubrication in the snubber was dried out. To determine the extent of the problem five additional snubbers at the same general drywell elevation were stroke tested. Two of these snubbers in the immediate vicinity (1H22H0408 and 1H22H0409) also failed the stroke test on February 16, 1993; the other three snubbers tested (1G41H1025, 1H22H0558 and 1H22H2483) had acceptable test results. Two additional NRs 93-S-048 and 93-S-049 were written to document the evaluation and disposition of snubbers 1H22H0408 and 1H22H0409 respectively. Additionally, due to unrelated concerns, seven additional snubbers were stroke tested during the 1993 mid-cycle outage and found to be acceptable.

The three failed snubbers were attached to the sensing line for steam condensing pot 1B21-D004A, which is associated with the Channel A reactor water level instrumentation. The snubbers allow for thermal growth of the level instrument line during plant heatups and cooldowns. Evaluations performed per the respective NRs concluded that the piping stresses remained within the pertinent ASME Code U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED BY OMB NO. 3150-0104 EXPIRES 5/31/95

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REDUEST: 50.0 MRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 2055-0001, AND TO THE PAREFRWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 2053

FACILITY NAME (1)	LER NUMBER (6) PAGE (3)					
		YEAR SEQUENTIAL REVISION NUMBER NUMBER				
Perry Nuclear Power Plant, Unit 1	05000 440	93	- 007 -	00	3 OF 4	

TEXT (II more space is required, use additional copies of NRC Form 3664) (17)

allowables with the snubbers locked-up in their as found position. The piping was also evaluated to be acceptable on an as-is basis for continued service following the maintenance outage.

During the evaluation of NR's 93-S-048 and 93-S-049 a probable link between snubber inoperability and past RPV level instrument reading anomalies was suspected. The trending data from the instrumentation indicated the snubbers in question may have been locked-up since as early as 1991, based on the "A" narrow range instrument reading consistently higher than the other 3 channels. This difference was within the allowable range between channels for these instruments. During plant startup in March of 1993 the previous difference between the channel reading was significantly reduced, thereby confirming the link to the degraded snubber.

III. Cause Analysis

NRC FORM 366A

(5.42)

The three affected snubbers were disassembled after failing their respective stroke tests to determine the failure mechanism. The internal lubricated surfaces within the snubber were coated with dried out lubricant. Based on the fact that there were no visual indications of mechanical defects or damage to the snubbers, the primary cause for the failures was attributed to the dried out lubricant resulting from exposure to elevated ambient temperature conditions.

IV. Similar Events

In April 1989, Licensee Event Report (LER) 89-10 was submitted to report a high temperature condition in the upper drywell area which resulted in heat damage to electrical cables and mechanical snubbers in the affected zone. The high temperature condition was caused by a lack of sufficient refueling bellows insulation. The high temperature condition was improved by installing reflective insulation on the drywell side of the refueling bellows and improving Drywell Cooling System [VB] air flow in the area surrounding the refueling bellows. Additional information regarding the elevated drywell temperature condition identified in 1989 was submitted to the NRC by letter PY-CEI/OIE-0348L and PY-CEI/OIE-0353L, dated April 19, 1989 and July 3, 1989 respectively.

V. Safety Analysis

Condensing chamber 1B21-D004A provides input to the reactor pressure vessel level Channel A instrumentation which includes wide range and narrow range level transmitters. Automatic protective functions associated with these transmitters include a Level 8 (L8) high level trip at 219.5 inches, a L3 low RPV level scram at 177.7 inches and L2 and L1 trips which initiate Emergency Core Cooling System (ECCS) functions.

U.S. NUCLEAR REGULATORY COMMISSION APPROVED BY OMB NO. 3150-0104 NRC FORM 366A EXPIRES 5/31/95 (5-92) ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST, 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT [3150-0104], OFFICE DF L'CENSEE EVENT REPORT (LER) TEXT CONTINUATION MANAGEMENT AND BUDGET, WASHINGTON, DC 20503 DOCKET NUMBER 12 LER NUMBER IN FACILITY NAME (1) PAGE (3) SEQUENTIAL REVISION. YEAR NUMBER NUMBER

Perry Nuclear Power Plant, Unit 1

TEXT (If more space is required, use additional copies of NRC Form 366A) [17]

The setpoints for the reactor vessel level instrument trips are established based on the cold vessel conditions. Actual calibration of the instrumentation is performed based on thermal expansion of the vessel and instrument condensing pots at plant normal operating conditions. This results in added margin incorporated in the setpoints such that protective functions will occur prior to the required setting. The specific margin built into the calibration is 1.5 inches for the Narrow Range L3 settings, 1.0 inch for the Wide Range L1 and L2 settings and 0.8 inches for the the Wide/Narrow Range L8 trip settings. The net effect of the restrained condition of 1B21-D004 was to cause the L8 trip to occur approximately 0.5 inches lower than the indicated level (approximately 219.5 inches) and the L3 and L2/L1 trips to occur approximately 0.9 inches and 0.6 respectively, lower than the corresponding indicated values which is in a non-conservative direction. However, these errors are enveloped by the margin included in the calibration setpoint values.

05000 440

93

007

00

4 OF 4

Since the associated piping stresses were within the pertinent ASME Code allowable values and the condition did not violate the Technical Specification acceptance criteria associated with the affected RPV level instrumentation, this event is not considered to be safety significant.

VI. Corrective Actions

The condensing chamber sensing line snubbers described previously were replaced during the 1993 mid-cycle outage with snubbers of the same type and design. Based on past experience with snubbers exposed to temperatures in the range of 200-205 degrees Fahrenheit (which envelopes the environmental conditions the snubbers experienced), a successful life of two operating cycles is expected. Therefore these snubbers are considered as acceptable for continuous service until at least RF04.

As stated previously, 3 additional snubbers located at the same drywell elevation as the snubber which failed, successfully passed the stroke tests performed as part of the NR 93-S-033 disposition. Seven additional snubbers stroke tested for an unrelated cause during the 1993 Maintenance Outage also successfully passed their respective stroke tests. In total, 13 of the 34 snubbers in the upper drywell population were tested, with the three failures occurring in the same local area. Due to a Technical Specification functional snubber test failure which occurred during RF03, an augmented test plan was developed, which includes functional testing of all upper drywell snubbers. These functional tests are scheduled to be performed during RF04.

Additionally, design modifications made during RFO1 have substantially reduced upper drywell temperatures, thereby improving the service environment for the upper drywell snubbers.

Energy Industry Identification System Codes are identified in the text as [XX].