



Nuclear Group  
P.O. Box 4  
Shippingport, PA 15077-0004

Telephone (412) 393-6000

April 12, 1993  
ND3MNO:3444

Beaver Valley Power Station, Unit No. 2  
Docket No. 50-412, Licensee No. NPF-73  
LER 93-006-00

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

Gentlemen:

In accordance with Appendix A, Beaver Valley Technical Specifications, the following Licensee Event Report is submitted:

LER 93-006-00, 10 CFR 50.73.a.2.iv, "Engineered Safety Feature Components Actuation Due to De-energization of the 1G 4KV Bus."

L. R. Freeland  
General Manager  
Nuclear Operations

DAW/sl

Attachment

150005

9304150031 930412  
PDR ADDCK 05000412  
S PPR

JE22

April 12, 1993  
ND3MNO:3444  
Page 2

cc: Mr. T. T. Martin, Regional Administrator  
United States Nuclear Regulatory Commission  
Region 1  
475 Allendale Road  
King of Prussia, PA 19406

Mr. G. E. Edison, BVPS Licensing Project Manager  
United States nuclear Regulatory Commission  
Washington, DC 20555

Larry Rossbach, Nuclear Regulatory Commission,  
BVPS Senior Resident Inspector

J. A. Holtz, Ohio Edison  
76 S. Main Street  
Akron, OH 44308

Larry Beck  
Centerior Energy  
6200 Oak Tree Blvd.  
Independence, OH 44101-4661

INPO Records Center  
Suite 1500  
1100 Circle 75 Parkway  
Atlanta, GA 30339

Mr. Robert Barkanic  
Department of Environmental Resources  
P.O. Box 2063  
16th Floor, Fulton Building  
Harrisburg, PA 17120

Director, Safety Evaluation & Control  
Virginia Electric & Power Co.  
P.O. Box 26666  
One James River Plaza  
Richmond, VA 23261

W. Hartley  
Virginia Power Company  
5000 Dominion Blvd.  
2SW Glenn Allen, VA 23060

April 12, 1993  
ND3MNO:3444  
Page 3

J. M. Riddle  
Halliburton NUS  
Foster Plaza 7  
661 Anderson Drive  
Pittsburgh, PA 15220

Bill Wegner, Consultant  
23 Woodlawn Terrace  
Fredricksburg, VA 22405

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
Beaver Valley Power Station Unit 2DOCKET NUMBER (2)  
0 5 0 0 0 4 1 2 1 OF 0 3

TITLE (4)

## Engineered Safety Feature Components Actuation Due to De-energization of the 1G 4KV Bus.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	3	1	2	9	3	9	3	0	0	6	0 0 0 4 1 2 9 3
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (3)											
OPERATING MODE (9)			20.402(b)			20.405(c)			X 50.73(a)(2)(iv)		
POWER LEVEL (10)			20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(iv)		
1 10 0			20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vi)		
			20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(vii)(A)		
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(vii)(B)		
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)		
			20.405(a)(1)(vi)			50.73(a)(2)(iv)			73.71(b)		
									73.71(c)		
									OTHER (Specify in Abstract below and in Text, NRC Form 266A)		

LICENSEE CONTACT FOR THIS LER (12)  
NAME: L. R. Freeland, General Manager Nuclear Operations  
TELEPHONE NUMBER: 4 1 2 6 4 3 - 1 2 5 8

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	
X	W	I	X	X	X	X	X	X	N	
X	V	F	X	X	X	X	X	X	N	
SUPPLEMENTAL REPORT EXPECTED (14)										
YES (If yes, complete EXPECTED SUBMISSION DATE)										
X NO										
EXPECTED SUBMISSION DATE (15)										
MONTH DAY YEAR										

ABSTRACT (Limit to 1000 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 3/12/93, an automatic closure of the Steam Generator Blowdown Outside Containment isolation valves and an automatic realignment of the contiguous area ventilation from unfiltered to filtered exhaust occurred during a test of the Emergency Response Facility Diesel Generator. The diesel generator was connected to the 1G 4KV bus and loaded to approximately 300 KW. While the operator was adjusting the power factor, the diesel generator output breaker tripped on ground overcurrent. The normal supply to the 1G 4KV bus also tripped, leaving the bus momentarily de-energized and locked out. This caused the 480 Volt busses J and K, and L and M, to automatically tie together. The voltage disturbance then caused several radiation monitors to momentarily go into high alarm, resulting in the steam generator blowdown isolation and ventilation realignment. This event is categorized as an unplanned automatic repositioning of Engineered Safety Feature components. There were no safety implications as a result of this event. The diesel generator was shut down and normal power was restored to the 1G 4KV bus. The radiation monitors were reset. The Steam Generator Blowdown system was restored to its normal configuration and the contiguous area ventilation was restored to its normal exhaust path.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Beaver Valley Power Station Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 4 1 2	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 3	0 0 6	0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION OF EVENT

On 3/12/93, station operators were performing an operations surveillance test on the Emergency Response Facility (ERF) Diesel Generator (RG-EG-1). The diesel generator was connected to the 1G 4KV bus and loaded to approximately 300 KW. The normal power supply for the 1G 4KV bus is from the 138KV bus No. 2. As the operator was adjusting the power factor, the diesel generator output breaker tripped on ground overcurrent. The normal supply to the 1G 4KV bus also tripped on ground overcurrent, leaving the bus momentarily de-energized and locked out. This caused the 480 Volt busses J and K, and L and M, to automatically tie together. The voltage disturbance caused an electrical spike on several radiation monitors (the Supplemental Leak Collection Vent, Steam Generator Blowdown Sample, and the Waste Gas Storage Vault monitors). The Steam Generator Blowdown Sample monitor electrical spike caused the Steam Generator Blowdown Outside Containment isolation valves to automatically close. The Leak Collection Ventilation monitor electrical spike caused the ventilation of the contiguous areas to realign from unfiltered to filtered exhaust. The repositioning of the Steam Generator Outside Containment isolation valves and the contiguous area ventilation dampers is categorized as an unplanned operation of Engineered Safety Feature components. There were no safety implications as a result of this event. The Ground Fault Relay reset, indicating there were no grounds present. The normal power supply was restored to the 1G 4KV bus and the diesel generator was shut down. The radiation monitors were reset. The Steam Generator Blowdown system was restored to its normal configuration and the contiguous area ventilation was restored to its normal exhaust path.

CAUSE OF EVENT

The cause of this event is operator difficulty due to the high sensitivity of the diesel generator controls while the diesel generator is lightly loaded. While making adjustments, the changing power factor and possible generator pole slippage resulted in a ground overcurrent being sensed. This caused the diesel generator output breaker and the 1G 4KV normal power supply breaker to trip open.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Beaver Valley Power Station Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 4 1 2 9 3 —	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0 0 6	—	0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 306A's) (17)

CORRECTIVE ACTIONS

The following corrective actions have been or will be taken:

- 1) To minimize the effects of a diesel generator trip during testing, a procedure revision was issued to transfer the power supply of certain loads to the other train of power while the diesel generator is being tested.
- 2) To improve operator awareness of the control sensitivity, a procedure revision was issued providing more detailed instructions on changing the power factor on the diesel generator and the effects it may have on the system.
- 3) The Relay Group performed a calibration check of the Ground Fault Relay and found it to be within specification.
- 4) A Human Performance Enhancement System (HPES) evaluation is being performed on this event to evaluate the root cause of the man - machine interface problems.

REPORTABILITY

This event was reported to the Nuclear regulatory Commission at 1150 hours on 3/12/93, in accordance with 10CFR50.72.b.2.ii, as an event involving an unplanned Engineered Safety Feature component actuation. This written report is being submitted in accordance with 10CFR50.73.a.2.iv, as an event involving an Engineered Safety Feature component actuation.

SAFETY IMPLICATIONS

There were no safety implications as a result of this event. All systems were returned to their normal operating conditions and alignments shortly after the event. There were no adverse effects on the plant or its operation.

PREVIOUS OCCURRENCES

There are previously reported incidents of unplanned Steam Generator Blowdown system isolations and Contiguous Area Ventilation realignments, but none were directly attributable to problems that occurred while operating the Emergency Response Facility Diesel Generator.